



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721 BEHALF OF LOO HUI SHAN JOANNA		Ref: Date: Code:	CS/TP24080027/Kvh3e2 19/08/2024 TP277
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	-	Veh. Inspected	SJV 2598U
	Policy No.	-	Coverage	0
	Claim No.	-	Excess	\$0.00
	Assign From	-	Assign Date	01/08/2024
2. Vehicle Details				
	Make & Model	HONDA CIVIC (A)	C.C	1597
	Engine No.	R16B25502767	Year of Reg.	15/01/2019
	Chassis No.	MRHFC5650JT002348	Colour	METALLIC PEARL WHITE
	Odometer	111232 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: STANDARD ALLOY RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	215/55R16	YOKOHAMA	9
	L/H Front Tyre	215/55R16	YOKOHAMA	9
	R/H Rear Tyre	215/55R16	YOKOHAMA	9
	L/H Rear Tyre	215/55R16	YOKOHAMA	9
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	21/07/2024	Inspection Date	01/08/2024
	Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				