



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721 ON BEHALF OF LOO HUI SHAN JOANNA		Ref: CS/TP24080027/Kvh3e2 Date: 19/08/2024 Code: TP277		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	-	Veh. Inspected	SVJ 2598U	
Policy No.	-	Coverage	0	
Claim No.	-	Excess	\$0.00	
Assign From	-	Assign Date	01/08/2024	
2. Vehicle Details				
Make & Model	HONDA CIVIC (A)	C.C	1597	
Engine No.	R16B25502767	Year of Reg.	15/01/2019	
Chassis No.	MRHFC5650JT002348	Colour	METALLIC PEARL WHITE	
Odometer	111232 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: STANDARD ALLOY RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	215/55R16	YOKOHAMA	9	
L/H Front Tyre	215/55R16	YOKOHAMA	9	
R/H Rear Tyre	215/55R16	YOKOHAMA	9	
L/H Rear Tyre	215/55R16	YOKOHAMA	9	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/07/2024	Inspection Date	01/08/2024	
Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				