



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721 ON BEHALF OF LOO HUI SHAN JOANNA		Ref: CS/TP24080027/Kvh3e2 Date: 19/08/2024 Code: TP277		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	-	Veh. Inspected	SVJ 2598U	
Policy No.	-	Coverage	0	
Claim No.	-	Excess	\$0.00	
Assign From	-	Assign Date	01/08/2024	
<b>2. Vehicle Details</b>				
Make & Model	HONDA CIVIC (A)		C.C	1597
Engine No.	R16B25502767		Year of Reg.	15/01/2019
Chassis No.	MRHFC5650JT002348		Colour	METALLIC PEARL WHITE
Odometer	111232 KM		Steering	IN ORDER
Brakes	IN ORDER		General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance (mm)
R/H Front Tyre		215/55R16	YOKOHAMA	9
L/H Front Tyre		215/55R16	YOKOHAMA	9
R/H Rear Tyre		215/55R16	YOKOHAMA	9
L/H Rear Tyre		215/55R16	YOKOHAMA	9
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/07/2024		Inspection Date	01/08/2024
Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				