



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

not Authorized

30 September 2024

her
more

5/8/24

1/s @ 4000/
take photo After repair
4 days

REG NO.: SCQ 513 L
MAKE/MODEL: HONDA CIVIC

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front bonnet	\$ 11 895.50 X
2	Front bonnet hinges	\$ 11 97.00 X
1	Front bonnet lock	\$ 11 105.20 X
1	Front headlamp -LH	\$ One 1,082.80 ✓
1	Front bumper	\$ car/turn 801.00 ✓
1	Front bumper side retainer	\$ bent 31.30 ✓
1	Front fender -LH	\$ 7.5 594.80 ✓
1	Front fender inner shield	\$ torn 194.80 ✓
1	Front fender signal lamp	\$ 5.20 30.00 ✓
1	Front wheel hub	\$ 11 176.90 X
1	Front wheel bearing	\$ 11 109.00 X
1	Front shock absorber	\$ 11 514.00 X
1	Front knuckle arm	\$ 11 257.00 X
1	Front lower arm	\$ 11 278.50 X
1	Front door -LH	\$ 22/bent 1,023.80 ✓
1	Front door checker	\$ 11 45.50 X
2	Front door hinges	\$ 11 71.00 X
1	Front door inner board	\$ 11 436.00 X
1	Front door lock	\$ 11 239.70 X
1	Front door protector	\$ 11 106.60 ✓
1	Front door rubber	\$ 11 136.40 X
1	Front door side mirror	\$ 2 617.80 X
1	Rocker panel -LH	\$ 11 452.20 X
1	Rocker panel side skirt	\$ 2 865.80 X
		\$ 9,162.60
	Less 20%	\$ 1,832.52
		\$ 7,330.08

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	\$	new	50.00	30
1	Front bumper lower spoiler	\$	new	850.00	X
1	Front fender inner shield clip (1 set)	\$	new	60.00	30
1	Front tyre 115	\$	new	400.00	X
1	Front wheel rim 115	\$	wopel	850.00	480
				<u>\$</u>	<u>2,210.00</u>

S/N**LABOUR CHARGES**

1	To check wiring and reset headlamps focusing.	\$		80.00	20
2	To remove and refit front undercarriage.	\$	new	250.00	X
3	To conduct wheel alignment.	\$		150.00	60
4	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$		200.00	50
5	To apply undercoating.	\$		150.00	50
6	Panel beating.	\$		1,600.00	500
7	To re-spray painting on the affected areas.	\$		1,500.00	800
				<u>\$</u>	<u>3,930.00</u>

GRAND TOTAL :**\$ 13,470.08**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-3865-1
20%
3092.08
540
1480
5112.08
222
4080