



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 S737896

HP: 93911482

Estimation

Date: 2/8/2024

Vehicle: SMX7780E

Make / Model: TOYOTA PRIUS

Not authorized
L1 Rep & 2750h
Runway After Pain
3 days

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	FRT BUMPER 653.31	1	\$ 879.00	\$ 879.00 ✓
2	FRT BUMPER SIDE RETAINER RH	1	\$ 45.00	\$ 45.00 X
3	FRT BUMPER SIDE GARNISH RH	1	\$ 112.00	\$ 112.00 ✓
4	FRT BUMPER LOWER 301.90	1	\$ 512.00	\$ 512.00 ✓
5	FRT BUMPER TOWING COVER 29.30	1	\$ 112.00	\$ 112.00 ✓
6	HEADLAMP RH	1	\$ 2,591.00	\$ 2,591.00 ✓
7	FRONT FENDER RH	1	\$ 698.00	\$ 698.00 X
9	FRONT FENDER EMBLEM RH	1	\$ 52.00	\$ 52.00 ✓
	TOTAL PART			\$ 5,001.00
	LIST DOWN	25%		\$ 1,250.25
	AFTER LIST DOWN			\$ 3,750.75
	SPECIAL NETT			
1	FRT BUMPER CLIP SET	1	\$ 50.00	\$ 50.00 ✓
	TOTAL AMOUNT			\$ 50.00
	LABOUR			
1	CHECK WIRING	1	\$ 100.00	\$ 100.00 200
3	REALIGN HEADLAMP	1	\$ 120.00	\$ 120.00 200
4	PANEL BEAT	1	\$ 600.00	\$ 600.00 400
5	SPRAY PAINTING	1	\$ 600.00	\$ 600.00
	TOTAL AMOUNT			\$ 1,420.00
	Parts Replacement Amount			\$ 7,595.00
	Total Amount for Labour			\$ 1,840.00
	Total Amount			\$ 9,435.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: