

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

Hui Rong

ESTIMATE OF REPAIR

Veh# : PC8901S

Model:

SC NEUSTAR

Accident Date : 24/05/2024

30/12/2019

Location : 1 Supreme Ct Ln, Singapore 178879

3P:

SFU391P (SOMPO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Font Rh luggage cover <i>Dented</i>	3,200.00	1400	
2	1 set	Font Rh luggage cover shock absorber <i>new</i>	600.00	+	
3	1 pc	Font Rh luggage cover reflector <i>lit.</i>	200.00	80	
4	1 pc	Font Rh luggage cover sticket <i>new</i>		40.00	✓
5	1 pc	Middle RH luggage cover <i>Dented</i>	3,200.00	1400	
6	1 set	Middle RH luggage cover shock absorber <i>new</i>	600.00	+	
7	1 pc	Middle RH luggage handle <i>lit.</i>	400.00	150	
8	1 pc	Rear Rh luggage cover <i>Dented</i>	3,200.00	1000	
9	1 set	Rear RH luggage cover shock absorber <i>new</i>	600.00	+	
10	1 pc	Rear Rh luggage cover handle <i>lit</i>	480.00	150	
11	1 pc	Rear Rh rim <i>new</i>		800.00	+
12	1 pc	Rear Rh 2nd air vent panel <i>Rear</i>	4,100.00	+	
13	1 set	Rear Rh panel <i>Rear</i>	4,600.00	+	
14	1 pc	Rear Rh panel reflector <i>new</i>	200.00	+	
15	1 pc	Rear bumper <i>Rear</i>	3,000.00	+	
16	6pcs	Lock <i>new</i>	1,200.00	+	
17	1 pc	Rh rocker panel (repair) <i>Rear</i>			
18	1 pc	Advertisement sticker <i>new</i>		2000.00	✗
		<i>4160 S.N. 60</i>	Sub-Total:	25,580.00	2,840.00
			10%	0%	0%
		<i>3744</i>	After Less %:	23,022.00	2840.00
					0.00
		Labour			
1		To remove & refix accident damaged parts & realign affected area.	4,000.00	1200	
2		To spray paint on accident affected area.	3,000.00	1200	
3		To check wiring, layout & check for function.	300.00	30	
4		To rust proof affected area.	300.00	100	
		<i>2930</i>	Sub-Total:	7,600.00	
			Total:	33,462.00	
			After less 20%:	26,769.60	

1600
Adrian G
2/5 17/12/24
05 Days
total: 6734
2/5: 5.3K

LKK Auto Consultants is hence notify the Repairer of the following:

- To resurvey before/after repair.
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation.
- Third party survey is subject to "What's New" effect.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signed

Chan San Choon
Director
DipEng, AAE MIMI/MSAE(Aust)

