



Inchcape
 Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	M/S Grab Rentals Pte. Ltd	
		Document No. 0	3 Media Close #01-03/06 Singapore 138498	
		Document Date 05/09/2024	Work: 65703925	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	17/03/2017	SLL9839H	0	31996	67/TP/SLL9839H
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MHFB29F3X02007944	2NRX133347	60	Sam San Joi	12/08/2024 8.00	14/08/2024 18.00		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP-SJV1775G ACC DATE:01/08/2024 DRIVE IN:01/08/2024 DATE-IN:12/08/2024 DATE SURVEY:12/08/2024 NO OF REPAIR DAYS:5 DAYS BY:RASUL(LKK)				50.00
2	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM	*			158.40
3	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT	BP64			158.40
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	BP64			158.40
5	B	BP-LAB2 REPLACE LH FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN LH ACCIDENT AFFECTED AREAS	*			950.40
6	B	BP-RES2 RESPRAY JOB ON LH FRT ACCIDENT AFFECTED AREAS	*			1049.60
7	B	BP-MECH2 REPLACE RIM AND WHEEL BALANCING	BP64			126.72
8	1	K53812-K0020 PANEL, FR FENDER, LH	1.00	1067.30	30.00	747.11
9	2	U90467-07214 CLIP	10.00	3.80	30.00	26.60
10	3	K42611-0DC00 WHEEL, DISC	1.00	2687.30	30.00	1881.11

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			5,306.74
	Please acknowledge receipt of vehicle		GST 9.00% 477.61
		Parts 2,654.82	
		Labour 2,651.92	
		Sublet 0.00	
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 5,784.35