## **FINAL COST OF REPAIR**

(To be completed for only one type of item)

To:				From:		Ref		BB72	
	CPT MUHAMM Unit S								
TRANSPORT HUB WEST Unit						3AMB/31FMD/MOS			
				Base/LEO Area Office					
Description of Item: TRUCK,UTILITY:FORD EVE				REST,FFR,0.7 TONS		SAF 1222:		BB72/PLN/D/011/24	
Part/Reg No:	MID99	Orginal Value:	\$28	3.160		Date: SAF 1204/SAF 1351:		14-Aug-24	
Tarviteg ivo.	WIID77	Orginal value.	ΨΖ	5,100	s				
Quantity:	01	CE/Non CE:	No	n CE		Date:			
Description of Damages and Costs of Repairs:					,	Workshop Job No:		C44/AUG24/QY4069	
						Date:		06.08.2024	
MATERIAL COST	(Each line item to	indicate amount before GST	)						
DESCRIPTION				Qty	Unit Price			Total Price	
Paint material				2	\$ 140.	00		\$280.00	
Mark Up Rate 10%					\$28	.00		\$28.00	
Total								\$308.00	
LABOUR COST	(Each line item to	indicate amount before GST	")	Man Hour			Rate	\$33.36	
Front Bumper scratc	hes and front fender	dented due to impact							
Front Bumper scratches and front fender dented due to impact Remove & refit front bumper and front fender to repair dented areas								¢422.00	
Spray paint on repaired area body				13				\$433.68	
Putty and respray on	front bumber and fro	ont fender							
Assessment Fee	(Each line item to indicate amount before GST)								
DF-Equip charged under basic								\$0.00	
General Services (Each line item to indicate amount before GST)									
Tow Svc Wheeled								\$119.92	
Base/LEO Area Off	ice's Assessment	of Damages							
	Labour Charges @	9 \$33.36 per hour x		13	hrs =	\$4	33.68		
		per hour x			hrs =				
	Total Cost of Parts / Materials Used				=		00.80		
	Sub-contractor Assessment Fee				=	9	0.00		
Towing Service = Grand Total (Before GST Amount) = @ 9%GST =							19.92		
							61.60		
						\$	77.54		
	Grand Total (After				=	\$9	39.14		
Total Repair Time:		13							
[Digitally Signed in F	PDF by Hd MOS/MO	OS 2IC/MAO/Workshop IC]							

<sup>\*</sup>Delete whichever is not applicable