[Internal]

**CAUTION:** This email originated from outside the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

## [Internal]

Your ref: SNM24D204447/GBD3793E/C02/CHEESC

LKK ref: CD/CTI24080043/Uma3

Dear So Chow,

ACCIDENT INVOLVING GBD 3793E (CHINA TAIPING) AND SKX 3061Y (TP) ON 04/08/2024

We refer to the above matter.

It is an accident under BOLA: 27 OID hit onto rear TP. We are of the view that liability is on our driver's.

We seek your approval to offer repairer "FASTECH AUTO PTE LTD" at \$7,422.18 (all-in).

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair	\$ 21,214.32	\$ 6,540.00 (L/S) (w/GST)
2. Loss of Rental (8 days x \$100.00)	\$ 800.00	\$ 800.00 (8 days X \$100.00)
3. LTA/GIA Search Fee	\$ 2.18	\$ 2.18
4. Towing Fee	\$ 80.00	\$ 80.00
Total	\$ 22,096.50	\$ 7,422.18

Surveyor recommended 7 days for repair.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 05/08/2024 is only for mandate purpose.

Kindly let us have your approval / instruction.

Best Regards,

Daphne Lee (Ms) | Case Handler

Third Party Direct Settlement

LKK Auto Consultants Pte Ltd

Phone: 6841 2157 | Email: <u>DaphneLee@lkkauto.com</u>|

HQ: Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Daphne Lee (LKK Auto)

Sent: Monday, 26 August 2024 9:10 AM

**To:** Chee So Chow (CTPIS) < sochow.chee@sg.cntaiping.com >; Claims Dept of CTI

<<u>claimsdept@sg.cntaiping.com</u>>