



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0593/2024/KS
DATE	:	5-Aug-24
WIP	:	25743

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME	:	MS KAREN LEE LING LING (KAREN LI LINGLING)
ADDRESS	:	250A UPPER THOMSON ROAD
		SINGAPORE 574374
TELEPHONE	:	HP +65 81800038
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1900246234-02
VEHICLE NO	:	SML 1000 B
MODEL CODE	:	A1 SB ADVANCED 1.0 TFSI
MODEL YEAR	:	21/11/2019
ENGINE NO	:	DKJ 044794
CHASSIS NO	:	WAUZZZGB7LR005752
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	2-Aug-24
PLACE OF ACCIDENT	:	THOMSON ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 1000 B.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	X
2	TO REMOVE, CHECK AND TRANSFER WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	/
3	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00 250	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT. REINSTALL ALL PARTS REMOVED.	\$	3,500.00 1500/750	
5	TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BONNET HINGES.	\$	3,500.00 2200	
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	X
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	/
TOTAL LABOUR CHARGES		:	\$	8,562.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 1000 B.

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
1	FRONT BUMPER <i>tan /</i>	1	\$	1,955.00	
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$	160.00	
3	FRONT BUMPER SPOILER - LH <i>scr /</i>	1	\$	126.00	
4	FRONT BUMPER AIR GUIDE GRILLE - LH <i>scr /</i>	1	\$	264.00	
5	FRONT BUMPER CLOSING ELEMENT <i>cm /</i>	1	\$	210.00	
6	FRONT BUMPER GUIDE PROFILE - LH / RH <i>cm /</i>	2	\$	90.00	
7	LED HEADLIGHT - LH <i>cm /</i>	1	\$	5,138.00	
8	LIFT CYLINDER - LH <i>?</i>	1	\$	165.00	
9	LIFT CYLINDER HOSE <i>cut / ?</i>	1	\$	75.00	
10	FRONT BUMPER GUIDE SECTION - LH / RH <i>Lt / X</i>	2	\$	268.00	
11	FRONT FENDER - LH / RH <i>regur</i>	2	\$	2,324.00	
12	FRONT FENDER ATTACHMENT PARTS - LH <i>X</i>	1	\$	135.00	
13	FRONT FENDER BRACKET - LH / RH <i>Lt /</i>	2	\$	144.00	
14	FRONT FENDER BRACKET - LH / RH <i>Lt /</i>	2	\$	34.00	
15	FRONT FENDER BRACKET - LH / RH <i>Lt /</i>	2	\$	92.00	
16	FRONT FENDER BRACE - LH / RH <i>Lt / gwh</i>	2	\$	166.00	
17	FRONT FENDER CLOSING ELEMENT - LH / RH <i>X</i>	2	\$	84.00	
18	FRONT FENDER COVER - LH / RH <i>?</i>	2	\$	56.00	
19	FRONT FENDER CLOSING ELEMENT - LH / RH <i>der X</i>	2	\$	144.00	
20	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	432.00	
SUB TOTAL SPARE PARTS			:	\$ 12,062.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 1000 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER ATTACHMENT- LH / RH X	1	\$ 77.00	
22	BONNET 64 ✓	1	\$ 2,840.00	
23	BONNET HINGE - LH / RH 64 ✓	2	\$ 150.00	
24	BONNET STRIKER - LH / RH ?	2	\$ 246.00	
25	BONNET ATTACHMENT PARTS X	1	\$ 150.00	
26	BONNET IMPACT PROTECTION - LH / RH M ✓	2	\$ 76.00	
27	BONNET IMPACT PROTECTION - CENTER M ✓	1	\$ 38.00	
28	BONNET SEAL ✓	1	\$ 106.00	
29	BONNET BOWDEN CABLE - CENTER ?	1	\$ 105.00	
30	BONNET BOWDEN CABLE - LH / RH ?	2	\$ 80.00	
31	BONNET LOCK WITH MICRO SWITCH - LH / RH ?	2	\$ 491.00	
32	BONNET BOWDEN CABLE - COVER ?	1	\$ 12.00	
33	PLENUM CHAMBER COVER ?	1	\$ 250.00	
34	PLENUM CHAMBER COVER SEAL - CENTER ?	1	\$ 92.00	
35	PLENUM CHAMBER COVER SEAL - LH / RH ?	2	\$ 310.00	
36	HORN - LH X	1	\$ 162.00	
37	WASH WATER RESERVOIR X	1	\$ 217.00	
38	WASH WATER FILLER NECK X	1	\$ 70.00	
39	WASH WATER SEAL RING X	1	\$ 8.00	
40	WASH WATER STRAINER X	1	\$ 26.00	
SUB TOTAL SPARE PARTS		:	\$ 5,506.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 1000 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	WASH WATER END CAP X	1	\$ 26.00	
42	FRONT ALUMINIUM RIM - LH X	1	\$ 1,251.00	
43	FRONT ALUMINIUM RIM RUBBER VALVE X	1	\$ 5.00	
44	SUNDRIES ?		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 19,350.00	
TOTAL LABOUR CHARGES		:	\$ 8,562.00	
GRAND TOTAL		:	\$ 27,912.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: *Posm - Hp 90010068*
: *05/08/24*
: *7 days*
: *EXCESS: TBA*
: *Posm / Res for part*
:

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT