

(08/11/13) Wef

ASS. REC. BY:

REF: CS/A16 24080050/Rvp?

1176

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SML1000B

at Workshop m/s

PREMIUM

of

BENDI SECTOR

Insured:

A16

Policy No.

1900246234

Claims No.

4655146953SG

Sum Insured:

Excess:

TBA 300


(Client's Record)

Make of Veh:

(Policy Condition)

2pr

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

87K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SML1000B

Yr Regn:

2019 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

AUDI A1SBAADVANCED 1.0TFSI 999

Colour:

GREEN

AC:

Insured / Std / Nil / NA

Sp. Reading:

11472

T/Radio:

Insured / Std / Nil / NA

Eng/No:

C/No:

WAM ZZZG B7L R05752

Gen. Cond: Good / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R16

R:

BS / DUN / EXNOVA / GV / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

02/08/24

D.O.I.

05/08/24

Survey held at

BENDI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 51K

Date/Time, File Pass to?



: Prel. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) S + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

10/1/25 Rasul confirm final fig \$16,920.88 (red 13,142.12, 43%)



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0593/2024/KS
DATE : 5-Aug-24
WIP : 25743

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS KAREN LEE LING LING (KAREN LI LINGLING)
ADDRESS : 250A UPPER THOMSON ROAD
SINGAPORE 574374
TELEPHONE : HP +65 81800038
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900246234-02
VEHICLE NO : **SML 1000 B**
MODEL CODE : A1 SB ADVANCED 1.0 TFSI
MODEL YEAR : 21/11/2019
ENGINE NO : DKJ 044794
CHASSIS NO : WAUZZZGB7LR005752
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Aug-24
PLACE OF ACCIDENT : THOMSON ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 1000 B.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	X
2	TO REMOVE, CHECK AND TRANSFER WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	/
3	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00 250	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT. REINSTALL ALL PARTS REMOVED.	\$	3,500.00 1500/750	
5	TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BONNET HINGES.	\$	3,500.00 2200	
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	X
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	/
TOTAL LABOUR CHARGES		:	\$	8,562.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 1000 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>tom</i>	1	\$	1,955.00
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$	160.00
3	FRONT BUMPER SPOILER - LH <i>scr</i>	1	\$	126.00
4	FRONT BUMPER AIR GUIDE GRILLE - LH <i>scr</i>	1	\$	264.00
5	FRONT BUMPER CLOSING ELEMENT <i>cm</i>	1	\$	210.00
6	FRONT BUMPER GUIDE PROFILE - LH / RH <i>cm</i>	2	\$	90.00
7	LED HEADLIGHT - LH <i>cm</i>	1	\$	5,138.00
8	LIFT CYLINDER - LH <i>?</i>	1	\$	165.00
9	LIFT CYLINDER HOSE <i>cut</i>	1	\$	75.00
10	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$	268.00
11	FRONT FENDER - LH / RH <i>lt repair</i>	2	\$	2,324.00
12	FRONT FENDER ATTACHMENT PARTS - LH <i>X</i>	1	\$	135.00
13	FRONT FENDER BRACKET - LH / RH <i>lt</i>	2	\$	144.00
14	FRONT FENDER BRACKET - LH / RH <i>lt</i>	2	\$	34.00
15	FRONT FENDER BRACKET - LH / RH <i>lt</i>	2	\$	92.00
16	FRONT FENDER BRACE - LH / RH <i>lt / gh</i>	2	\$	166.00
17	FRONT FENDER CLOSING ELEMENT - LH / RH <i>?</i>	2	\$	84.00
18	FRONT FENDER COVER - LH / RH <i>?</i>	2	\$	56.00
19	FRONT FENDER CLOSING ELEMENT - LH / RH <i>der</i>	2	\$	144.00
20	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	432.00
SUB TOTAL SPARE PARTS		:	\$	12,062.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 1000 B.

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT WHEEL HOUSING LINER ATTACHMENT- LH / RH X	1	\$	77.00	
22	BONNET Lt/	1	\$	2,840.00	
23	BONNET HINGE - LH / RH Lt/	2	\$	150.00	
24	BONNET STRIKER - LH / RH ?	2	\$	246.00	
25	BONNET ATTACHMENT PARTS X	1	\$	150.00	
26	BONNET IMPACT PROTECTION - LH / RH Lt/	2	\$	76.00	
27	BONNET IMPACT PROTECTION - CENTER Lt/	1	\$	38.00	
28	BONNET SEAL Lt/	1	\$	106.00	
29	BONNET BOWDEN CABLE - CENTER ?	1	\$	105.00	
30	BONNET BOWDEN CABLE - LH / RH ?	2	\$	80.00	
31	BONNET LOCK WITH MICRO SWITCH - LH / RH ?	2	\$	491.00	
32	BONNET BOWDEN CABLE - COVER ?	1	\$	12.00	
33	PLENUM CHAMBER COVER ?	1	\$	250.00	
34	PLENUM CHAMBER COVER SEAL - CENTER ?	1	\$	92.00	
35	PLENUM CHAMBER COVER SEAL - LH / RH ?	2	\$	310.00	
36	HORN - LH X	1	\$	162.00	
37	WASH WATER RESERVOIR X	1	\$	217.00	
38	WASH WATER FILLER NECK X	1	\$	70.00	
39	WASH WATER SEAL RING X	1	\$	8.00	
40	WASH WATER STRAINER X	1	\$	26.00	
SUB TOTAL SPARE PARTS		:	\$	5,506.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 1000 B.**DAMAGED PARTS & PRICES**

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	WASH WATER END CAP X	1	\$ 26.00	
42	FRONT ALUMINIUM RIM - LH X	1	\$ 1,251.00	
43	FRONT ALUMINIUM RIM RUBBER VALVE X	1	\$ 5.00	
44	SUNDRIES ?		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 19,350.00	
TOTAL LABOUR CHARGES		:	\$ 8,562.00	
GRAND TOTAL		:	\$ 27,912.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Posui - Hp 90010068
05/08/24
7 days
EXCESS: THA
Posui / Res for part

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	113G
Vehicle Details	
Vehicle No.:	SML1000B
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Aug 2024
Vehicle Make:	AUDI
Vehicle Model:	A1 SB ADVANCED 1.0 TFSI S TRONIC
Primary Colour:	Green
Manufacturing Year:	2019
Engine No.:	DKJ044794
Chassis No.:	WAUZZZGB7LR005752
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,590.00
Original Registration Date:	21 Nov 2019
First Registration Date:	21 Nov 2019
Transfer Count:	0
Actual ARF Paid:	\$25,026.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Nov 2029
PARF Rebate Amount:	\$18,769.00
Intended COE Rebate Details	
COE Expiry Date:	20 Nov 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,000.00
COE Rebate Amount:	\$16,924.00
Total Rebate Amount:	\$35,693.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 06 Aug 2024

OK



Audi A1 Sportback 1.0A TFSI S-tronic S-Line

\$91,800 Instalment \$1,121/mth

💰 Apply for 2.48% loan

♡ Shortlist

✔ Get Warranty

NEW CAR DISCOUNTS & OFFERS

BEST DEAL DAILY!

▶ **VIEW ALL
PROMO**

Overview Financial Photo Research

Depreciation	📘 \$14,260 / year
Reg. Date	26-Feb-2020 (5yrs 6mths 19days COE left)
Manufactured	📘 2019
Mileage	83,824 km (18.9k / year)
Transmission	Auto
Engine Cap	999 cc
Road Tax	📘 \$392 / year
Power	85.0 kW (113 bhp) View specs of the Audi A1 Sportback (2019-2022)
Curb Weight	📘 1,200 kg
COE	📘 \$30,010
OMV	📘 \$23,590
ARF	📘 \$25,026