

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
MS	LIBERTY INSURAN	CE PTE LTD	Ref:	CS/LIP24080059/Uvh3		
	ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583		Date:	16/08/2024		
	SINOAI OILE 04030		Code:	LIP		
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PC 798B	Veh. Inspected	SNC 9119B		
	Policy No.	-	Coverage	0		
	Claim No.	BVS24/0545	Excess	\$0.00		
	Assign From	ANDY SEAH	Assign Date	05/08/2024		
2. Vehicle Details						
	Make & Model	B.M.W. 216D (A)	C.C	1496		
	Engine No.	30469930B37C15A	Year of Reg.	29/05/2017		
	Chassis No.	WBA2E320905H46314	Colour	BLACK		
	Odometer	228493 KM	Steering	IN ORDER		
	Brakes	IN ORDER	General	GOOD		
	Modification(s)	RIMS: SPORTS RIM	-			
3. Conditions of Tyres						
		Size	Make	Balance (mm)		
	R/H Front Tyre	215/50R17	YOKOHAMA	6		
	L/H Front Tyre	215/50R17	YOKOHAMA	6		
	R/H Rear Tyre	215/50R17	YOKOHAMA	6		
	L/H Rear Tyre	215/50R17	YOKOHAMA	6		
4. Description of Damages						
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.						
DAMAGES SEE DETAILS.						
5.	General Information					
	Accident Date	02/08/2024	Inspection Date	06/08/2024		
	Survey held at	HH MOTOR TRADING BLOCK 3012, BEDOK NORTH AVE 4, #01-2054 BEDOK INDUSTRIAL PARK E, SINGAPORE 489978				
5a.	5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b. Estimate Days of Repair						
5b.		• •				

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days