

(08/11/13) . wef

REF:

CS/LIP 24080059/Uvh3

ASS. REC. BY: Marcus

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV**To Inspect Vehicle No: SNC 9119Bat Workshop m/s H/M motor

of \_\_\_\_\_

Insured: PC 798B

Policy No. \_\_\_\_\_


Claims No. BVS24/0545

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: \$48k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No**CA / REV / REP. / 24 HRS**

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: LTA 30746Veh No: SNC 9119B Yr Regn: 29/2/17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or AMake: BMW 216 D c.c. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 228493 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA2E320905H 46314Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 215/50 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 02/08/24 D.O.I. 6/8/24

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS Rep.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Ref 136.14/8/24whatsapp video2/5 \$4500in hand Ben. (red 12,346.65, 73%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech. Invs (\$ \_\_\_\_\_)

☐

: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\_\_\_\_ S + RS, \_\_\_\_ \$I

Photos

Others

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	479C
Vehicle Details	
Vehicle No.:	SNC9119B
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Aug 2024
Vehicle Make:	B.M.W.
Vehicle Model:	216D GRAN TOURER LED NAV 7 SEATER
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	30469930B37C15A
Chassis No.:	WBA2E320905H46314
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$32,369.00
Original Registration Date:	29 May 2017
First Registration Date:	29 May 2017
Transfer Count:	1
Actual ARF Paid:	\$27,317.00 13658
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 May 2027
PARF Rebate Amount:	\$16,390.00
Intended COE Rebate Details	
COE Expiry Date:	28 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,106.00
COE Rebate Amount:	\$14,356.00
Total Rebate Amount:	\$30,746.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 06 Aug 2024

OK



## Post an Advertisement

Sell it yourself! Advertise it at just  
**\$72 until it's SOLD!**

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

Low Interest Rate In-House Loan by GV Cars Financing



Flexible In-House Loan by GV  
Cars Financing at 2.98% p.a.  
Low Interest Rate.  
GV Automobile  
Centre [StarAd](#)

**PRIME MOTOR & LEASING**  
(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles  
to choose from, ranging from  
all European to Japanese Makes.

« Back ( 1 2 3 ) Next »

Sort by  20 results/page

42 vehicles



BMW 216

Any Category

[Advanced Search](#)[Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>BMW 216</b>		Any	Any	2017	Any	Any	Any	Available
	BMW 2 Series 216d Active Tourer		\$46,500	\$12,600 /yr	30-May-2017	1,496 cc	97,000 km	Hatchback	Available
	<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) Rocket auto trading. Posted: 06-Aug-2024								
	BMW 2 Series 216d Active Tourer		\$61,800	\$15,180 /yr	24-Nov-2017	1,496 cc	45,000 km	Hatchback	Available
	<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) 1 owner with lower mileage. The 216d Active Tourer benefits from BMW's engineering expertise in handling. The vehicle has a well-tuned suspension that strikes a good balance between comfort and sportiness. The driving experience is... VINCAR Pte Ltd Posted: 05-Aug-2024								
	BMW 2 Series 216d Active Tourer		\$50,888	\$13,040 /yr	07-Sep-2017	1,496 cc	139,808 km	Hatchback	Available
	Introducing the active tourer embrace versatility and style with this compact powerhouse. Perfect for urban adventures and family getaways, the active tourer delivers a thrilling driving experience while accommodating your lifestyle... Posted: 05-Aug-2024								
	BMW 2 Series 216d Active Tourer		\$46,888	\$13,970 /yr	17-Mar-2017	1,496 cc	92,511 km	Hatchback	Available
	<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) Full loan available! Lowest depreciation unit in market! Doorstep viewing can be arranged! More attractive discount with trade in! Preowned with low mileage done for peace of mind! 100% loan approval with our flexible loan arrangement... Creative Auto Leasing Pte Ltd Posted: 05-Aug-2024								
	BMW 2 Series 216d Active Tourer		\$51,800	\$14,080 /yr	29-Jun-2017	1,496 cc	124,331 km	Hatchback	Available
	<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) Immaculate condition. Well taken care of. Loan to suit your needs. High trade in. Don't miss! Call now for a viewing today! You won't be disappointed! Posted: 04-Aug-2024								
	BMW 2 Series 216i Gran Tourer Luxury		\$72,800	\$16,270 /yr	28-Dec-2017	1,499 cc	83,000 km	MPV	Available
	1 owner only! Pristine condition with original paintwork! 1 year warranty. Super well maintained. Original paintwork, good fuel consumption. Nothing to repair. Workshop check and STA evaluation available. Contact us for more details. Posted: 03-Aug-2024								

[Compare](#)

# Hock Wah Motor Workshop PTE LTD

Blk 3011 Bedok North Ave4  
#01-2008/2010/2012/2014 Singapore 489977

Phone Number: 6441 5655


Fax Number: 64415355

Customer:		Date:	8/8/2024 5:31:45 PM
Company:		VIN:	
License No:	SNC 9119 B	Technician:	
Odometer:		Order No.:	

## VEHICLE ALIGNMENT REPORT

BMW 2 SERIES (F22) RWD M235i Standard Suspension(Custom), 14-17,

Primary Angles		Initial	Specifications		Final
			Min.	Max.	
Front	Left	3.6°	-----	-----	3.8°
	Right	3.0°	-----	-----	4.4°
	Left	-0.9°	-1.3°	-0.5°	-0.7°
	Right	-0.6°	-1.3°	-0.5°	-0.5°
	Left	-0.7	0.5mm	0.9mm	0.5
	Right	1.7	0.5mm	0.9mm	0.4
Rear	Total	1.0	1.0	1.8	0.9
	Left	-2.6°	-1.8°	-1.7°	-2.4°
	Right	-2.7°	-1.8°	-1.7°	-2.5°
	Left	1.3	0.7mm	1.1mm	1.1
	Right	-1.2	0.7mm	1.1mm	-1.6
	Total	+0.1	1.4	2.2	-0.5
Thrust Angle		-0.2°	-0.2°	0.2°	-0.2°
Secondary Angles		Initial	Specifications		Final
			Min.	Max.	
Camber	Left	13.0°	-----	-----	13.0°
	Right	16.8°	-----	-----	16.8°
Included Angle	Left	12.1°	-----	-----	12.3°
	Right	16.2°	-----	-----	16.3°
Toe Out On Turns	Left	1.6°	1.5°	1.5°	1.6°
	Right	1.7°	1.5°	1.5°	1.7°
Steering Arms	Left	-----	39.8°	39.8°	-----
	Right	-----	39.8°	39.8°	-----
Steer Curve Change	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Squatback	Front	0.1"	-----	-----	0.1"
	Rear	-0.5"	-----	-----	-0.5"
Track Width Diff		-0.4"	-----	-----	0.3"
		0.6"	-----	-----	0.6"
Front Ride Height	Left	-----	23.5"	24.3"	-----
	Right	-----	23.5"	24.3"	-----
Rear Ride Height	Left	-----	23.3"	24.1"	-----
	Right	-----	23.3"	24.1"	-----
Frame Angle		-----	-----	-----	-----



# 發 福 摩 多 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,  
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.  
Tel / Fax: 6445 2934 Hp: 8161 6988  
BUSINESS REG NO. 375654/00C

Carplate: SNC9119B
Chassis No: WBA2E320905H46314
Accident Date: 02/08/2024
Make & Model: BMW 216D GRAN TOURER

Not Authorised  
der  
moas  
6/8/24  
3 dys 2/5 \$4500/  
light. Atty.

No.	Item	Price	✓/✗	Remarks
1	Front Bumper	\$ 1,526.95	1205-32	cut/rip ✓
2	Front Bumper Side Retainer LH	\$ 122.35		17 X
3	Front Headlamp LH	\$ 2,660.80	2363-65	CME ✓
4	Front Headlamp Bracket LH	\$ 98.20		17 X
5	Front Bumper Reinforcement Beam	\$ 735.90		17 X
6	Front Bumper Reinforcement Beam Foam	\$ 311.25		17 X
7	Front Bumper Reinforcement Beam Bracket LH	\$ 226.10		17 X
8	Front Bumper Logo "H"	\$ 98.10		PU X
9	Front Bumper Sensor x 2 @ \$204.40/pc	\$ 408.80		PU X
10	Front Door LH	\$ 1,820.95		17 X
11	Front Door Hinge LH x2 @ \$112.50/pc	\$ 225.00		17 X
12	Front Fender LH	\$ 1,113.90	750-25	10/30 ✓
13	Front Fender Splash Guard LH	\$ 298.10		17 X
14	Front Bonet	\$ 2,160.25		17 X
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				

	Special Nett Items	Price	✓/✗	Remarks
1	Front Bumper Clips (1 Set)	\$ 40.00		nu 30 S/W
2	Front Tyre LH	\$ 580.00		Svc X
3	Front Tyre Rim LH	\$ 980.00		C47 450 S/W
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
No.	All Necessary Work	Price	✓/✗	Remarks
1	To Carry Out Anti-rust Treatment	\$ 120.00		20
2	Remove and Install New Front Sensor	\$ 120.00		30
3	Rewiring to Facilitate Repairs	\$ 150.00		20
4	Remove and Refit All Trims, Upholders, Garnish and All Necessary to Facilitate Repair Works	\$ 320.00		11X
5	To carry out computer diagnosis for fault codes	\$ 180.00		11X
6	4 Wheel Allignement and Adjustment	\$ 150.00		60
7				
8				
9	Labour to remove and replace damaged parts, including refitting and repositioning of replaced parts	\$ 1,200.00		400
10	Spray painting materials and respray of all affected and replaced parts necessary for paintwork	\$ 1,200.00		600
	Estimated No. of days for repairs and respray of all necessary	8 Days	3 dy	

16,846.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4319.22  
52

4103.26

480

1130

5713.26

222

4500