



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS INCOME INSURANCE LTD		Ref:		CS/INC24080060/Unh3e2
75 BRAS BASAH ROAD		Date:		12/08/2024
INCOME CENTRE SINGAPORE 189557		Code:		INC
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SCM 9098E	Veh. Inspected	SKQ 6763Y
	Policy No.	-	Coverage	0
	Claim No.	MT/1289004-002	Excess	\$0.00
	Assign From	AMANDA CHOOI	Assign Date	06/08/2024
2. Vehicle Details				
	Make & Model	TOYOTA WISH (A)	C.C	1797
	Engine No.	2ZR1416325	Year of Reg.	03/11/2014
	Chassis No.	ZGE206016210	Colour	GREY
	Odometer	196638 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	215/50R17	PROMIX	6
	L/H Front Tyre	215/50R17	CONTINENTAL	6
	R/H Rear Tyre	215/50R17	CONTINENTAL	6
	L/H Rear Tyre	215/50R17	CONTINENTAL	6
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	02/08/2024	Inspection Date	06/08/2024 (09:16)
	Survey held at	CARSMITH PTE LTD - 8 KAKI BUKIT AVENUE 4 #04-35 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				