

Not Withheld
L/Sing & 2430h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9500Z

AAD2407-048

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD9500Z

JTDKB3FU403080996

200303878K

TOYOTA

PRIUS

13/7/2024

SNB7328H/ 市

31/5/2019

PART

LIST

- 1 COVER, FRONT BUMPER
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 FRONT BUMPER SIDE RETAINER RH
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 UNIT ASSY, HEADLAMP, RH
- 1 LAMP ASSY, FOG, RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 FRONT FENDER EMBLEM RH

\$	Bu	516.00	✓
\$	n	902.16	X
\$	DIT	80.10	✓
\$	sn	219.10	X
\$	sn	2,637.60	X
\$	sn	1,200.78	✓
\$	Ry	977.80	✓
\$	sn	206.70	X
\$	n	54.60	✓

TOTAL	\$	6,794.84
25%	\$	1,698.71
	\$	5,096.13

Special Nett

- 1 FRT BUMPER CLIP
- 1 FRT BUMPER SIDE RETAINER CLIP
- 1 FENDER LINER CLIP

\$	me	65.00	60sn
\$	nn	65.00	X
\$	nn	75.00	X

TOTAL	\$	205.00
--------------	-----------	---------------

TOTAL PARTS	\$	5,301.13
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$

250.00 30h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9500Z**AAD2407-**

Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	440
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	400
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of front fender panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X

TOTAL \$ 4,990.00**Over All Total \$ 10,291.13****(Lump Sum) Repair Days**~~04 Days~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part's prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: