

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile	
MS SOMPO INSURANCE SINGAPORE PL Ref: CS3/SMO2406009	90/Ugh3e2	
50 RAFFLES PLACE #03-03 Date: 17/07/2024	·	
SINGAPORE LAND TOWER SINGAPORE 048623		
Code: SMO		
1. Policy Particulars :- PRE-REPAIR SURVEY		
Insured Veh. SCL 5185T Veh. Inspected SJT 1054P		
Policy No. D23MTPV01013268 Coverage 0		
Claim No. CMTD2401970/RUC Excess \$0.00		
Assign From GRACE TEO Assign Date 13/06/2024		
2. Vehicle Details		
Make & Model MERCEDES BENZ B180 (A) C.C 1699		
Engine No. 26694030658319 Year of Reg. 24/09/2009		
Chassis No. WDD2452322J498063 Colour SILVER		
Odometer 187885 KM Steering IN ORDER		
Brakes IN ORDER General GOOD		
Modification(s) RIMS: STANDARD ALLOY RIM		
3. Conditions of Tyres		
Size Make Balar	nce (mm)	
R/H Front Tyre 215/45R17 MICHELIN	5	
L/H Front Tyre 215/45R17 MICHELIN	5	
R/H Rear Tyre 215/45R17 MICHELIN	5	
L/H Rear Tyre 215/45R17 MICHELIN	5	
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.		
5. General Information		
Accident Date 12/06/2024 Inspection Date 14/06/2024 (12:17	PM)	
Survey held at BLK 3012 BEDOK IND PARK E #01-2016 - YK SUPREME AUTOWERKZ PTE LT	D	
5a. Remarks		
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.		
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.		
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.		
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000		
5b. Estimate Days of Repair		
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days	

CKS

## MARCUS CHUA KANG SENG Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.