

SOON BENG MOTOR

1 Kaki Bukit Avenue 6, #01-96, Singapore 417883

UEN: 53432271M / Tel: 9663 2833 (Ah Beng)

Vehicle number: SJA1323M

Vehicle Made & Model: TOYOTA SIENTA

Qty	List Items	Amount \$
1	Front door - LH <i>R</i>	1,895.60 <i>X</i>
1	Front door side mirror <i>Damage (CR)</i>	1,210.65 <i>X</i>
1	Front door side mirror cover <i>u1</i>	181.35 <i>X</i>
1	Front door glass <i>u1</i>	1,055.90 <i>X</i>
1	Front door glass outer moulding <i>u1</i>	181.60 <i>X</i>
Sub-total		4,525.10
Less 25%		1,131.28
Total List		3,393.83

Labour charges

To respray painting and etc	600.00 <i>200</i>
Panel beating, cut, weld remove & replacing above parts	500.00 <i>200</i>
Total Labour	1,100.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 4,493.83

*Not Authorized
all
memo
6/8/24
P/P \$ 1307.98
2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*P-1210.65
252
967.98
400
1307.98*