

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CCPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	03/08/2024
Vehicle Reg. No.:	SHB2003Z	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI KONA, OS EV (A)	Vehicle Reg. Date:	29/12/2023
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LLPS265118	Chassis No:	KMHBB811VRU037148
Odometer:	76994 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	4,291.06
Miscellaneous Items	12.00
Labour	2,165.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,468.06
+ GST 9.00% (S\$)	582.13
Nett Amount (S\$)	7,050.19

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

PAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2024)
Parts:	144	HYUNDAI KONA OS EV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHB2003Z/05/08/2024 13:39	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*COVER ASSY BUMPER UPPER / CR4 (P1102)	20.00	0.00	*375.30 FL /
2	1		*COVER ASSY BUMPER LOWER / CR4	20.00	0.00	*188.14 FL /
3	1		*SKID PLATE ASSY BUMPER REAR / CR4	20.00	0.00	*537.48 FL /
4	1		*BEAM- BUMPER REAR / DEF	20.00	0.00	*582.00 FL /
5	1		*PANEL ASSY TAIL GATE X R	20.00	0.00	*2,164.00 FL
6	1		*TAIL LAMP LH / x nn	20.00	0.00	*935.40 FL
7	1		*EMBLEM- KONA / x nn	20.00	0.00	*97.00 FL
8	1		*EMBLEM- H / x nn	20.00	0.00	*47.00 FL
9	1		*TAIL GATE ZIG STICKER / x nn	0	0.00	*40.00 FS
10	1		*TAIL GATE COMFORTDELGRO & TE NUMBER STICKER / x nn	0	0.00	*80.00 FS
11	1		*REAR NUMBER PLATE X nn	0	0.00	*50.00 FS
12	1		*REAR REVERSE SENSOR X nn	0	0.00	*180.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$) 5,276.32
 - List Item Discount on L Items (\$\$) 985.26

Total Parts (\$\$) 4,291.06

ComfortDelGro Engineering Pte Ltd/SHB2003Z/05/08/2024 13:39. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

1682.92
 -20%
 1346.33

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	1 OD/TP Case (Insurer)	12.00
Sub Total (\$\$)		12.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New 760	1,150.00
2	SPRAY PAINTING	New 560	800.00
3	CHECK LIGHTING AND WIRING	New 30	60.00
4	REMOVE.REFIX REVERSE SENSOR	New 20	60.00
5	TOWING FEE	(8.11) New 1	95.00
Gross Labour Cost (\$\$)			2,165.00

ComfortDelGro Engineering Pte Ltd/SHB2003Z/05/08/2024 13:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)

6/8/24, 3.00pm

M R

P/P

4 Bel sy

2 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: