

(08/11/13) Wef

ASS. REC. BY:

REF: CS/ICS24080095/Rnp3

823H

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMY533T

at Workshop m/s BORNU

of 2, PANDAN CRESCENT

Insured: ICS

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: FBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

2PM

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 143K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMY533T Yr Regn: 2021 / PGB

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: LEXUS UX200 EXE cc 1987

Colour: GRAY AC: Insured / Std / NI / NA

Sp. Reading: 50021 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JT4435BH802035124

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 02/08/24

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 07/08/24

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - TAK

We will be advising our principal a cost of repair P/P \$7,246.95 /- with 05 days of repair (red, \$5479.63, 43%)

Date/Time, File Pass to?

☐
☐

: Prel. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) S + RS S

) Photos

) Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Format: _____

Lump Sum / I.B.I: (\$

TOTAL



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Mr Toh Hung Meng (zhao Hanming) 24 Sumang Walk #03-05 Singapore 828678 Mobile: 96300351
	Document No. 0	
	Document Date 05/08/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAA10R	AWXBB S4	10/02/2021	SMY0533T	0	24851	77/ODUL/SMY0533T

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHY35BH802035124	M20AN257274	60	Cheng Wei Ting	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MPC24A00131100 ACC DATE:02/08/2024 TOW/DRIVE IN:02/080/2024 EXCESS:750.00\$ DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	B	BP-LAB3 TO CHECK WIRING AND CONDUCT WATER LEAK T EST				192.00
3	B	BP-LAB3 TO REMOVE AND REINSTALL FRONT BUMPER SEN SOR TOENABLE FOR THE REPAIR				192.00
4	B	BP-ECU3 TO RESET ECU & REPROGRAMME				192.00
5	B	BP-MECH3 TO CONDUCT ADJUSTMENT ON FRONT PRE-COLLI SION SENSO				192.00
6	B	BP-MECH3 TO REPLACE TYRE RIM AND CONDUCT WHEEL BA LANCING				192.00
7	B	BP-MECH3 TO CONDUCT ADJUATMENT ON WHEEL ALIGNMENT				168.00
8	B	BP-LAB3 TO REPLACE AND REPAIR ON FRONT ACCIDENT AFFECTED A				1536 2304.00
9	B	BP-RES3 TO SPRAY PAINTING ON FRONT ACCIDENT AFPE CTED AREA				1305 3284.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Mr Toh Hung Meng (zhao Hanming)
	Document No. 0	24 Sumang Walk #03-05 Singapore 828678
	Document Date 05/08/2024	Mobile: 96300351

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAA10R	AWXBB S4	10/02/2021	SMY0533T	0	24851	77/ODUL/SMY0533T

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHY35BH802035124	M20AN257274	60	Cheng Wei Ting	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	Z	BP-SLANT SUPPLY SEALANT (NETT) X				100.00
11	1	L42611-76310 WHEEL, DISC <i>scr</i>	1.00	4002.80	30.00	2801.96
12	2	L52113-76902 EXTENSION, FR <i>requ</i>	1.00	527.90	30.00	369.53
13	3	L89348-12140 B5 RETAINER, ULTRASONIC X	1.00	57.90	30.00	40.53
14	4	L75895-53010 TAPE, MOULDING, NO.1 X	2.00	55.50	30.00	77.70
15	5	L16563-24020 SEAL, RADIATOR TO X	1.00	55.60	30.00	38.92
16	6	L52126-76050 BRACKET, FOG LAMP X	1.00	84.10	30.00	58.87
17	7	L81482-76070 COVER, FOG LAMP, LH X	1.00	189.20	30.00	132.44
18	8	L52411-76010 GUARD, FR BUMPER X	1.00	537.10	30.00	375.97
19	9	L52116-76020 SUPPORT, FR BUMPER X	1.00	120.60	30.00	84.42
20	0	L75392-35220 RETAINER, OUTSIDE <i>scr</i>	4.00	5.60	30.00	15.68
21	1	L53802-76030 FENDER SUB-ASSY, FR X	1.00	2035.50	30.00	1424.85
22	2	L75602-76010 MOULDING SUB-ASSY, <i>scr</i> / photo	1.00	506.50	30.00	354.55
23	3	T90467-07215 CLIP <i>scr</i>	8.00	3.60	30.00	20.16
24	4	L90269-04051 RIVET <i>scr</i>	10.00	2.20	30.00	15.40
25	5	T90269-06013 RIVET <i>scr</i>	10.00	2.80	30.00	19.60

RASUL
Hp 90010068

5 days

P/P

07/08/24

EXCESS: TBA

Revert

Res after requ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey before/after (s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer's Signature

Charge Summary

Parts	5,830.58
Labour	6,896.00
Sublet	0.00
Lubrication/Fluid	0.00
Others	0.00

Total	12,726.58
GST 9.00%	1,145.39
Less	0.00
Amount Due	13,871.97

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	823H
Vehicle Details	
Vehicle No.:	SMY533T
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS UX200 5DR SUV (AT) (2WD) EXECUTIVE
Primary Colour:	Silver
Manufacturing Year:	2020
Engine No.:	M20AN257274
Chassis No.:	JTHY35BH802035124
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$35,342.00
Original Registration Date:	10 Feb 2021
First Registration Date:	10 Feb 2021
Transfer Count:	1
Actual ARF Paid:	\$41,479.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Feb 2031
PARF Rebate Amount:	\$31,109.00
Intended COE Rebate Details	
COE Expiry Date:	09 Feb 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,100.00
COE Rebate Amount:	\$32,579.00
Total Rebate Amount:	\$63,688.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 08 Aug 2024

OK



Lexus UX200 Executive

\$147,800 Instalment \$1,306/mth

PREMIUM AD

💰 Apply for 2.48% loan

♡ Shortlist

📄 Loan Calculator

NEW CAR DISCOUNTS & OFFERS

BEST DEAL DAILY!

▶ **VIEW ALL
PROMO**

Overview Financial Leasing Photo Research

Depreciation	\$18,980 / year
Reg. Date	19-Apr-2021 (6yrs 8mths 10days COE left)
Manufactured	2020
Mileage	61,000 km (18.4k / year)
Transmission	Auto
Engine Cap	1,987 cc
Road Tax	\$1,198 / year
Power	127.0 kW (170 bhp)
Curb Weight	1,485 kg
COE	\$52,309
OMV	\$35,342
ARF	\$41,479
Dereg Value	\$66,135 as of today