

(08/11/13) Wef

ASS. REC. BY:

REF:

CS/AGI 24080102/Rnp3

4856

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 71434

at Workshop m/s

of SION LEE ST #01-61

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 29K

We will be advising our principal a cost of repair L/S \$3,700.00 /- with 05 days

(red, 8913.9, 70%)

Date/Time, File Pass to?

☐

Prel. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL


Add Fee:

☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

)



Veh No: SLU 71434

Yr Regn: 2017 / DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA VEZEL HYBRID 1.5XACC 1496

Colour:

GREEN

A/C: Insured / Std / NI / NA

Sp. Reading:

469099

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

R431253181

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

03/08/24

D.O.I.

07/08/24

Survey held at

SION LEE ST

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

FIX AUTO PTE LTD

5 SOON LEE STREET # 01-61 (PIONEER POINT) SINGAPORE 627607

PEK KONG HWA
5 Soon Lee Street
01-61 (Pioneer Point)
Singapore 627607

07th August 2024

Accident date: 03rd August 2024

Estimated repair cost for vehicle no: SLU7143Y HONDA VEZEL 1.5 (COE DEC 2027)

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet X		\$1,150.00
2	1	Front bonnet lock X		\$188.00
3	1	Front head lamp -RH <i>br</i>		\$1,785.00
4	1	Front head lamp lower bracket-RH <i>can</i> X		\$122.00
5	1	Front bumper <i>de</i>		\$890.00
6	2	Front bumper side bracket <i>cut</i>	\$135.00	\$270.00
7	1	Front bumper clips-SET <i>re</i>		\$60.00
8	1	Front bumper number plate X		\$100.00
9	1	Front bumper reinforcement <i>bt</i>		\$552.00
10	1	Front bumper mud shield -RH <i>cut</i>		\$185.00
11	1	Front bumper center lower garnish X		\$220.10
12	1	Front bumper center lower cover X		\$455.00
13	1	Front Bumper Fog lamp -RH		\$215.00
14	1	Front Bumper Fog lamp cover-RH		\$155.00
15	1	Front Grille X		\$411.00
16	1	Front Grille emble logo X		\$100.00
17	1	Front Grille clips-SET X		\$65.00
18	1	Front fender-RH <i>bt</i>		\$768.00
19	1	Front fender inner cowling -RH <i>de</i>		\$188.00
20	1	Front R/H fender logo <i>re</i>		\$58.80
21	1	front lower arm-RH X		\$388.00
22	1	Front knuckle arm-RH X		\$385.00
23	1	Front bearing-RH X		\$211.00
24	1	front shock absorber-RH X		\$512.00
25	1	front tyre -RH X		\$350.00
26	1	front rim -RH X		\$600.00
Subtotal :-				\$10,383.90

Labour charges

To remove & re-fix front undercarriage -RH X \$200.00X

Wheel alignment (computer) X \$150.00X

To Check Wiring System

Tuff Kote

Towing charges

Panel beating

Spray painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :-

Total:-

\$2,230.00

\$12,613.90

Repair
Hp 90010068
5 days
4/8
07/08/24
Repair after
repair

30 ~~\$60.00~~
40 ~~\$120.00~~
100.00 *? receipt*
800.00 *400*
800.00 *600*

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	485G
Vehicle Details	
Vehicle No.:	SLU7143Y
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Aug 2024
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	LEB5953197
Chassis No.:	RU31253181
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$25,291.00
Original Registration Date:	12 Dec 2017
First Registration Date:	12 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2027
PARF Rebate Amount:	\$3,250.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$17,946.00
Total Rebate Amount:	\$21,196.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 08 Aug 2024

OK



Honda Vezel Hybrid 1.5A X

\$51,800 Instalment \$1,005/mth

PREMIUM AD

Shortlist

Get Warranty

Loan Calculator



Overview Financial Photo Research

Depreciation	\$14,730 / year
Reg. Date	14-Dec-2017 (3yrs 4mths 5days COE left)
Manufactured	2017
Mileage	-
Transmission	Auto
Engine Cap	1,496 cc
Road Tax	\$682 / year
Power	112.0 kW (150 bhp)
Curb Weight	1,280 kg
Fuel Type	Petrol-Electric
COE	\$57,390
OMV	\$25,121
ARF	\$5,000
Dereg Value	\$22,464 as of today