



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24080105/Rnp3e2
16 RAFFLES QUAY	Date:	07/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2182P	Veh. Inspected	SDN 6262A
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24006829MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	07/08/2024

2. Vehicle Details

Make & Model	TOYOTA RAV4 2.0 PREMIUM	C.C	1987
Engine No.	M20AV213491	Year of Reg.	27/10/2020
Chassis No.	JTMY43FV40D056477	Colour	WHITE
Odometer	60943 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/60 R18	MICHELIN	6
L/H Front Tyre	225/60 R18	MICHELIN	6
R/H Rear Tyre	225/60 R18	MICHELIN	6
L/H Rear Tyre	225/60 R18	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/08/2024	Inspection Date	07/08/2024
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 19 Working Days