

(08/11/13) Wef

REF:

CS/FC124080105/Rnp3

747E

ASS. REC. BY:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP/WS/TP RES/OD RES/EVA/INV/MV)

To Inspect Vehicle No: SDN 6262A

at Workshop m/s BERNKO MOTORS

of 2, PANDAN C

Insured:

FC12

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

140k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDN 6262A

Yr Regn:

2020 / 009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA RAV4 2.0 PREMIUM

c.c 1987

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

60943

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTMH43FV400056477

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A

04/08/24

D.O.I.

01/08/24

Survey held at

PANDAN G

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 88K

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

o. Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mr Han Choon Poo 62 Jalan Binchang Singapore 573952 Mobile: 96350607		
			Document No.				
			0				
			Document Date				
			05/08/2024				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTMY43FV40D056477	M20AV213491	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI TP INS:First Capital Insurance Ltd TP VEH:SHB2182P DATE OF ACC:04.08.2024				50 100.00
2	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP				134.64
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
4	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON FRONT RADAR SEN SOR				198.00
5	S	BP-SUBLET SUPPLY NO PLATE - FRONT & BACK				160.00
6	B	BP-LAB2 REPLACE ACC DAMAGED PARTS - FRONT				2376.00
7	B	BP-RES2 RESPRAY ACC AFFECTED AREAS - FRONT				1968.00
8	Z	BP-SLANT SUPPLY SEALANT (NETT) - REAR				300.00
9	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR -R EAR				198.00
10	B	BP-LAB2 CHECK WIRING SYSTEM				134.64
11	B	BP-LAB2 REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE. R/I REAR REVERSE CAMERA TO FAC REPAIR.				540.00
12	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR - REAR				326 782.00
13	B	BP-WS2 REPLACE TAILGATE GLASS				594.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total Less Amount Due
	Please acknowledge receipt of vehicle 	Parts Labour Sublet Lubrication/Fluid Others	

Borneo Motors



Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mr Han Choon Poo 62 Jalan Binchang Singapore 573952 Mobile: 96350607		
			Document No.				
			0				
			Document Date				
			05/08/2024				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTMY43FV40D056477	M20AV213491	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	S	BP-SUBLET SUPPLY SOLAR FILM				480.00
15	S	BP-SUBLET REPLACE KICK SENSOR				198.00
16	B	BP-MECH2 REPLACE REAR EXHAUST PIPE SYSTEM				792.00
17	B	BP-LAB2 REPLACE ACC DAMAGED PARTS - REAR				3168 6836.00
18	B	BP-RES2 RESPRAY ACC AFFECTED AREAS - REAR				3780 5248.00
19	Z	BP-SUNDRY SUPPLY REAR BUMPER TOP CHROME				380.00
20	1	T52119-4A916 COVER, FR BUMPER	1.00	636.90		636.90
21	2	T52437-42901 COVER, FR BUMPER	1.00	27.10		27.10
22	3	T52438-42901 COVER, FR BUMPER	1.00	27.10		27.10
23	4	T53285-42120 COVER, FR BUMPER ARM	1.00	25.10		25.10
24	5	T53286-42130 COVER, FR BUMPER ARM	1.00	25.10		25.10
25	6	T53113-42121 GRILLE, RADIATOR	1.00	395.50		395.50
26	7	T52114-42150 BRACKET, FR BUMPER	1.00	110.80		110.80
27	8	T52411-42110 GUARD, FR BUMPER	1.00	502.70		502.70
28	9	T52711-42140 B0 MOULDING, FR BUMPER	1.00	661.60		661.60
29	0	S52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00
30	1	T53395-42080 SEAL, HOOD TO FR END	1.00	118.50		118.50
31	2	T52535-42050 RETAINER, FR BUMPER	1.00	150.50		150.50
32	3	T52536-42080 RETAINER, FR BUMPER	1.00	150.50		150.50
33	4	T90467-07215 CLIP	10.00	3.60		36.00

For & on behalf of		Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd				
		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
				Amount Due



Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	Mr Han Choon Poo 62 Jalan Binchang Singapore 573952 Mobile: 96350607
	Document No. 0	
	Document Date 05/08/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTMY43FV40D056477	M20AV213491	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
34	5	T52614-42120 ABSORBER, FR BUMPER ?	1.00	124.50		124.50
35	6	T52021-42200 REINFORCEMENT ?	1.00	1061.60		1061.60
36	7	T53141-33130 GARNISH, RADIATOR ?	1.00	1091.60		1091.60
37	8	T53112-42190 GRILLE, RADIATOR, ?	1.00	443.50		443.50
38	9	T53123-42020 MOULDING, RADIATOR X	1.00	60.70		60.70
39	0	T53124-42060 MOULDING, RADIATOR X	1.00	60.70		60.70
40	1	T53115-42010 BRACKET, RADIATOR ?	1.00	458.90		458.90
41	2	T53510-42150 LOCK ASSY, HOOD X ?	1.00	188.00		188.00
42	3	T53019-42020 SHUTTER SUB-ASSY, ?	1.00	457.70		457.70
43	4	T16681-25010 PLATE, RADIATOR UPR ?	1.00	154.80		154.80
44	5	T90467-10216 CLIP ?	10.00	4.80		48.00
45	6	T16594-25020 GUIDE, RADIATOR AIR, ?	1.00	87.50		87.50
46	7	T16593-25110 GUIDE, RADIATOR AIR, ?	1.00	137.10		137.10
47	8	T16595-25120 GUIDE, RADIATOR AIR, ?	1.00	122.10		122.10
48	9	T81145-42A23 UNIT, HEADLAMP ?	1.00	5536.60		5536.60
49	0	T81185-42A23 UNIT, HEADLAMP cm	1.00	5536.60		5536.60
50	1	SPC507-42001 RAV4 BACK SENSOR RES ?	1.00	221.80		221.80
51	2	T51931-42030 CARRIER, SPARE WHEEL ?	1.00	28.70		28.70
52	3	T64777-42071 CUSHION, SPARE WHEEL ?	1.00	273.50		273.50
53	4	T52159-42230 COVER, RR BUMPER de	1.00	480.20		480.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	



cape
Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mr Han Choon Poo			
			Document No. 0		62 Jalan Binchang			
			Document Date 05/08/2024		Singapore 573952 Mobile: 96350607			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTMV43FV40D056477		M20AV213491	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
54	5	S52161-0K040 PIECE, RR BUMPER			10.00	5.80		58.00
55	6	T52453-42040 B0 GUARD, RR BUMPER			1.00	901.50		901.50
56	7	L75392-35220 RETAINER, OUTSIDE			4.00	5.60		22.40
57	8	T52161-42944 PIECE, RR BUMPER, RH			1.00	472.20		472.20
58	9	T52162-42944 PIECE, RR BUMPER, LH			1.00	472.20		472.20
59	0	T52155-42050 SUPPORT, RR BUMPER			1.00	112.50		112.50
60	1	T52562-42060 RETAINER, RR BUMPER			1.00	150.50		150.50
61	2	T52156-42050 SUPPORT, RR BUMPER			1.00	112.50		112.50
62	3	T52563-42050 RETAINER, RR BUMPER			1.00	150.50		150.50
63	4	T52023-42060 REINFORCEMENT			1.00	551.50		551.50
64	5	T891B1-42030 BRACKET, KICK DOOR			1.00	205.20		205.20
65	6	T891B2-0W050 SENSOR, KICK DOOR			1.00	768.30		768.30
66	7	T89747-30040 BUZZER, WIRELESS			1.00	187.50		187.50
67	8	T31364-42020 WIRE, CLUTCH CONTROL			1.00	186.40		186.40
68	9	T58307-42080 PANEL SUB-ASSY, BODY			1.00	1058.90		1058.90
69	0	T58301-42902 PAN SUB-ASSY, RR			1.00	886.30		886.30
70	1	T58327-42030 INSULATOR, MAIN			1.00	233.90		233.90
71	2	T64730-42221 C0 PANEL ASSY, DECK			1.00	870.90		870.90
72	3	T64740-42161 C0 PANEL ASSY, DECK			1.00	825.10		825.10
73	4	T58387-42130 C0 PLATE, RR FLOOR			1.00	334.70		334.70
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		



scope
 Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details					
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept		S1000005 / ICFC1	Mr Han Choon Poo					
		Document No. 0	62 Jalan Binchang					
		Document Date 05/08/2024	Singapore 573952 Mobile: 96350607					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTM43FV40D056477		M20AV213491	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
74	5	T58410-42120 C1 BOARD ASSY, DECK ?			1.00	1034.30		1034.30
75	6	T58416-42070 C0 BOARD, RR FLOOR, ?			1.00	207.00		207.00
76	7	T58417-42070 C0 BOARD, RR FLOOR, ?			1.00	207.00		207.00
77	8	T58577-42150 C0 PLATE, RR FLOOR MAT ?			1.00	645.40		645.40
78	9	T64779-42050 STOPPER, SPARE WHEEL ?			1.00	248.40		248.40
79	0	T67005-42650 PANEL SUB-ASSY, BACK ?			1.00	3113.60		3113.60
80	1	T67881-42070 WEATHERSTRIP, BACK ?			1.00	465.30		465.30
81	2	T68105-42300 GLASS SUB-ASSY, BACK ?			1.00	1706.50		1706.50
82	3	T62785-60030 SPACER, QUARTER ?			2.00	8.20		16.40
83	4	T21000-20 SIKI 182010 SIKI TACK GO! (BLA ?			2.00	108.00		216.00
84	5	T21000-22 SIKI 207. G+P ADHESIVE PRIMER ?			1.00	200.00		200.00
85	6	T76802-42140 GARNISH SUB-ASSY, ?			1.00	332.40		332.40
86	7	T67750-42060 C0 BOARD ASSY, BACK ?			1.00	647.90		647.90
87	8	T69350-42080 LOCK ASSY, BACK DOOR ?			1.00	1100.10		1100.10
88	9	T75431-42180 EMBLEM, BACK DOOR, ?			1.00	75.70		75.70
89	0	T75606-42150 MOULDING SUB-ASSY, ?			1.00	154.40		154.40
90	1	T90467-07215 CLIP ?			10.00	3.60		36.00
91	2	T81551-42230 LENS & BODY, RR ?			1.00	748.10		748.10
92	3	T81561-42230 LENS & BODY, RR ?			1.00	748.10		748.10
93	4	S81910-0K030 REFLECTOR ASSY, REFL ?			1.00	91.80		91.80
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total		
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		



Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details			
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept				S1000005 / ICFIC1		Mr Han Choon Poo 62 Jalan Binchang Singapore 573952 Mobile: 96350607			
				Document No.					
				0					
				Document Date					
				05/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	MXAA52R	ANXGBW P3	27/10/2020	SDN6262A	0	32099	72/DS/SDN6262A		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTMV43FV40D056477		M20AV213491	60	Thomas Pang W T	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
94	5	S81920-0K010	REFLECTOR ASSY, REFL ?			1.00	91.80		91.80
95	6	T89997-30100	ANTENNA, ELECTRICAL ?			1.00	100.00		100.00
96	7	T17408-25042	BAFFLE SUB-ASSY, ?			2.00	217.60		435.20
97	8	T17430-25221	PIPE ASSY, EXHAUST ?			1.00	2436.70		2436.70
98	9	T17565-28010	SUPPORT, EXHAUST ?			1.00	68.20		68.20
99	0	T17577-25010	BRACKET, EXHAUST ?			1.00	76.60		76.60
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ <i>Rasul</i> <i>Ap 90010068</i> <i>12clup</i> <i>07/08/24</i> <i>Pay by print</i>									
For & on behalf of			Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd							64,390.68		
			Please acknowledge receipt of vehicle				GST 9.00%		
					Parts 43,263.40		5,795.16		
					Labour 20,289.28				
					Sublet 838.00				
					Lubrication/Fluid 0.00		Less 0.00		
					Others 0.00		Amount Due 70,185.84		

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	747E
Vehicle Details	
Vehicle No.:	SDN6262A
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	RAV4 2.0 PREMIUM SUV (AUTO) (2WD)
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	M20AV213491
Chassis No.:	JTMY43FV40D056477
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$30,048.00
Original Registration Date:	27 Oct 2020
First Registration Date:	27 Oct 2020
Transfer Count:	0
Actual ARF Paid:	\$34,068.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Oct 2030
PARF Rebate Amount:	\$25,551.00
Intended COE Rebate Details	
COE Expiry Date:	26 Oct 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,990.00
COE Rebate Amount:	\$25,475.00
Total Rebate Amount:	\$51,026.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 08 Aug 2024

OK



Toyota Rav4 2.0A Premium

\$140,000

Instalment \$1,545/mth

CONSIGNMENT

[\\$ Apply for 2.48% loan](#)[♡ Shortlist](#)[✔ Get Warranty](#)

Overview

Financial

Leasing

Photo

Research

Depreciation

[i](#) \$19,890 / year

Reg. Date

14-Oct-2020

(6yrs 2mths 5days COE left)

Manufactured

[i](#) 2020

Mileage

71,000 km (18.6k / year)

Transmission

Auto

Engine Cap

1,987 cc

Road Tax

[i](#) \$1,198 / year

Power

127.0 kW (170 bhp)

[View specs of the Toyota RAV4 \(2019-2022\)](#)

Curb Weight

[i](#) 1,530 kg

COE

[i](#) \$40,989

OMV

[i](#) \$30,048

ARF

[i](#) \$34,068

Dereg Value

[i](#) \$50,897 as of today