



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080111/Avh3e2
75 BRAS BASAH ROAD	Date:	22/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 8043T	Veh. Inspected	SME 6720K
Policy No.	-	Coverage	0
Claim No.	MT/1289182-002	Excess	\$0.00
Assign From	JEFF LIN	Assign Date	07/08/2024

2. Vehicle Details

Make & Model	HONDA MOBILIO	C.C	1497
Engine No.	L15Z12100047	Year of Reg.	10/04/2015
Chassis No.	MRHDD4870FP000033	Colour	WHITE
Odometer	316459 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/55 R15	YOKOHAMA	6
L/H Front Tyre	195/55 R15	YOKOHAMA	6
R/H Rear Tyre	195/55 R15	YOKOHAMA	6
L/H Rear Tyre	195/55 R15	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/08/2024	Inspection Date	07/08/2024 (16:36)
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days