

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

06/08/2024 15:52

JOB-NO: 50116290

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB2324Y

TRANS: AUTO

CHASSIS: JTDKB3FUX03564302

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZRS064167

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHT AND PANEL BEAT ACCIDENT AREA	1.00	0.00	0.00	0.00		Y	600
2 RUST PROOFING	1.00	0.00	0.00	0.00		Y	Xnn
3 SUNDRIES	1.00	0.00	0.00	0.00		Y	200
4 DIAGNOSTIC(CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	1.00	0.00	0.00	0.00		Y	80
5 R&R SPARE TYRE & CARPET & TRIM & BOARD	1.00	0.00	0.00	0.00		Y	Xnn
6 R&R REVERSE SENSOR	1.00	0.00	0.00	0.00		Y	40
7 R&R TAILGATE COMPONENTS	1.00	0.00	0.00	0.00		Y	Xnn
8 R&R TAILGATE WINDSCREEN UPPER & LOWER	1.00	0.00	0.00	0.00		Y	Xnn
9 R&R TAILGATE SPOILER	1.00	0.00	0.00	0.00		Y	Xnn
10 RESPRAY REAR BUMPER	1.00	0.00	0.00	0.00		Y	200
11 RESPRAY REAR BUMPER EXTENSION DIFFUSER LH	1.00	0.00	0.00	0.00		Y	Xnn
12 RESPRAY REAR BUMPER DIFFUSER	1.00	0.00	0.00	0.00		Y	Xnn
13 RESPRAY REAR END PANEL	1.00	0.00	0.00	0.00		Y	Xnn
14 RESPRAY REAR FENDER LH	1.00	0.00	0.00	0.00		Y	200
15 RESPRAY REAR FENDER RH	1.00	0.00	0.00	0.00		Y	Xnn
16 RESPRAY TAILGATE	1.00	0.00	0.00	0.00		Y	Xnn
17 RESPRAY TAILGATE OUTER GARNISH	1.00	0.00	0.00	0.00		Y	200
18 RESPRAY TAILGATE HINGE LH & RH	1.00	0.00	0.00	0.00		Y	Xnn
TOTAL:		0.00	0.00	0.00			

MATERIALS

1 REAR BUMPER	1.00	442.60	110.65	331.95 /	L	Y	
2 REAR BUMPER REINFORCEMENT	1.00	332.70	83.18	249.52 /	L	Y	
3 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	126.30	31.58	94.72	L	Y	
4 REAR BUMPER DIFFUSER	1.00	576.30	144.08	432.22 /	L	Y	
5 REAR BUMPER RETAINER LH	1.00	117.70	29.43	88.27 /	L	Y	
6 REAR BUMPER UNDER COVER LH	1.00	241.90	60.48	181.42	L	Y	
7 REAR BUMPER UNDER COVER CENTER	1.00	229.90	57.48	172.42	L	Y	
8 SEAL, REAR BUMPER SIDE, LH	1.00	88.50	22.13	66.37	L	Y	
9 REAR BUMPER EXTENSION DIFFUSER LH	1.00	123.70	30.93	92.77	L	Y	
10 BOX, DECK FLOOR, LH	1.00	313.60	78.40	235.20	L	Y	
11 TAILLAMP UPPER LH	1.00	443.30	110.83	332.47 /	L	Y	
12 TAILLAMP LOWER LH	1.00	502.00	125.50	376.50 /	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
13 TAILLAMP LOWER LED BULB LH (STOP LAMP) <i>Xm</i>	1.00	90.50	22.63	67.87	L	Y	
14 TAILLAMP LOWER LED BULB LH (FOG LAMP) <i>Xm</i>	1.00	94.80	23.70	71.10	L	Y	
15 TAILGATE <i>Xm</i>	1.00	1,147.80	286.95	860.85	L	Y	
16 TAILGATE HINGE LH <i>Xm</i>	1.00	61.00	15.25	45.75	L	Y	
17 TAILGATE HINGE RH <i>Xm</i>	1.00	61.00	15.25	45.75	L	Y	
18 TAILGATE OUTER GARNISH <i>sa</i>	1.00	925.60	231.40	694.20	L	Y	
19 TAILGATE EMBLEM - HYBRID <i>m</i>	1.00	54.60	13.65	40.95	L	Y	
20 TAILGATE EMBLEM - TOYOTA LOGO <i>m</i>	1.00	47.90	11.98	35.92	L	Y	
21 TAILGATE EMBLEM - PRIUS <i>m</i>	1.00	54.60	13.65	40.95	L	Y	
22 REAR BUMPER SMART KEY ANTENNA <i>Xm</i>	1.00	72.00	18.00	54.00	L	Y	
23 REAR END PANEL <i>Xm</i>	1.00	650.30	162.58	487.72	L	Y	
24 TAILLAMP PANEL LH <i>Xm</i>	1.00	103.40	25.85	77.55	L	Y	
25 TAILLAMP COVER LH <i>Xm</i>	1.00	64.50	16.13	48.37	L	Y	
26 REAR BUMPER CLIP SET <i>m</i>	1.00	50.00	0.00	50.00	S	Y	
27 REAR BUMPER UNDER COVER CLIP SET <i>Xm</i>	1.00	45.00	0.00	45.00	S	Y	
28 REAR BUMPER EXTENSION DIFFUSER LH CLIP SET <i>Xm</i>	1.00	35.00	0.00	35.00	S	Y	
29 REAR BUMPER ADS STICKER <i>m</i>	1.00	250.00	0.00	250.00	S	Y	
30 REAR REVERSE SENSOR SET <i>Xm</i>	1.00	230.00	0.00	230.00	S	Y	
31 REAR FENDER ADS STICKER LH <i>m</i>	1.00	250.00	0.00	250.00	S	Y	
32 REAR FENDER ADS STICKER RH <i>Xm</i>	1.00	250.00	0.00	250.00	S	Y	
33 REAR END PANEL SEALANT <i>Xm</i>	1.00	60.00	0.00	60.00	S	Y	
34 TAILGATE WINDSCREEN UPPER PRIMER <i>Xm</i>	1.00	20.00	0.00	20.00	S	Y	
35 TAILGATE WINDSCREEN UPPER SEALANT <i>Xm</i>	1.00	60.00	0.00	60.00	S	Y	
36 TAILGATE WINDSCREEN LOWER PRIMER <i>Xm</i>	1.00	20.00	0.00	20.00	S	Y	
37 TAILGATE WINDSCREEN LOWER SEALANT <i>Xm</i>	1.00	60.00	0.00	60.00	S	Y	
38 TAILGATE STICKER - ZIG LOGO & BOOK NOW <i>m</i>	1.00	150.00	0.00	150.00	S	Y	
39 TAILGATE STICKER - COMFORT DELGRO & 65521111 <i>m</i>	1.00	150.00	0.00	150.00	S	Y	
40 REAR FENDER STICKER -PETROL ONLY <i>Xm</i>	1.00	120.00	0.00	120.00	S	Y	
41 TAILLAMP PANEL SEALANT LH <i>Xm</i>	1.00	60.00	0.00	60.00	S	Y	
TOTAL:		8,776.50	1,741.69	7,034.81			
42 Rear fender RH repair							
TOTAL PARTS & LABOUR:		8,776.50	1,741.69	7,034.81			
43 Rear fender sealant RH <i>Xm</i>							
EXCESS/LOADING:\$S		0.00					

No. Of Day:

6 Days

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM \$S

DATE OF SURVEY: 07 / 08 / 24

SURVEYED BY: Rasm

CONTACT NO: 90010568

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

60190078

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved by Insurance Company

Acknowledged by Repairer

Signature:

Date: