



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080113/Anh3e2
75 BRAS BASAH ROAD	Date:	22/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHF 668Y	Veh. Inspected	GBD 8534D
Policy No.	-	Coverage	0
Claim No.	MT/1283973-003	Excess	\$0.00
Assign From	SHAFAWATI	Assign Date	07/08/2024

### 2. Vehicle Details

Make & Model	TOYOTA DYNA	C.C	2982
Engine No.	1KD2493947	Year of Reg.	15/06/2015
Chassis No.	JTFAT35Y10K204541	Colour	SILVER
Odometer	342649 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195 R15C	BRIDGESTONE	6
L/H Front Tyre	195 R15C	BRIDGESTONE	6
R/H Rear Tyre	155 R12C	HABILEAD	6
L/H Rear Tyre	155 R12C	HABILEAD	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	29/06/2024	Inspection Date	07/08/2024 (16:43)
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days