G NO:	21272900D				
O ADMIRA	ALTY STREET. I	NORTHLINK BUILDING			
01-10/11					
INGAPO	RE 757695				
ВМОТОБ	@SINGNET.CC	M.SG			
DATE	14/06/2024				
VEH	ICLE C	QUOTATION			
		2001/11/011			
BL3660	Μ - ΥΑΜΑΗΔ	TMAX 530 CVT ABS			
	IAWAWA	TIMAN OUU OVI MB3			
ITEM	PC	DESCRIPTION		PR	ICE
1	1 SET	R/S MIRROR COVER		Pd/lm \$153	
2 .	1	EXHAUST COVER		R \$295	
3	1	EXHAUST COVER SHORT		CM \$204	
4	1	R/S TAIL COVER		cm \$216	
5	1	R/S FOOT BOARD		CM \$275	
6	1	R/S LOWER COVER		CM \$180	
7	1	R/S CENTER COVER		cm \$234	
8	1	YAMAHA LOGO		na \$30	
9	1	R/S TOP COVER		CM \$210	
				\$1,797	.00
			LESS 10%	\$179	.70
				\$1,617	.30
10		TOW	-	0	
11		TOW	(Bill) \$120	
12		RE-SPRAY		\$550	
12		LABOUR CHARGE	(NETT)	\$400	
				\$2,687.	.30
			GST 9%		

Kenneth (CKIE) & 1800/2 1218/14 Renny After Pain

\$2,929.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: