



SPF/ paper survey 2

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120
T : (65) 6419 3000
www.aig.sg

Claim No: 4591583054SG Date of Survey: 11/07/2024
Repairer: PROGRESSIVE CAR CARE PTE LTD

REFERENCE

Insured: TOH SHENG HUI Policy No: 1900115762
Date of Loss: 05/07/2024 Nature of Claim: OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg. No: SMF3336B
Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A) Reg. Date: 18/08/2018
Engine No: G4FGJU204237 Chassis No: KMHD841CMJU702988

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable): Yes Engine Modification: No
Handbrake (Serviceable): Yes Steering (Serviceable): Yes Pre-accident Condition: Good

TOTAL OFFER

Offer Authorized By: LAU, JASON on 15 Jul 2024 12:22
Offer Initiated By: LAU, JASON on 15 Jul 2024 12:18
Rep. Gross Total: **S\$5,215.54** [Diff: S\$0.00, 0.00%]
Approved Gross Total: **S\$5,215.54**
- Excess: **S\$600.00** [Remarks: Not Applicable]
+ GST (9.00%): **S\$415.40**
Approved Nett Amount: **S\$5,030.94**
(No Betterment/Depreciation)

COST OF CLAIMS

	Repairer's	Our Offer	Difference	Diff %
Parts	4,108.70	4,108.70	0.00	0.00
Miscellaneous Items	117.00	117.00	0.00	0.00
Labour	398.40	398.40	0.00	0.00
Paintwork Labour	591.44	591.44	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,215.54	5,215.54	0.00	0.00

- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	4,615.54	4,615.54	0.00	0.00
+ GST 9.00/9.00% (\$\$)	415.40	415.40	0.00	0.00
Nett Amount (\$\$)	5,030.94	5,030.94	0.00	0.00

SURVEYOR'S REMARKS

This inspection is conducted on a "Without Prejudice Basis"

Estimated repair period : 5.0 days

Authorised Repair : Yes

Inspection conducted by : Lau, Jason (AIG Claims Dept)

Signature : _

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET (Used part)	Bent ✓	595.00 US	*595.00 US ✓
2	1	NA	*BONNET INSULATION Photo	Distorted ✓	115.00 F	*115.00 F ✓
3	1	NA	*BONNET LOCK	Jammed / Damaged ✓	65.00 F	*65.00 F ✓
4	1	NA	*CONDENSER (Used part)	Bent	364.00 US	*364.00 US ✓
5	1	NA	*COWL PANEL COVER	Broken ✓	130.00 F	*130.00 F ✓
6	1	NA	*FRONT BONNET SEAL	Damaged	20.00 F	*20.00 F ✓
7	1	NA	*FRONT BUMPER (Used part)	Deformed	384.00 US	*384.00 US ✓
8	1	NA	*FRONT IMPACT DAMPER	Broken	90.00 F	*90.00 F ✓
9	1	NA	*FRONT PANEL CPL	Broken	360.00 F	*360.00 F ✓
10	1	NA	*FRT BUMPER CLAMP KIT	Necessary	15.00 F	*15.00 F ✓
11	1	NA	*FRT NO PLATE REINF	Bent	15.00 F	*15.00 F ✓
12	1	NA	*GRILLE (Used part)	Broken	280.00 US	*280.00 US ✓
13	1	NA	*INSULATION MNTG KIT	Necessary	15.00 F	*15.00 F ✓
14	1	NA	*L/BONNET HINGE	Bent	30.00 F	*30.00 F ✓
15	1	NA	*LEFT HEADLAMP ASSY (Used part)	Broken	480.00 US	*480.00 US ✓
16	1	NA	*R/BONNET HINGE	Bent	30.00 F	*30.00 F ✓
17	1	NA	*R/F WING BRACKET	Bent	16.00 F	*16.00 F ✓
18	1	NA	*R/HEADLAMP REINF	Broken	18.00 F	*18.00 F ✓
19	1	NA	*R/RADIATOR AIR GUIDE	Damaged	25.00 F	*25.00 F ✓
20	1	NA	*RAD GRILLE BRACKET	Broken	55.00 F	*55.00 F ✓
21	1	NA	*RADIATOR (Used part)	Bent	385.00 US	*385.00 US ✓
22	1	NA	*RIGHT HEADLAMP ASSY (Used part)	Broken	480.00 US	*480.00 US ✓
23	1	NA	*WASHER CONTAINER	Distorted	38.00 F	*38.00 F ✓

F=Franchise part. U=Used part. S=SpcNett.

Sub Total (\$\$)	4,005.00	4,005.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	103.70	103.70
Total Parts (\$\$)	4,108.70	4,108.70

AIG Asia Pacific Insurance Pte. Ltd./SMF3336B/15/07/2024 12:22

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AIRCON GAS Check	50.00	50.00 ✓
2	1	ANTI FREEZE Check	20.00	20.00 ✓
3	1	FRT NO PLATE	35.00	35.00 ✓
4	1	OD/TP Case (Insurer)	12.00	12.00 ✓
Sub Total (\$\$)			117.00	117.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Labour	New	412.80	412.80
2	Total Paint Materials	New	178.64	178.64
Labour Items				
3	Total Panel/Mechanical Labour	New	398.40	398.40
Gross Labour Cost (\$\$)			989.84	989.84

AIG Asia Pacific Insurance Pte. Ltd./SMF3336B/15/07/2024 12:22

< END OF REPORT >