

Daphne.

Vehicle Number : SMG7633L
 Vehicle Model : TOYOTA VIOS
 Accident Date : 01.11.2023
 Original Reg Date : 31.12.2018

Date : 05.08.2024
 Chassis : MR2B23F3901160273
 TP Ins. CHINA TAIPING
 AIG.

ESTIMATE

1	1 pc	Rear Bumper <i>2hd</i>		686.70	✓ 565
2	1 pcs	Rear Bumper Side Retainers <i>cut</i>	85.80	85.80	✓
3	2 pcs	Rear Bumper Attachment Retainers <i>new</i>	69.30	138.60	+
4	2 pcs	Rear Bumper reinforcement Brackets	92.10	184.20	+
5	1 pcs	Rear Bumper Reflectors <i>cut</i>	168.50	168.50	✓
6	1 pc	End Panel <i>new</i>		645.30	+
7	1 pc	End Panel Top Trim		186.90	+
8	1 pc	Rear Air Vent LH		86.20	+
9	2 pcs	Rear Fender Inner Trim <i>new</i>	286.30	286.30	+
10	2 pcs	Rear Fender Inner Shield	125.80	125.80	+
11	2 pcs	Bootlid lamp <i>new</i>	408.20	408.20	+
12	1 pcs	Taillamps <i>new</i>	468.60	468.60	+
13	1 pcs	Taillamps Inner Sealer <i>new</i>	38.00	38.00	+
14	1 pcs	Taillamps Panels	131.50	131.50	+

SUBTOTAL 3,640.60

Less 25% 910.15

TOTAL 2,730.45

941.50

705.75

SPECIAL NETTS

1	1 set	End Panel Joint Sealant <i>new</i>		150.00	+
2	1 pc	Rear Number Plate with Cover <i>new</i>		50.00	+
3	1 set	Rear Bumper Clips <i>new</i>		30.00	✓
4	1 set	End Panel Top Trim Clips <i>2</i>		30.00	+
5	2 set	Rear Fender Inner Trim Clips <i>new</i>	40.00	80.00	+
6	2 set	Rear Fender Inner Shield Clips <i>new</i>	30.00	60.00	+
7	2 set	Taillamps Clips	30.00	60.00	+
8	1 set	Reverse Sensor		250.00	+

30

Panel Beating		1,200.00	200
---------------	--	----------	-----

Spray painting		1,200.00	40
Check Wiring on tailamp		120.00	+
Anti rust		180.00	+
Remove and install interior upholstery		120.00	+
Remove and install reverse sensor		120.00	50
Remove and install reverse camera		150.00	+
To conduct reset and management unit calibration		250.00	+
To four wheel alignment		120.00	+

650

total \$ 6,900.45
less 20% 1,380.09
Lump sum 5,520.36

Adrian Wry,
1/s 05/08/24.
02 Days.

Total: 1385.75
y/s: 1.1K

1.1K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date: