



HYUNDAI

KOMOTO MOTORS PTE LTD.

250, Telok Ayer St, Singapore 068601
TEL: 6472 7688 FAX: 6472 7689
250 Telok Ayer St

(GST REGISTRATION NO: MR-8500364-4)

Date :

MS FIRST CAPITAL Insurance Pte Ltd

Attn: Motor Claims Department

Vehicle number : SMG9565L
Make and model : AVANTE 1.6 4DR AUTO
Registration Date : 05/01/2019
Chassis number : KMHD841CMKU815946
Engine number : G4FGJU044796

Claim Officer : Robyn
Job No. :
Owner name : CHONG CHEE WEI
Date of Acc : 03/08/2024
Policy number : A 300743551 AHM
Claim Type : TP

Items :		2nd	Estimate	Revised
1	FRT BUMPER CLIP X10 <i>sc</i> ✓	865952T500	\$	20.00
2	LAMP ASSY-FRONT TURN SIGNAL, LH <i>Xm</i>	92301F2500	\$	165.00
3	BRACKET-FR BUMPER SIDE, LH <i>?Xm</i>	86513F2AA0	\$	14.00
4	COVER-FR BUMPER <i>scxm</i>	86511F2AA0	\$	573.00
5	MOULDING-FRONT BUMPER, LH <i>Xm</i>	86563F2AA0	\$	29.00
6	GRILLE-FRONT BUMPER SIDE, LH <i>Xm</i>	86561F2AA0	\$	34.00
7	LIP ASSY-FRONT BUMPER <i>Xm</i>	86591F2AA0	\$	76.00
8	LAMP ASSY-HEAD, LH <i>sc</i> ✓	92101F2520	\$	1,205.00
			\$	2,116.00
Less 20% Discount			\$	423.20
Material total			\$	1,692.80

Vehicle number

: SNG5736A

Body, Paint & Labour Items:

		Estimate
1	To carry out accident body repair - FRT BUMPER / SUPPORT PANEL	\$ 840.00 420
	Complete putty and spray paint all affected areas - FRT	
2	BUMPER / FRT BUMPER LIP	\$ 1,140.00 760

Labour Charges:

	2nd	Estimate	Revised
3	TO REALIGN FRT HEADLAMP (S.NETT)	\$ 40.00	
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AFTER ACCIDENT REPAIR (S.NETT)	\$ 180.00	
5	TO PERFORM PREPROGRAMME AFTER ACCIDENT REPAIR (S.NETT)	\$ 180.00	
6	SUNDRIES	\$ 40.00 20	

Total Labour

\$ 2,420.00

Total Parts

\$ 1,692.80

Excess

\$ -

\$ 4,112.80

Add GST 9%

\$ 370.15

Grand Total

\$ 4,482.95

*** Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 90010068
3 days
13/08/24
Res by paint

SUPPLEMENTARY

Vehicle number : **SMG9565L**
Make and model : **AVANTE 1.6 4DR AUTO**
Registration Date : **05/01/2019**
Chassis number : **KMHD841CMKU815946**
Engine number : **G4FGJU044796**

Claim Officer : Robyn
Job No. :
Owner name : **CHONG CHEE WEI**
Date of Acc : **03/08/2024**
Policy number : **A 300743551 AHM**
Claim Type : **TP**

SUPPLEMENTARY Labour Charges:	2nd	Estimate	Revised
1 TO REPAIR FRONT BUMPER (S.NETT) <i>nee</i>		\$ 210.00	
2 TO REPAIR FRONT LHS FENDER PANEL (S.NETT) <i>nee</i>		\$ 210.00	
 Total Labour		\$ 420.00	\$ -
Total Parts			
Excess		\$ -	\$ -
		\$ 420.00	\$ -
 Add GST 9%		\$ 37.80	\$ -
Grand Total		\$ 457.80	\$ -

*** Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out***