



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080143/Uvh3
75 BRAS BASAH ROAD	Date:	30/08/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDZ 6628R	Veh. Inspected	SLL 4050Z
Policy No.	-	Coverage	0
Claim No.	MT/1289682-002	Excess	\$0.00
Assign From	EILEEN LEE	Assign Date	08/08/2024

2. Vehicle Details

Make & Model	HONDA VEZEL (A)	C.C	1496
Engine No.	L15B4036374	Year of Reg.	23/02/2017
Chassis No.	RU11116367	Colour	WHITE
Odometer	56724 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60R16	YOKOHAMA	6
L/H Front Tyre	215/60R16	YOKOHAMA	6
R/H Rear Tyre	215/60R16	YOKOHAMA	6
L/H Rear Tyre	215/60R16	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/08/2024	Inspection Date	08/08/2024 (13:28)
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days