



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24080147/Aqh3e2
(BUDGET DIRECT INSURANCE)	Date:	23/10/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 1506M	Veh. Inspected	SMG 3574A
Policy No.	P10736814R02	Coverage	0
Claim No.	C10030840 / JK	Excess	\$0.00
Assign From	-	Assign Date	08/08/2024

### 2. Vehicle Details

Make & Model	TOYOTA PREVIA	C.C	2362
Engine No.	2AZ1A85080	Year of Reg.	17/12/2018
Chassis No.	JTEGD56MX07165745	Colour	GREY
Odometer	67850 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55 R17	FORTUNE	6
L/H Front Tyre	215/55 R17	FORTUNE	6
R/H Rear Tyre	215/55 R17	FORTUNE	6
L/H Rear Tyre	215/55 R17	FORTUNE	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	29/07/2024	Inspection Date	12/08/2024
Survey held at	N-51 AUTOMOTIVE PTE LTD - 2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB SINGAPORE 417921		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days