



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24080149/Kqh3e2
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	20/08/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMR 5094Y	Veh. Inspected	SNE 715D
Policy No.	-	Coverage	0
Claim No.	AVS24/2445	Excess	\$0.00
Assign From	KAHARUDIN	Assign Date	08/08/2024

2. Vehicle Details

Make & Model	TOYOTA VIOS (A)	C.C	1496
Engine No.	2NR5567000	Year of Reg.	18/02/2022
Chassis No.	MR2B23F3001242893	Colour	METALLIC GREY
Odometer	25208 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60R15	DUNLOP	6
L/H Front Tyre	185/60R15	DUNLOP	6
R/H Rear Tyre	185/60R15	DUNLOP	9
L/H Rear Tyre	185/60R15	DUNLOP	9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/08/2024	Inspection Date	14/08/2024
Survey held at	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days