



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

12 August 2024

not Authorized

meras

12/8/24

2/s \$2800

Take photo of damage

4 days

REG NO.: SLZ 8343 D
MAKE/MODEL: HONDA FIT

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

AMT(\$)

QTY	DESCRIPTION		AMT(\$)
	<u>LIST ITEMS</u>		
1	Front door - LH <i>Body DD</i>	\$ 980.50	1,046.90
1	Front door glass outer moulding <i>up</i>	\$	131.60 X
1	Front door inner board <i>Re Torn</i>	\$ 422.30	662.50
1	Front door lock <i>Done</i>	\$ 241.50	305.50
1	Front door outer handle <i>11</i>	\$	136.50 X
1	Front door regulator come with motor <i>11</i>	\$	440.40 X
1	Front door rubber <i>11</i>	\$	165.50 X
1	Centre pillar -LH <i>11</i>	\$	1,119.80 X
1	Rocker panel -LH <i>11</i>	\$	598.75 X
1	Rear door -LH <i>DD/Seif</i>	\$ 960.50	1,046.90
1	Rear door checker <i>11</i>	\$	21.20 X
1	Rear door glass outer moulding <i>11</i>	\$	61.20 X
1	Rear door hinges <i>11</i>	\$	161.20 X
2	Rear door inner board <i>11</i>	\$	235.12 X
1	Rear door rubber <i>11</i>	\$	165.50 X
		\$	6,298.57
		Less 20%	\$ 1,259.71
			\$ 5,038.86

SPECIAL NETT ITEMS

1	Front door black tape (1 set) <i>11</i>	\$	120.00 50
1	Rear door black tape (1 set) <i>11</i>	\$	120.00 50
		\$	240.00

LABOUR CHARGES

S/N	DESCRIPTION		
1	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$	400.00 120
2	To apply undercoating.	\$	100.00 60
3	Panel beating.	\$	1,400.00 500
4	To re-spray painting on the affected areas.	\$	1,300.00 650
		\$	3,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1

Acknowledged by Repairer

Signature:

Date:

\$ 8,478.86

P. 260+80

202

2083.84

100

1330

3813

28