

## **SMRT Accident Vehicle Repair Estimates**

SMRT Autor 60 Woodland

FAX Number

Estimator Te

Accident Rep

Date Genera

User ID

China Taiping

	Section A - Accident De	etalls				
Registration Number	SHB1045J					
Case Reference Number	TAX/08/24/2012					
Registration Date	30/11/2020					
Company Type	Strides Premier Taxi Pte Ltd					
Make	TOYOTA					
Model	PRIUS4FL					
Name of Driver	ALVIN WEE THIAM LYE					
Type of Accident	Head to Rear					
Accident Date and Time	3/8/2024 9:25 PM					
Accident Reported Date and Time	5/8/2024 3:51 PM					
s Surveyor Required?	No					
Survey by						
Vehicle is Towed Back?	No					
Towed Back Date and Time						
Replacement Vehicle issued?	No					
Job Card Number	24122042					
Special Instruction to ARC,if any	DAMAGE TO THE REAR LEFT OF	TAXI				
Prepared Date and Time	8/8/2024 10:13 AM	7701				
Chassis Number	0.0000					
Mileage						
Work Shop						
Repair Completion Date and Time						
	Section B - Summary of Repai	r Estimates				
Summary of Repair Estimates						
	Quotation from ARC	Adjusted by Surveyor, if applicable				
Total Labour Cost	\$676.00	\$0.00				
Total Spray Cost	\$818.00	\$0.00				
Total Spare Part Cost	\$1,214.34	\$0.00				
Total Other Cost	\$500.00	\$0.00				
TOTAL COST	\$3,208.34	\$0.00				
Lump Sum Total	\$3,200.00	\$0.00				
Number of Repair Days	4.0	90.00				
Prepared / Adjusted By	ARC Manager Team					
ARC / Surveyor Sign Off Date	08/08/2024 10:20 AM	Sten CLKK)				
Signature	Towards	1/2/				
	7	± 12/8/24, 3.30 <sub>2</sub>				
		MI				
Remarks		1.10				
		- /s				
		$\sim$				
		<b>√</b>				
	Section C - Quotation and Acade					
transport of the second	Section C - Quotation and Acciden	t invoice Details				
Quotation Number	Invoice Nu	mber				
Quotation Date	Invoice Da					
Involce Amount						

	LKK Auto Consultar the Repairer of the To resurvey beforelafte To display damaged pe Parts prices are subject Third party survey is or No illegal medification Supplementary item(s is subject to final appro- Acknowledged by Repair Signature:	following; or apray painting ant(s) during resurvey at to confirmation on a "Without Prejudice (s) is allowed ) must be resurveyed oval from Insurance C	s' basis	ent Veh	icle Repair	Estimates	5			Estima. Accident R  Date Genera
TL	Date:		Section	on D - Deta	ails of Repair E	stimates				
Part 1	- Labour Works									
Job Sco	ope		***************************************	Quotation f	rom AR			Adjusted by S	urvey	or, if applicab
TO REPAIR REAR PORTION LH								000		
Total Labour				\$676,00				200		
Part 2	Spray Painting & P	anni Boating Rol	atad Warks	4070,00						
		and bouning room	ated Works							
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicab		
TO RESPRAY REAR BUMPER				\$378.00				200		
TO RESPRAY BUMPER BEAM				\$220.00				X		
TO RESPRAY REAR PANEL				\$220.00				X		
	pray Painting & Panel			\$818.00						
Job Sco		dent and Acciden	nt Repair Related Expens							
				Quotation from ARC				Adjusted by Surveyor, if applicab		
TO WASH AND VACUUM				\$60.00				√ nn		
TO CHECK WIRING AND SYSTEM FUNCTION TO APPLY RUST-PROOFING ON AFFECTED AREA				\$120.00				30 nec		
TO TEST AND REFIX REVERSE SENSOR SYSTEM				\$100.00 \$120.00				y nn		
TO REPLACE SUNDRY PARTS				\$100.00				y nn		
Total Other Costs				\$500,00				<b>⅓</b> nn 430		
Part 4 -	Spare Parts / Mater	ial Usage							_	100
Part Nur	mber Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator App	roved	Surveyor Ap
		52023-47030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace	nr	
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace X	R	
		52462-47130	PAD, RR BUMPER, RH & LH, 3	2.00	\$12.00	25.00	\$18.00	Replace X		
		52462-47030	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace X	nn	
		52462-47020	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace X	nn	
		52576-47060	RETAINER, RR BUMPER, LH	1.00	\$143.60	25.00	\$107.70	Replace X	nn	
		52161-16010	CLIPS PIECE, RR BUMPER	1.00	\$4.80	25.00	\$3.60	Replace X	nn	
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$405.00	25.00	\$303.75	Replace /	(u	7
		81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1.00	\$42.20	25.00	\$31.65	Replace X	nn	
		58399-47030	COVER, REAR FLOOR UNDER , LH	1.00	\$261.60	25.00	\$196.20	Replace X	nn	
			SENSOR REVERSE	1,00	\$180.00	0.00	\$180.00	Replace X	nn	
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	1,00	\$707.10	25.00	\$530.33	Replace X	nn	
Total					\$2,650,40		\$2,048.26			

303.75

Stock Number | Part Name

Part Number

Total

Portion

L/S - 243 + 430 = 673 = 650

Quantity

List Price \$

Discount (%)

Final Price (\$) ARC Check



Surveyor Cl