

Not Authorized
L/R \$ 2200/-

Trans-cab Auto Services Pte Ltd

AAD2408-032

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5379P

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

13 AUG 2024

SHC5379P

JTDKB3FU903093761

200303878K

TOYOTA

PRIUS GEN 4

7/8/2024

SNH4292P / III

25/2/2021

PART		LIST	
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	R 1,641.36 X
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	SL 243.81 X
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$	SL 493.40 X
1	WEATHERSTRIP, FRONT DOOR, LH	\$	SL 292.32 X
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	N 139.86 X
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	N 123.06 X
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	na 16.91 X
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	na 55.02 X
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	na 33.29 X
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	SL 1,161.83 X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	SL 300.62 X
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	R 1,634.33 ✓
1	GLASS SUB-ASSY, REAR DOOR, LH	\$	SL 518.07 X
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	\$	SL 243.81 X
1	HANDLE ASSY, REAR DOOR OUTSIDE, LH	\$	SL 123.06 X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$	SL 369.60 X
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	N 109.62 X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	N 124.74 X
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	na 27.62 —
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	na 44.00 —
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	na 19.43 —
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	N 756.74 X
1	PANEL SUB-ASSY, QUARTER, LH	\$	N 1,099.46 X
1	LINER, REAR WHEEL HOUSE, LH	\$	SL 176.09 X
TOTAL		\$	9,748.05

Trans-cab Auto Services Pte Ltd**AAD2408-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5379P

25%	\$	2,437.01
	\$	7,311.03

Special Nett

1SET DOOR TRIM CLIP	\$	nn	70.00	X
1SET DOOR WEATHERSTRIP CLIP	\$	nn	65.00	X
1 DOOR STICKER TRANSCAB	\$	nn	100.00	600N
1 DOOR STICKER TEL NO.	\$	nn	100.00	600N
1SET FENDER CLIP	\$	nn	65.00	X
1 FENDER LINER CLIP	\$	nn	65.00	X
TOTAL	\$		465.00	
TOTAL PARTS	\$		2,300.00	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		240.00	300
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	400
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	800
To reinstall rear bumper parking sensor.	\$	nn	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	200
To check steering geometry and computer wheel alignment	\$	nn	220.00	X

Trans-cab Auto Services Pte Ltd**AAD2408-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5379P

To remove and refit of rear fender fittings, attachment and
perform water seepage test.

	\$	~ 170.00 X
TOTAL	\$	4,720.00

Over All Total	\$	14,331.03
-----------------------	----	------------------

(PART-BY-PART) Repair Days~~07~~ Days

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHC5379P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	2ZR2H94675
Chassis No.:	JTDKB3FU903093761
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,879.00
Original Registration Date:	25 Feb 2021
First Registration Date:	25 Feb 2021
Transfer Count:	0
Actual ARF Paid:	\$7,131.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Feb 2029
PARF Rebate Amount:	\$5,348.00

Intended COE Rebate Details

COE Expiry Date:	24 Feb 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$31,876.00
COE Rebate Amount:	\$18,119.00
Total Rebate Amount:	\$23,467.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Aug 2024

OK