

ASSIGNMENT

Surveyor:

Kenneth

DOI:

22/02/14

Assg Date:

22/02/14

Pre-assign / CCU / FTE



Insured Vehicle No.:

XB 5471 X

Claim No.:

C0297655

Name of Insured:

Kuber Global P/L

Policy No.:

P1450576

Insured Tel No.:

HP:

Make / Model:

Mitsubishi

Excess Sec II :SS

1,000/-

D.O.A.:

20/02/14

Place of Accident:

Fort Rd Near LTA

Is driver the owner? (YES / NO)

(NO)

Nature of Accident:

If NO, Driver Name / Age:

Sundara

Bharathi

Senthikumar

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :8668 2352

(V/L: YES / NO Insured Liability :

% Final ? Yes / No



INSRS:

WSP: choy hoe

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

10/03/14 -

FOR CSO ONLY:

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age :

Driver's Own Vehicle Number:

Insurance Company:

XB 7335T - X

XB 5471 X - NA/IN/13004049/Cel ; DOA: 27/02/13

10/03/14

Rec'd email from Ruth - P/L retrieve DL from insured's driver.

11/03/14 @ 2:34 PM

WENT TO CID. GOT LANGUAGE KNO. HE ASK ME TO CALL COMPANY. WENT TO OI PIC MR. SETHUKUMAR. HE COMMENTED ACCIDENT DETAILS. HE SAID HIS TRUCK WAS HIT FROM BEHIND. HE ALSO SAID THAT CID TOOK PHOTO. HE GOT CID D/L. SEND EMAIL TO HIM TO GET THESE DOCUMENTS.

EMAIL LIABILITY UNCOVER.

RECEIVED EMAIL FROM OI WITH COPY OF

CID OG D/L THEY NOW FORWARDED COPY OF INSA D/L ONLY

ANALYSIS. IF COW FOOTAGE / V DRIVE / VIC / XB 7335T

TO WRITE TO AXA.

SEND EMAIL TO AXA FOR FURTHER INSTRUCTIONS.

EMAIL LIABILITY UNCOVER, TO GET EVIDENCE.

20-8-15 CONSIDERATION: IF RIGHT LANE IS SAME DIRECTION AS Y/I WE RELY ON TP CHARGING LAST

IF RIGHT LANE IS MEANT FOR ENCLAVING WAY, TP COULD RELY ON B

PLEASE VARY WITH % TO DETERMINE AT LIABILITY.

FINAL: 27-10-16 AFTER VIEWING T/P'S FOOTAGE, TP TURNING RIGHT & TRIED TO OVERTAKING HIM ON RIGHT. WE ARE LIABLE

Repair Cost: 9/2'S SS STATEMENT IS MISLEADING.

50

% (Agreed / Assessed)

BOLA S/N No.:

NIL

Loss of Rental: 9/4/17 TO SS EXPENSE SETTLEMENT - days)

If NO or B 28, Ass. Lia:

Loss of Use:

SS

-

(\$

x

days)

Format Type:

RECEIPT TP CLAIM

Disbursement:

SS

-

\$350.00

Total:

SS

-

Global Sum: SS

Ref:

CCG/AXA/1003606/KH03

Date/Time

Actions / Instructions

23/09/17

- GIVE MESSAGES TO AXA VIA EMAIL.

14/09/17

- RESEND REMINDER TO AXA.

17/10/17

- RESEND EMAIL TO AXA.

18/01/18

- RESEND EMAIL TO AXA.

29/01/18

- IF CHECK FOR UPDATE.

- RESEND EMAIL TO AXA.

05/02/18

- AXA INSTRUCTED TO RESTART CLAIM.

- OI AGENT - VICTOR.

- EMAIL TO IF RESTART CLAIM.

- TO CLOSE.

VIC
V.
05/02/18

ASS. REC. BY:

REF:

A/A/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: XB 73357 Yr Regn: 101 01

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MIT FV c.c. 11945Colour: white A/C: Insured / Std / NI / NASp. Reading: 348254 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FV 517 J A 00122

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim orTyre Size: F: 1100 R 20 X 10R: 103

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 22 88 mmL/Bal. 5 mm L/Bal. 77 88 mmD.O.A. 20/2/14 D.O.I. 22/2/14

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Est not ready</u>
	<u>17/2/14 11:50 816,100 email</u>
	<u>(app: 4 1.7.14)</u>
	<u>5,121.85 24%</u>

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS ____ \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CAI14004162/Keb3		
105 CECIL STREET #16-01/02 THE OCTAGON SINGAPORE 069534 (TP)		Date : 04-03-2014		
		Code : CAI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 8287U	Veh. Inspected	SHB 7503P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	04/03/2014	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/02/2014	Inspection Date	03/03/2014	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 42 SUNGEI KADUT ST 1 SINGAPORE 729346			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

XB7335T

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST: 201001158E RCB NO: 201001158E

M/S: AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 20/02/2014

TP Veh Reg No: XB5471X

Not Notion

61 Sep 87

Assessing After Repair

Estimate No: ES1490345/YISHUN

Date: 23 Feb 2014

Policy No: DB329311995

Veh Reg No: XB7335T

Make/Model: MITSUBISHI FV517

Chassis No: FV517JD2RDEB

Engine No: 6D24312773

Reg. Date: 10/10/2001

Estimate Repair Cost to Vehicle No :XB7335T

Description	U/Price	Quantity	List Price	Amount
List Price			SS	SS
1 FRONT BUMPER	1,455.41	1 PC	B1 1,455.41	—
2 FRONT BUMPER RH BRACKET	323.78	1 PC	B1 323.78	—
3 FRONT BUMPER RH PROTECTOR	95.00	1 PC	B1 95.00	—
4 FRONT BUMPER RH LAMP	423.32	1 PC	B2 423.32	—
5 FRT BUMPER RH LAMP GARNISH	146.27	1 PC	CM 146.27	—
6 FRONT BUMPER RH SIDE PAD	132.79	1 PC	CM 132.79	—
7 FRONT BUMPER RH CENTRE GRILLE	108.68	1 PC	B1 108.68	—
8 FRONT BUMPER RH LAMP HOUSING	65.60	1 PC	CM 65.60	—
9 FRONT RH STEP TRAY	343.12	1 PC	B2 343.12	—
10 FRONT RH STEP TRAY SIDE GARNISH	268.68	1 PC	B1 268.68	—
11 FRONT RH STEP TRAY HOUSING LOWER	192.54	1 PC	B1 192.54	—
12 FRONT RH STEP TRAY BRACKET	772.23	1 PC	B1 772.23	—
13 FRONT RH STEP TRAY BAR	527.12	1 PC	B1 527.12	—
14 RH TOP STEP TRAY	343.12	1 PCS	CM 343.12	—
15 RH TOP STEP TRAY SIDE GARNISH	316.85	1 PCS	CM 316.85	—
16 FRONT RH SIDE LAMP	167.63	1 PC	B2 167.63	—
17 FRONT RH SIDE RIM <i>front lamp rim</i>	241.22	1 PC	B1 241.22	—
18 FRONT GRILLE	551.31	1 PC	CM 551.31	—
19 FRONT RH CORNAL PANEL	845.18	1 PC	CM 845.18	—
20 RH HEAD LAMP	653.20	1 PC	mg 653.20	—
21 FRONT PANEL EMBLEM (MITSUBISHI)	298.15	1 PC	mg 298.15	—
22 FRONT PANEL LOGO	57.30	1 PC	mg 57.30	—
23 FRONT RH DOOR	5,883.87	1 PC	B1 5,883.87	—
24 FRONT WINDSCREEN GLASS	2,620.67	1 PC	CM 2,620.67	—
25 FRONT WINDSCREEN GLASS RUBBER	589.98	1 PC	mg 589.98	501.220.4794.93.61
26 FRONT RH SIDE MIRROR	538.94	1 PC	B2 538.94	—
27 FRONT RH SIDE MIRROR SQUARE	190.00	1 PC	B1 190.00	—
28 FRONT RH SIDE MIRROR ROUND	125.34	1 PC	B1 125.34	—
29 FRONT RH SIDE MIRROR BRACKET	195.67	1 PC	B1 195.67	—
30 FRONT RH WINDSCREEN PILLAR	2,040.10	1 PC	B1 2,040.10	—
31 GEAR BOX OIL COOLER	1,971.30	1 PCS	B1/pa 1,971.30	—

21,894.37 22,484.37
 Less 25% 5,621.09 16,863.28

16,420.79

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chinotor@singnet.com.sg
 GST: 201001158E RCB NO: 201001158E

M/S: AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 20/02/2014

TP Veh Reg No: XB5471X

Estimate No: ES1490345/YISHUN

Date: 23 Feb 2014

Policy No: DB329311995

Veh Reg No: XB7335T

Make/Model: MITSUBISHI FV517

Chassis No: FV517JD2RDEB

Engine No: 6D24312773

Reg. Date: 10/10/2001

Estimate Repair Cost to Vehicle No :XB7335T

Description	U/Price	Quantity	List Price	Amount
Labour			SS	SS
32 TOWING	150.00	1 LA	150.00	1200
33 REMOVE AND REFIX FRONT WINDSCREEN GLASS	120.00	1 LA	120.00	✓
34 REMOVE AND REFIX DASH BOARD, METER ASSY & CHECK WIRING	250.00	1 LA	250.00	2700
35 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS & SIDE LAMPS, SIDE MIRROR ASSY, STEP ASSY & BRACKETS, CORNAL PANEL, FRT RH DOOR & ATTACHMENT, TO CUTTING, WELDING FRT RH W/SCREEN PILLAR, KNOCK & REPAIR FRT RH FLOOR BOARD & DOOR, RR SIDE PANEL & REALIGN THE SAME	2,000.00	1 LA	2,000.00	15000
36 REMOVE & REFIX GEAR BOX OIL COOLER, BRAKE, AIR-TANK & CHECK GEAR BOX & BRAKE SYSTEM	280.00	1 LA	280.00	1800
37 PUTTY & RESPRAY ON FRT RH W/SCREEN PILLAR, FRT RH DOOR, DOOR REAR SIDE PANEL, FRT PANEL, CORNAL PANEL, FLOOR BOARD, FRT BUMPER & AFFECTED AREAS	1,200.00	1 LA	1,200.00	10000
38 REMOVE & REFIX FRT RH DOOR GLASS & CHECK CENTRE LOCKING & POWER MIRROR	60.00	1 LA	60.00	✓
39 RUSTPROOFING	100.00	1 LA	100.00	900 3280
			4,160.00	4,160.00

Total SS 21,023.28

Add GST @ 7% 1,471.63

Total Amount Payable SS 22,494.91

Not Notified
 LKK Auto Consultants Pte Ltd
 - Repairing before Spray Painting
 - Damaged parts to display when P-impaction
 - Parts prices subject to confirmation
 - Third Party Survey without prior notice
 - No illegal modification is allowed

1 day 8?

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

#20,005.76

Total 21372.85

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374 382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Supp 1

M/S : TENET SOMPO INSURANCE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 62212211 FAX: 62213147
ATTN: Motor Claim Department
WS Ref: TP/AXA/YS
Claim Type: Third Party
Accident Date: 20/02/2014

Estimate No: ES1490345/YISHUN
Date: 04 Mar 2014
Policy No: DB329311995
Veh Reg No: XB7335T
Make/Model: MITSUBISHI FV517
Chassis No: FV517JD2RDEB
Engine No: 6D24312773
Reg. Date: 10/10/2001

Estimate Repair Cost to Vehicle No :XB7335T

Description	U/Price	Quantity	List Price S\$	Amount S\$
Supplementary 1				
List Price				
1 FRONT RH CORNAL PANEL SEAL	64.10	1 PC	64.10	
		Less 25%	16.03	48.08
Special Net				
2 GEARBOX OIL	20.00	8 LIT	160.00	160.00
			160.00	160.00
		Total		S\$ 208.08
		GST Amount		S\$ 14.57
		Total Amount Payable		S\$ 222.64

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Let's Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

\$20,213.84 ✓

45 \$16,150 / (2%)
\$16,100/-

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 20/02/2014

TP Veh Reg No: XB5471X

Estimate No: ES1490345/YISHUN

Date: 23 Feb 2014

Policy No: DB329311995

Veh Reg No: XB7335T

Make/Model: MITSUBISHI FV517

Chasis No: FV517JD2RDEB

Engine No: 6D24312773

Reg. Date: 10/10/2001

Estimate Repair Cost to Vehicle No :XB7335T

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	1,455.41	1 PC	B1 1,455.41	—
2 FRONT BUMPER RH BRACKET	323.78	1 PC	B1 323.78	—
3 FRONT BUMPER RH PROTECTOR	95.00	1 PC	D1 95.00	—
4 FRONT BUMPER RH LAMP	423.32	1 PC	B2 423.32	—
5 FRT BUMPER RH LAMP GARNISH	146.27	1 PC	CM 146.27	—
6 FRONT BUMPER RH SIDE PAD	132.79	1 PC	CM 132.79	—
7 FRONT BUMPER RH CENTRE GRILLE	108.68	1 PC	D1 108.68	—
8 FRONT BUMPER RH LAMP HOUSING	65.60	1 PC	CM 65.60	—
9 FRONT RH STEP TRAY	343.12	1 PC	B2 343.12	—
10 FRONT RH STEP TRAY SIDE GARNISH	268.68	1 PC	B2 268.68	—
11 FRONT RH STEP TRAY HOUSING LOWER	192.54	1 PC	B2 192.54	—
12 FRONT RH STEP TRAY BRACKET	772.23	1 PC	B2 772.23	—
13 FRONT RH STEP TRAY BAR	527.12	1 PC	B2 527.12	—
14 RH TOP STEP TRAY	343.12	1 PCS	CM 343.12	—
15 RH TOP STEP TRAY SIDE GARNISH	316.85	1 PCS	CM 316.85	—
16 FRONT RH SIDE LAMP	167.63	1 PC	B2 167.63	—
17 FRONT RH SIDE RIM <i>Exide Lamp Rims</i>	241.22	1 PC	M1 241.22	—
18 FRONT GRILLE	551.31	1 PC		?
19 FRONT RH CORNAL PANEL	845.18	1 PC	B1 845.18	—
20 RH HEAD LAMP	653.20	1 PC		?
21 FRONT PANEL EMBLEM (MITSUBISHI)	298.15	1 PC	M1 298.15	—
22 FRONT PANEL LOGO	57.30	1 PC	M1 57.30	—
23 FRONT RH DOOR	5,883.87	1 PC	B1 5,883.87	—
24 FRONT WINDSCREEN GLASS	2,620.67	1 PC	CM 2,620.67	—
25 FRONT WINDSCREEN GLASS RUBBER	589.98	1 PC	M1 589.98	501.22
26 FRONT RH SIDE MIRROR	538.94	1 PC	B2 538.94	—
27 FRONT RH SIDE MIRROR SQUARE	190.00	1 PC	M1 190.00	—
28 FRONT RH SIDE MIRROR ROUND	125.34	1 PC	M1 125.34	—
29 FRONT RH SIDE MIRROR BRACKET	195.67	1 PC	B1 195.67	—
30 FRONT RH WINDSCREEN PILLAR	2,040.10	1 PC	B1 2,040.10	—
31 GEAR BOX OIL COOLER	1,971.30	1 PCS	B1/PC 1,971.30	—
			22,484.37	
			Less 25%	5,621.09
				16,863.28

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 20/02/2014

TP Veh Reg No: XB5471X

Estimate No: ES1490345/YISHUN

Date: 23 Feb 2014

Policy No: DB329311995

Veh Reg No: XB7335T

Make/Model: MITSUBISHI FV517

Chasis No: FV517JD2RDEB

Engine No: 6D24312773

Reg. Date: 10/10/2001

Estimate Repair Cost to Vehicle No :XB7335T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
32 TOWING	150.00	1 LA	150.00	1200
33 REMOVE AND REFIX FRONT WINDSCREEN GLASS	120.00	1 LA	120.00	✓
34 REMOVE AND REFIX DASH BOARD, METER ASSY & CHECK WIRING	250.00	1 LA	250.00	2200
35 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS & SIDE LAMPS, SIDE MIRROR ASSY, STEP ASSY & BRACKETS, CORNAL PANEL, FRT RH DOOR & ATTACHMENT, TO CUTTING, WELDING FRT RH W/SCREEN PILLAR, KNOCK & REPAIR FRT RH FLOOR BOARD & DOOR, RR SIDE PANEL & REALIGN THE SAME	2,000.00	1 LA	2,000.00	15000
36 REMOVE & REFIX GEAR BOX OIL COOLER, BRAKE, AIR-TANK & CHECK GEAR BOX & BRAKE SYSTEM	280.00	1 LA	280.00	1800
37 PUTTY & RESPRAY ON FRT RH W/SCREEN PILLAR, FRT RH DOOR, DOOR REAR SIDE PANEL, FRT PANEL, CORNAL PANEL, FLOOR BOARD, FRT BUMPER & AFFECTED AREAS	1,200.00	1 LA	1,200.00	10000
38 REMOVE & REFIX FRT RH DOOR GLASS & CHECK CENTRE LOCKING & POWER MIRROR	60.00	1 LA	60.00	✓
39 RUSTPROOFING	100.00	1 LA	100.00	900
			4,160.00	4,160.00

Total S\$ 21,023.28

Add GST @ 7% 1,471.63

Total Amount Payable S\$ 22,494.91

Not Authorized
LKK Auto Consultants Pte Ltd
• Resurvey before repair, Spray Painting.
• Damaged parts to Display when Re-inspection.
• Parts prices subject to confirmation.
• Third Party Survey without prejudice.
• No illegal modification is allowed.

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Text size + -

Enquire Vehicle & Owner Information (Vehicle No. XB5471X As At 20 Feb 2014 / 15:20:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM- XB7335

Current Owner Details

Owner ID Type: Company

Owner ID: 201003033D

Owner Name: KUBER GLOBAL PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 89

Registered Street Name: SHORT STREET

Registered Unit No.: # B1 - 11

Registered Building Name: GOLDEN WALL CENTRE

Registered Postal Code: 188216

Current Vehicle Details

Vehicle No.: XB5471X

Make Description/Model: MITSUBISHI / FUSO FV415J

Insurance Company Name: AXA INSURANCE SINGAPORE PTE LTD



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2014 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 198104709G

Vehicle Details

Vehicle No.: XB7335T
Vehicle to be Exported: Yes
Intended De-registration Date: 21 Feb 2014
Vehicle Make: MITSUBISHI
Vehicle Model: FV517JD2RDEB
Primary Colour: Blue
Manufacturing Year: 2001
Engine No.: 6D24312773
Chassis No.: FV517JA00122
Maximum Power Output: -
Open Market Value: \$97,091.00
Original Registration Date: 10 Oct 2001
First Registration Date: 10 Oct 2001
Transfer Count: 0
Actual ARF Paid: \$4,855.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Sep 2021
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$32,248.00
COE Rebate Amount: \$24,535.00
Total Rebate Amount: \$24,535.00

The information contained herein is correct as at 21 Feb 2014

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2014 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

Jojo Ngai

From: Ruth Chua [ruth.chua@axa.com.sg]
Sent: Monday, 10 March, 2014 1:22 PM
To: 'admin-b@lkkauto.com'; 'assignments@lkkauto.com'; 'sur@lkkauto.com'
Subject: RE: WP (OSP) / Cheng Hoe Motor / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC

Hi LKK,

Please retrieve DL from insured driver. Thanks.

Thanks & Regards,
Ruth

Ruth Chua (Ms)
Executive – Motor Claims
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
ruth.chua@axa.com.sg
DID: (65) 6880 4087 Fax: (65) 6880 4838
Website: www.axa.com.sg



redefining / insurance

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From 14 March 2011, AXA Insurance has moved to 8 Shenton Way, #27-01 AXA Tower Singapore 068811. Our Customer Service Centre will be located at #B1-01. All contact numbers remain unchanged.



Please consider the environment before printing this email

From: Tan Tiong Beng
Sent: Thursday, March 06, 2014 5:16 PM
To: admin-b@lkkauto.com; assignments@lkkauto.com; sur@lkkauto.com
Cc: Ruth Chua
Subject: WP (OSP) / Cheng Hoe Motor / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC

RISK 1 – P1450576

CLAIM RECEIVED : 24.02.14

XB5471X (INSD) C/W XB7335T

VTP - \$18,000

ASSESSOR – LKK 06.03.14

NCD – Y

RC 06.03.14

From: Jojo Ngai [mailto:admin-b@lkkauto.com]
Sent: Thursday, 06 March, 2014 4:10 PM
To: Winnie Ho Ping Ping; Kitty Teo Poh Guek; Tan Tiong Beng
Cc: KKLau; Sharon Yee
Subject: RE: Direct Settlement - Acc Invl XB 5471X(OI : AXA - TBA) & XB 7335T(TP : LKK - CC3/AXA14003606/Ksb3) on 20.02.2014

Dear Sir/Madam,

We refer to the above matter.

Kindly advise whether we can proceed for direct settlement for this case. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thanks & Regards
Jojo Ngai
LKK Auto Consultants Pte Ltd
51 Ubi Ave 1,
#01-25 Paya Ubi Industrial Park,
Singapore 408933
DID : 6742 8617
Fax : 6741 4108



Save the trees - Do you really need to print this e-mail?

From: Jojo Ngai [mailto:admin-b@lkkauto.com]
Sent: Monday, 24 February, 2014 6:34 PM
To: 'Winnie Ho Ping Ping'; 'Kitty Teo Poh Guek'; 'Tan Tiong Beng'
Cc: KKLau; Sharon Yee
Subject: Direct Settlement - Acc Invl XB 5471X(OI : AXA - TBA) & XB 7335T(TP : LKK - CC3/AXA14003606/Ksb3) on 20.02.2014

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle XB 7335T AT M/s Cheng Hoe Motor Pte Ltd.

Enclosed herewith a copy of TP's GIA report & photos for your perusal.

Please be informed that our estimated cost of repair is not ready yet.

Kindly take note that the case handler in-charge is Sharon and she can be contacted at DID: 6749 4274.

Thanks & Regards
Jojo Ngai

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1,
#01-25 Paya Ubi Industrial Park,
Singapore 408933
DID : 6742 8617
Fax : 6741 4108



Save the trees - Do you really need to print this e-mail?

Vic

From: Vic
Sent: Tuesday, 11 March, 2014 2:59 PM
To: contactkg365@gmail.com
Cc: Sharon Yee; Admin-B (LKK Auto); Vic
Subject: ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014

Our Ref: CC6/AXA14003606/Ksb3
Policy Number: P1450576

Dear Sir,

ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014

We refer to the above accident where we are acting for AXA Insurance Singapore Pte Ltd (AXA) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We also refer to our telephone conversation earlier.

As discussed, we would like to request for a copy of the driver, Mr Sundara's Driving Licence (**Singapore and International Licence**) and the photos taken at the time of accident for our further review.

You may call us if you have further queries.

Thank you.

Kind Regards,
Vic Alpeh Sanghilan
LKK Auto Consultants Pte Ltd
51 Ubi Avenue 1 #01-25
Paya Ubi Industrial Park
Singapore 408933
DID : 65- 6841 2157
Fax : 65- 6741 4108
Email: vicalpeh@lkkauto.com

Vic

From: Vic
Sent: Tuesday, 11 March, 2014 3:07 PM
To: Cheng Hoe Motor Pte Ltd (Yishun)
Cc: Sharon Yee; Admin-B (LKK Auto); Vic
Subject: Your ref: XB 7335T_ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014
Attachments: XB 5471X Statement.pdf

Your ref: XB 7335T

Our ref: CC6/AXA14003606/Ksb3

"WITHOUT PREJUDICE"

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014

We refer to the above matter.

Please be informed that liability is **not** yet clear. There is no conclusive evidence yet to substantiate either party's version. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, kindly forward to us with any evidence (if any) your client have to support your claim.

Kindly take note that the case handler in-charge is Sharon and she can be contacted at her DID 6749 4274.

Kind Regards,
Vic Alpeh Sanghilan
LKK Auto Consultants Pte Ltd
51 Ubi Avenue 1 #01-25
Paya Ubi Industrial Park
Singapore 408933
DID : 65- 6841 2157
Fax : 65- 6741 4108
Email: vicalpeh@lkkauto.com

Vic

From: Kuber Global Pte Ltd [contactkg365@gmail.com]
Sent: Wednesday, 12 March, 2014 8:19 AM
To: Vic
Cc: Sharon Yee; Admin-B (LKK Auto); Kuber Global Pte Ltd
Subject: Re: ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014
Attachments: XB5471X_Accident_Incident.docx

Dear Mr. Vic,

Herewith I have attached the lorry XB5471X accident incident report, photos taken during that time and our driver's license copy.

Right now he don't have this India license copy, we will try to send it tomorrow asap.

If you required any clarification about the incident, please contact us or our lorry driver Senthil Kumar.

Our contact:

Jeeva
Tel: 63000897
Mobile: 91801356

Lorry Driver Contact :

Senthil Kumar
Mobile: 8668 2352 / 8313 3173

Thanks

regards,
Jeeva
Director
Kuber Global Pte Ltd
Tel: 63000897 | Mobile: 91801356

On 11/3/2014 2:59 PM, Vic wrote:

Our Ref: CC6/AXA14003606/Ksb3
Policy Number: P1450576

Dear Sir,

ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014

We refer to the above accident where we are acting for AXA Insurance Singapore Pte Ltd (AXA) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We also refer to our telephone conversation earlier.

As discussed, we would like to request for a copy of the driver, Mr Sundara's Driving Licence (**Singapore and International Licence**) and the photos taken at the time of accident for our further review.

You may call us if you have further queries.

Thank you.

Kind Regards,
Vic Alpeh Sanghila
LKK Auto Consultants Pte Ltd
51 Ubi Avenue 1 #01-25
Paya Ubi Industrial Park
Singapore 408933
DID : 65- 6841 2157
Fax : 65- 6741 4108
Email: vicalpeh@lkkauto.com

- On the day of accident, many Lorries are queuing up at left side road (red color arrows) including the XB7335T (the opponent lorry) waiting for soil disposal and tried to enter LTA site gate at RIGHT side at the time of incident
- Our lorry XB5471X (Kuber Global) going all the way in the road at right side
- The opponent lorry XB7335T, after waiting, suddenly tried to turn right to enter the site gate entrance at the time. At the time our lorry XB5471X going on the way (right side road) to the next soil disposal site.
- The lorry XB7335T DID NOT signal and suddenly turned right side without watching the behind the our lorry from the right side road.
- When our lorry XB5471X going towards to next site, the opponent lorry HIT our lorry's left side BACK Tire barrier (refer Figure-2)
- Refer the Figure-1, the opponent lorry hit with our lorry at right side back tire barrier.

Figure-1



Figure-2 The opponent lorry hit into our lorry at back tire barrier when suddenly turned right from the left side after waiting (as indicated below)



Figure-3 : The opponent lorry XB7335T trying to turn right and enter into the site at the time of accident



Figure-4 : The opponent lorry damaged after hit into our lorry behind while turning right into LTA site after waiting in road side



Our Lorry Driver's IC copy (this is recent renewal license copy)

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **G7496304N**

Name: **SUNDARA BHARATHI SENTHILKUMAR**

Birth Date: **19 May 1975**

Issue Date: **20 Jan 2014**

Valid Till: **22 Jan 2018**

9902267175A



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

	EFFECTIVE DATE
Class 3 Motor Cars < 2000kg with <= 7 passengers, exclusive of taxicabs, and other motor vehicles <= 2500kg	23 Jan 2008
Class 4 Motor vehicles which are constructed to carry load or passengers and the unladen weight > 2500kg	24 Nov 2012

Motor vehicles which are not constructed to carry load and the unladen weight < 2500kg

NP 120A

License No: G7496304N

Vic

From: Vic
Sent: Wednesday, 10 September, 2014 2:55 PM
To: Kuber Global Pte Ltd
Cc: Admin-B (LKK Auto); Vic
Subject: RE: ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014

Dear Sir,

We refer to your below email.

Kindly advise further update if any.

Thank you.

Kind Regards,
Vic Alpeh
LKK Auto Consultants Pte Ltd
51 Ubi Avenue 1 #01-25
Paya Ubi Industrial Park
Singapore 408933
DID : 65- 6841 2096
Fax : 65- 6741 4108
Email: vicalpeh@lkkauto.com

Save the Earth. Print only when necessary.

From: Kuber Global Pte Ltd [<mailto:contactkg365@gmail.com>]
Sent: Monday, 28 April, 2014 4:56 PM
To: Vic
Cc: Sharon Yee; Admin-B (LKK Auto); Jojo Ngai
Subject: Re: ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014

Dear Mr. Vic Alpeh Senghilan,

As spoken over the the phone regarding the lorry accident XB5471X on 20/02/2014.
Currently we don't have any video evidence except the photos what we produced initially.

The fault is 100% to the opponent party. The opponent driver suddenly turned right from the queue (from left side), while our lorry on the way he hit with our lorry behind left side.

The accident happened in front of the construction site, there is cctv camera available. But not sure they have record for the past 2 months and as well as don't know whether can get it or not.

We will check any eyewitness during that accident, if come to know will let you know the eye witness person's detail.

thanks

regards,
Jeeva
Mobile : 91801356

On Wed, Mar 12, 2014 at 9:58 AM, Vic <vicalpeh@lkkauto.com> wrote:

Our Ref: CC6/AXA14003606/Ksb3

Dear Sir,

We refer to your below email and we thank you for the attached copy of the driver's Driving Licence.

We will forward this copy to our principal for their record.

You may call us if you have further queries.

Thank you.

Dear Jojo,

Kindly assist to forward to our principal for their necessary action.

Thank you.

Kind Regards,

Vic Alpeh Sanghilan

LKK Auto Consultants Pte Ltd

51 Ubi Avenue 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

DID : 65- 6841 2157

Fax : 65- 6741 4108

Email: vicalpeh@lkkauto.com

From: Kuber Global Pte Ltd [<mailto:contactkg365@gmail.com>]

Sent: Wednesday, 12 March, 2014 8:19 AM

To: Vic

Cc: Sharon Yee; Admin-B (LKK Auto); Kuber Global Pte Ltd

Subject: Re: ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014

Dear Mr. Vic,

Herewith I have attached the lorry XB5471X accident incident report, photos taken during that time and our driver's license copy.

Right now he don't have this India license copy, we will try to send it tomorrow asap.

If you required any clarification about the incident, please contact us or our lorry driver Senthil Kumar.

Our contact:

Jeeva

Tel: 63000897

Mobile: 91801356

Lorry Driver Contact :

Senthil Kumar

Mobile: 8668 2352 / 8313 3173

Thanks

regards,

Jeeva

Director

Kuber Global Pte Ltd

Tel: 63000897 | Mobile: 91801356

On 11/3/2014 2:59 PM, Vic wrote:

Our Ref: CC6/AXA14003606/Ksb3

Policy Number: P1450576

Dear Sir,

ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014

We refer to the above accident where we are acting for AXA Insurance Singapore Pte Ltd (AXA) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We also refer to our telephone conversation, earlier.

As discussed, we would like to request for a copy of the driver, Mr Sundara's Driving Licence (**Singapore and International Licence**) and the photos taken at the time of accident for our further review.

You may call us if you have further queries.

Thank you.

Kind Regards,

Vic Alpeh Sanghilan

LKK Auto Consultants Pte Ltd

51 Ubi Avenue 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

DID : 65- 6841 2157

Fax : 65- 6741 4108

Email: vicalpeh@lkkauto.com

Vic (LKKAuto)

From: Ruth Chua <ruth.chua@axa.com.sg>
Sent: Thursday, 18 September, 2014 9:02 AM
To: Vic
Subject: FW: WP (OSP) / Cheng Hoe Motor / C0297655 / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC
Attachments: XB5471X_Accident_Incident.docx; RE: ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014

Dear Vic,

Please provide your advice.

Thanks & Regards,

Ruth

Ruth Chua (Ms)
Executive – Motor Claims
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
ruth.chua@axa.com.sg
DID: (65) 6880 4087
Website: www.axa.com.sg



redefining / insurance

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From 14 March 2011, AXA Insurance has moved to 8 Shenton Way, #27-01 AXA Tower Singapore 068811. Our Customer Service Centre will be located at #B1-01. All contact numbers remain unchanged.



Please consider the environment before printing this email

From: Vic [mailto:vicalpeh@lkkauto.com]
Sent: 17 September, 2014 5:23 PM
To: Ruth Chua
Cc: Admin-B (LKK Auto); Vic
Subject: RE: WP (OSP) / Cheng Hoe Motor / C0297655 / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC

Our Ref: CC6/AXA14003606/Kh2b3

Dear Ms Ruth,

We refer to the below email.

Please be informed that we had spoken to the insured company Person-in-charge where they insisted that they are not at fault and doesn't want to settle the TP claim.

There were no CCTV footage and independent witness available. However, the insured managed to provide the scene photos. Please refer to the attached email and photos for your reference.

No further evidence provided by TP.

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Thursday, 27 October, 2016 2:18 PM
To: Ruth Chua
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: WP (OSP) / Cheng Hoe Motor / C0297655 / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC
Attachments: XB5471X_Accident_Incident.docx; RE: ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014

Dear Ruth,

We refer to your below email.

Please be informed that we managed to have the TP CCTV Footage (copy sent via Accellion). Based on the footage, TP was driving on a single lane dual carriage and made a right turn to enter the building premises when OI vehicle overtakes and collided to TP vehicle.

As such, under bola 33, OI vehicle is more liable.

We will now proceed to do DS with TP claimant as per your below email.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Ruth Chua [<mailto:ruth.chua@axa.com.sg>]
Sent: Thursday, 18 September, 2014 9:02 AM
To: Vic <vicalpeh@lkkauto.com>
Subject: FW: WP (OSP) / Cheng Hoe Motor / C0297655 / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC

Dear Vic,

Please provide your advice.

Thanks & Regards,
Ruth

Ruth Chua (Ms)
Executive – Motor Claims
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, Singapore 068811

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Tuesday, 23 May, 2017 4:23 PM
To: Vale Oh
Cc: Admin A; Vic (LKKAUTO); Asher Sng (LKKAUTO); ruth.chua@axa.com.sg
Subject: <SEEK MANDATE>_RE: WP (OSP) / Cheng Hoe Motor / C0297655 / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC
Attachments: XB5471X_Accident_Incident.docx; RE: ACCIDENT INVOLVING VEHICLES XB 5471X AND XB 7335T ON 20/02/2014; Preliminary Advice - XB 7335T.pdf; LKK INSPECTION REPORT.pdf; LKK ADJUSTMENT REPORT.pdf; LKK INSPECTION PHOTOS.pdf; LKK REINSPECTION PHOTOS.pdf; TP LOD.pdf

Your Ref: C0297655
Our Ref: CC6/AXA14003606/Kha3

Dear Vale,

ACCIDENT INVOLVING VEHICLES XB 5471X (OI) AND XB 7335T (TP) ON 20/02/2014

We refer to the above matter.

It was reported that Insured vehicle had collided to TP vehicle while overtaking the TP vehicle that is making a right turn. A copy of the TP CCTV Footage was already forwarded via accellion.

We had spoken to the Insured PIC Mr Jeeva and he confirmed accident details and was informed of the TP claim and NCD issue on 11/03/2014. OI PIC then forwarded to us their detailed statement and scene photos by email as enclosed.

Summary to offer to repairer **CHENG HOE MOTOR PTE LTD** is as follows:

	TP CLAIMED	REVISED - TO OFFER
Cost of Repair (w/gst)	\$ 22,717.54	\$ 17,227.00
Loss of Use (\$150 x 10 days)	\$ 1,500.00	\$ 1,500.00
LTA Search Fee	\$ 8.00	\$ 8.00
TOTAL	\$ 24,225.54	\$ 18,735.00

Breakdown of days is as follows:

Recommended days	7 days
Weekends / Downtime	3 days
TOTAL	10 days

Relevant supporting claim documents are uploaded in merimen for your perusal.

For your approval and/or further instruction please.

Thank you.



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date: 10 MAR 2017

AXA Insurance (S) Pte Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. XB7335T & XB5471X ON 20/02/2014
MARINA GROVE.**

We are authorized by XB7335T for their above matter.

Record reveals that you are the insurer of XB5471X. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 17227.00
2. Loss of Use (10 x 150)	S\$ 1500.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
TOTAL	S\$ 18735.00

Please let us have your reply soonest possible.

Thank you.

Yours faithfully





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AXA14003606/Ksb3

Policy Number: P1450576

17 APRIL 2014

KUBER GLOBAL PTE LTD

89 SHORT STREET

#B1-11 GOLDEN MILE CENTRE

SINGAPORE 188216

Dear Sir/Madam,

ACCIDENT INVOLVING XB 5471X AND XB 7335T ON 20/02/2014

We refer to the above accident where we are acting for AXA Insurance Singapore Pte Ltd (AXA) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by **28/04/2014**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Accordingly your No Claim Discount (NCD – if applicable) may not be preserved. However, if you are making a claim against third party and successful with 80% in your favor, our principal will re-instate your NCD.

As your policy carries an excess of \$1,000.00 under third party claim and the third party vehicle has lodged a claim against your vehicle, you are advice to issue a cheque of **\$1,000.00** in favour of our principal **AXA Insurance Singapore Pte Ltd** to enable us to handle third party claim.

Please call us if you have further queries.

Yours faithfully,

Vic Alpeh Sanghilan

Case Handler

DID: 6841 2157

FAX: 6741 4108

Email: vicalpeh@lkkauto.com

c.c. *AXA Insurance Singapore Pte Ltd (AXA)*
(Motor Claims Dept)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 68804739
ATTN: Motor Claim Department
WS Ref: TP/AXA/YS
Claim Type: Third Party
Accident Date: 20-02-2014
TP Veh Reg No: XB5471X

Final Repair Bill

Claim No: ES1490345
NO: PS1700243
Date: 10 Mar 2017
Policy No: DB329311995
Veh Reg No: XB7335T
Make/Model: MITSUBISHI FV517

PAGE:1

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	S\$ 16,100.00	S\$ 16,100.00

Total	S\$ 16,100.00
Add GST @ 7%	1,127.00
Total Amount payable	<u>S\$ 17,227.00</u>

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD	BILL NO : B015/2014
YOUR REF:	
OUR REF : ACS.CH.LTA.2014 (FEB 2014)	DATE : 3/3/14
TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.	
<u>LTA SEARCHES:</u>	
1. GBB 6307 (SKB9534) as at 3.2.14	SKB9534 \$ 8.00
2. SJM 9652 (SCH 2177) as at 1.2.14	SCH 2177 \$ 8.00
3. SKE 9855 (GR 787) as at 25.1.14	GR 787 \$ 8.00
4. PH 2968 (SJD2934) as at 3.2.14	SJD 2934 \$ 8.00
5. SGV 2739R (SGV 6486) as at 5.2.14	SGV 6486 \$ 8.00
6. FZ5610Z as at 5.12.13	Tokio Jan \$ 8.00
7. SJS2675X (SJD 8779U) as at 4.3.14	SJD 8779 \$ 8.00
8. SGT6386 (GX8446K) as at 28.1.14	GX 8446 \$ 8.00
9. GBA9302 (SGN1256) as at 11.2.14	SGN 1256 \$ 8.00
10. SGL9322 (GX9845) as at 9.1.14	GX 9845 \$ 8.00
11. GY5581S (SKA1330) as at 8.2.14	SKA 1330 \$ 8.00
12. FT3989 (GX9845) as at 12.1.14	GX 9845 \$ 8.00
13. SGL5825H (SGB3921D) as at 12.2.14	SGB 3921 \$ 8.00
14. PA1262 (SGF1547T) as at 14.2.14	SGF 1547 \$ 8.00
15. SJP815 (SGR6546) as at 13.2.14	SGR 6546 \$ 8.00
16. SGN191A	- \$ 8.00
17. SJX9351H	- \$ 8.00
18. SGE9576L (SJF5492) as at 14.2.14	SJF 5492 \$ 8.00
19. XD1119 (GZ7924T) as at 13.5.14	GZ 7924 \$ 8.00
20. SJJ6575 (SDX8666C) as at 15.2.14	SDX 8666 \$ 8.00
21. SJQ2334R (SJL7885K) as at 15.2.14	SDL 7885 \$ 8.00
22. YW3812 (GX2609Y) as at 24.1.14	GX 2609 \$ 8.00
23. SGQ539R (SGR 8075) as at 13.2.14	SGR 8075 \$ 8.00
24. SW6150 (GX8265) as at 19.2.14	GX 8265 \$ 8.00
25. SJU2157 (SKE1826X) as at 19.2.14	SKE 1826 \$ 8.00
26. XB5471 (XB7335) as at 20.2.14	XB 7335 \$ 8.00
27. GZ4106H (SKF7078) as at 21.2.14	SKF 7078 \$ 8.00
28. SGB6126 (SKL1660U) as at 25.2.14	SKL 1660 \$ 8.00
29. SJG9534 (SGR2443B) as at 14.2.14	SGR 2443 \$ 8.00
30. SJD965 (GW4284) as at 12.2.14	GW 4284 \$ 8.00
31. SGW8937 (GU2111) as at 6.2.2014	GU 2111 \$ 8.00
	\$ 248.00
[SINGAPORE DOLLARS: TWO HUNDRED & FORTY-EIGHT ONLY.]	
SD. A C SYED & PARTNERS	
M/s A C SYED & PARTNERS ADVOCATES & SOLICITORS SINGAPORE	
We reserved the right to forward a subsequent bill for any disbursements omitted herein. E. & O.E.	


AUTHORIZATION TO ACT

I, Lian Xing Sand & Grante Pte Ltd (the third party claimant")
of Blk 212 Hougang St 21 #03-345 S 530212 (address),
owner of XB7335T (vehicle no.) hereby authorize
CHENG HOE MOTOR PTE LTD
("The workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my
Vehicle No. XB7335T that was damaged pursuant to the
accident which occurred on 20/2/2014 (date) along Marina
Grove (location)
involving Vehicle No/s XB5471X
("The accident").


I further authorize the workshop to settle my above mentioned
claim in a manner that they deem fit and the workshop is further
authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach
on my behalf is on a without prejudice and without admission of
liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 21 day of February (month) 20 14 (year)



Signed by "the third party claimant"



Signed by "the workshop"

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Monday, 5 February, 2018 9:12 AM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Cc: Hsiao Tong (LKKAUTO); Thin Thin (LKKAUTO); Admin A; Olivia Lau (LKKAUTO); Asher Sng (LKKAUTO); Vic (LKKAUTO)
Subject: RE: URGENT- REMINDER- LOD- XB7335T- doa 20/02/14 (AXA Insured - XB5471X) LKK REF CC6/AXA14003606/Kha3q2

Without Prejudice

Dear June,

We refer further to our below email.

Please be informed that our principal after reviewing the matter, instructed us to deny your client's claim.

As such, we are unable to further look into the claim.

We will now close the matter in our end.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAUTO)
Sent: Monday, 29 January, 2018 5:16 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Cc: Hsiao Tong (LKKAUTO); Thin Thin (LKKAUTO); Admin A; Olivia Lau (LKKAUTO); Vic (LKKAUTO); Asher Sng (LKKAUTO)
Subject: RE: URGENT- REMINDER- LOD- XB7335T- doa 20/02/14 (AXA Insured - XB5471X) LKK REF CC6/AXA14003606/Kha3q2

Without Prejudice

Dear June,

We refer to your below email.

Please be informed that till date, we are still pending for mandate approval from our principal.

We had already highlighted and made several follow ups but we have not receive their approval yet.

We will follow up again and will get back to you for an update.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [<mailto:chmotor@singnet.com.sg>]

Sent: Monday, 29 January, 2018 5:08 PM

To: Vic (LKKAuto)

Cc: Hsiao Tong (LKKAuto); Thin Thin (LKKAuto); Admin A; Olivia Lau (LKKAuto); Vic (LKKAuto)

Subject: URGENT- REMINDER- LOD- XB7335T- doa 20/02/14 (AXA Insured - XB5471X)

Hi ALL,

Pls update status urgently.

Thank you.

Rgds

June Phua

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

From: Vic (LKKAuto)

Sent: Friday, May 12, 2017 9:41 AM

To: Cheng Hoe Motor Pte Ltd (Yishun-June)

Cc: Hsiao Tong (LKKAuto) ; Thin Thin (LKKAuto) ; Admin A ; Olivia Lau (LKKAuto) ; Vic (LKKAuto)

Subject: RE: REMINDER- LOD- XB7335T- doa 20/02/14 (AXA Insured - XB5471X)

Without Prejudice

Dear June,

We refer to your below email.

We are currently in the midst of seeking mandate approval from our principal.

Vic (LKKAUTO)

From: OH Vale <vale.oh@axa.com.sg>
Sent: Monday, 5 February, 2018 8:42 AM
To: Vic (LKKAUTO); TAY Ernest
Cc: Admin A; Olivia Lau (LKKAUTO)
Subject: RE: <SEEK MANDATE>_RE: WP (OSP) / Cheng Hoe Motor / C0297655 / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC

Hi Vic

Pls proceed to reject TP and do not finalize with TP workshop.

Agent-Virtual

*Please note we have terminated our fax-line. Hence, please send in your correspondences to our two common mail boxes instead. For OD/TP survey, send it to motor_survey@axa.com.sg and other correspondences send it to motor.doc@axa.com.sg, thanks.

Best Regards

Vale Oh/A.Manager – Motor Claims
AXA Insurance Pte Ltd/ 8 Shenton Way, #24-01 AXA Tower, Singapore 068811/www.axa.com.sg
vale.oh@axa.com.sg
Customer Care No. 1800 8804741



GLOBAL
INSURANCE
BRAND
FOR THE 9th
CONSECUTIVE
YEAR

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Please consider the environment before printing this email

From: Vic (LKKAUTO) [<mailto:vicalpeh@lkkauto.com>]
Sent: Friday, July 07, 2017 2:42 PM
To: TAY Ernest <ernest.tay@axa.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>
Subject: RE: <SEEK MANDATE>_RE: WP (OSP) / Cheng Hoe Motor / C0297655 / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC

Dear Ernest,

We refer to our below email.

For your approval and/or further instructions please.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Vic (LKKAuto)

Sent: Monday, 3 July, 2017 10:12 AM

To: TAY Ernest <ernest.tay@axa.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>

Subject: RE: <SEEK MANDATE>_RE: WP (OSP) / Cheng Hoe Motor / C0297655 / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC

Dear Ernest,

We refer to our below email.

For your approval and/or further instructions please.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: OH Vale [<mailto:vale.oh@axa.com.sg>]

Sent: Tuesday, 6 June, 2017 3:09 PM

To: TAY Ernest <ernest.tay@axa.com.sg>

Cc: Vic (LKKAUTO) <vicalpeh@lkkauto.com>

Subject: FW: <SEEK MANDATE>_RE: WP (OSP) / Cheng Hoe Motor / C0297655 / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC

Hi Ernest

Pls assist, tks.

*Please note we have terminated our fax-line. Hence, please send in your correspondences to our two common mail boxes instead. For OD/TP survey, send it to motor.survey@axa.com.sg and other correspondences send it to motor.doc@axa.com.sg, thanks.

Best Regards

Vale Oh/A.Manager – Motor Claims

AXA Insurance Pte Ltd/ 8 Shenton Way, #24-01 AXA Tower, Singapore 068811/www.axa.com.sg

vale.oh@axa.com.sg

Customer Care No. 1800 8804741



We are all born to protect, but for me it's a calling.

Discover our stories on www.borntoprotect.sg

redefining / insurance



**GLOBAL INSURANCE
BRAND
FOR THE 8TH
CONSECUTIVE YEAR**

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Please consider the environment before printing this email

From: Vic (LKKAUTO) [<mailto:vicalpeh@lkkauto.com>]

Sent: Tuesday, May 23, 2017 4:23 PM

To: OH Vale <vale.oh@axa.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; CHUA Ruth <ruth.chua@axa.com.sg>

Subject: <SEEK MANDATE>_RE: WP (OSP) / Cheng Hoe Motor / C0297655 / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC

Your Ref: C0297655

Our Ref: CC6/AXA14003606/Kha3

Dear Vale,

ACCIDENT INVOLVING VEHICLES XB 5471X (OI) AND XB 7335T (TP) ON 20/02/2014

We refer to the above matter.

It was reported that Insured vehicle had collided to TP vehicle while overtaking the TP vehicle that is making a right turn. A copy of the TP CCTV Footage was already forwarded via accellion.

We had spoken to the Insured PIC Mr Jeeva and he confirmed accident details and was informed of the TP claim and NCD issue on 11/03/2014. OI PIC then forwarded to us their detailed statement and scene photos by email as enclosed.

Summary to offer to repairer **CHENG HOE MOTOR PTE LTD** is as follows:

	TP CLAIMED	REVISED - TO OFFER
Cost of Repair (w/gst)	\$ 22,717.54	\$ 17,227.00
Loss of Use (\$150 x 10 days)	\$ 1,500.00	\$ 1,500.00
LTA Search Fee	\$ 8.00	\$ 8.00
TOTAL	\$ 24,225.54	\$ 18,735.00

Breakdown of days is as follows:

Recommended days	7 days
Weekends / Downtime	3 days
TOTAL	10 days

Relevant supporting claim documents are uploaded in merimen for your perusal.

For your approval and/or further instruction please.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Ruth Chua [<mailto:ruth.chua@axa.com.sg>]

Sent: Tuesday, 1 November, 2016 11:23 AM

To: Vale Oh <Vale.Oh@axa.com.sg>

Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>

Subject: FW: WP (OSP) / Cheng Hoe Motor / C0297655 / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC

Hi Vale

Sorry for the late forwarding.

Thanks & Regards,

Ruth

Ruth Chua (Ms)

Executive - Motor Claims

AXA Insurance Singapore Pte Ltd

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

ruth.chua@axa.com.sg

DID: 1800 8804741 (Option 3)

Website: www.axa.com.sg



We are all born to protect, but for me it's a calling.

Discover our stories on www.borntoprotect.sg

redefining / insurance



From 14 March 2011, AXA Insurance has moved to 8 Shenton Way, #27-01 AXA Tower Singapore 068811. Our Customer Service Centre will be located at #B1-01. All contact numbers remain unchanged.

 Please consider the environment before printing this email

"This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately."

From: Vic (LKKAUTO) [<mailto:vicalpeh@lkkauto.com>]

Sent: 27 October, 2016 2:18 PM

To: Ruth Chua

Cc: Admin A; Vic (LKKAUTO)

Subject: RE: WP (OSP) / Cheng Hoe Motor / C0297655 / P1450576 / OD XB5471X / TP XB7335T / 20.02.14 / EST \$22,494.91 / TP X/S \$1000 / RC

Dear Ruth,

We refer to your below email.

Please be informed that we managed to have the TP CCTV Footage (copy sent via Accellion). Based on the footage, TP was driving on a single lane dual carriage and made a right turn to enter the building premises when OI vehicle overtakes and collided to TP vehicle.

As such, under bola 33, OI vehicle is more liable.

We will now proceed to do DS with TP claimant as per your below email.

Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC6/AXA14003606/Kha3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RUTH CHUA			Date : 07-02-2018	
			Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XB 5471X	Veh. Inspected	XB 7335T
	Policy No.	P1450576	Coverage (\$)	0.00
	Claim No.	C0297655	Excess (\$)	0.00
	Assign From		Assign Date	22/02/2014
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi FV	c.c	11945
	Engine No.	HIDDEN	Year of Reg.	2001
	Chassis No.	FV517JA00122	Colour	WHITE
	Odometer	348254	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	1100 R20X10	FIRENZA	5 mm
	L/H Front Tyre	1100 R20X10	FIRENZA	5 mm
	R/H Rear Tyre	1100 R20X10 (D)	SUMO	7/7/8/8 mm
	L/H Rear Tyre	1100 R20X10(D)	SUMO	7/7/8/8 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	20/02/2014	Inspection Date	22/02/2014
	Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XB 7335T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	BENT	1,455.41	1,455.41
1	FRONT BUMPER RH BRACKET (CONSISTENT)	BENT	323.78	323.78
1	FRONT BUMPER RH PROTECTOR (CONSISTENT)	DISTORTED	95.00	95.00
1	FRONT BUMPER RH LAMP (CONSISTENT)	BROKEN	423.32	423.32
1	FRT BUMPER RH LAMP GARNISH (CONSISTENT)	CRACKED	146.27	146.27
1	FRONT BUMPER RH SIDE PAD (CONSISTENT)	CRACKED	132.79	132.79
1	FRONT BUMPER RH CENTRE GRILLE (CONSISTENT)	DISTORTED	108.68	108.68
1	FRONT BUMPER RH LAMP HOUSING (CONSISTENT)	CRACKED	65.60	65.60
1	FRONT RH STEP TRAY (CONSISTENT)	BROKEN	343.12	343.12
1	FRONT RH STEP TRAY SIDE GARNISH (CONSISTENT)	BENT	268.68	268.68
1	FRONT RH STEP TRAY HOUSING LOWER (CONSISTENT)	BENT	192.54	192.54
1	FRONT RH STEP TRAY BRACKET (CONSISTENT)	BENT	772.23	772.23
1	FRONT RH STEP TRAY BAR (CONSISTENT)	BENT	527.12	527.12
1	RH TOP STEP TRAY (CONSISTENT)	CRACKED	343.12	343.12
1	RH TOP STEP TRAY SIDE GARNISH (CONSISTENT)	CRACKED	316.85	316.85
1	FRONT RH SIDE LAMP (CONSISTENT)	BROKEN	167.63	167.63
1	FRONT RH SIDE RIM (CONSISTENT)	MISSING	241.22	241.22
1	FRONT GRILLE (CONSISTENT)	CRACKED	551.31	551.31
1	FRONT RH CORNAL PANEL (CONSISTENT)	CRACKED	845.18	845.18
1	RH HEAD LAMP (CONSISTENT)	MTG CRACKED	653.20	653.20
1	FRONT PANEL EMBLEM (MITSUBISHI) (CONSISTENT)	NECESSARY	298.15	298.15
1	FRONT PANEL LOGO (CONSISTENT)	NECESSARY	57.30	57.30
1	FRONT RH DOOR (CONSISTENT)	BENT	5,883.87	5,883.87
1	FRONT WINDSCREEN GLASS (CONSISTENT)	CRACKED	2,620.67	2,620.67
1	FRONT RH SIDE MIRROR (CONSISTENT)	BROKEN	538.94	538.94
1	FRONT RH SIDE MIRROR SQUARE (CONSISTENT)	MISSING	190.00	190.00
1	FRONT RH SIDE MIRROR ROUND (CONSISTENT)	MISSING	125.34	125.34
1	FRONT RH SIDE MIRROR BRACKET (CONSISTENT)	BENT	195.67	195.67
1	FRONT RH WINDSCREEN PILLAR (CONSISTENT)	BENT	2,040.10	2,040.10
1	GEAR BOX OIL COOLER (CONSISTENT)	BENT / PUNCTURE	1,971.30	1,971.30

Report Ref No. CC6/AXA14003606/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RH CORNAL PANEL SEAL (ADDITIONAL) (CONSISTENT)	NECESSARY	64.10	64.10
	LESS 25% DISCOUNT		-5,489.62	-5,489.62
			16,468.87	16,468.87
1	FRONT WINDSCREEN GLASS RUBBER (50%) (SN) (CONSISTENT)	NECESSARY	589.98	294.99
	LESS 25% DISCOUNT		-147.50	-
			442.48	294.99
	SPECIAL NETT ITEMS			
8	LIT GEARBOX OIL (50%) (SN) (CONSISTENT)	NECESSARY	160.00	80.00
			160.00	80.00
	LABOUR			
	TOWING.		150.00	120.00
	REMOVE AND REFIX FRONT WINDSCREEN GLASS.		120.00	120.00
	REMOVE AND REFIX DASH BOARD, METER ASSY & CHECK WIRING.		250.00	220.00
	REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS & SIDE LAMPS, SIDE MIRROR ASSY, STEP ASSY & BRACKETS, CORNAL PANEL, FRT RH DOOR & ATTACHMENT. TO CUTTING, WELDING FRT RH W/SCREEN PILLAR. KNOCK & REPAIR FRT RH FLOOR BOARD & DOOR, RR SIDE PANEL & REALIGN THE SAME.		2,000.00	1,500.00
	REMOVE & REFIX GEAR BOX OIL COOLER, BRAKE, AIR-TANK & CHECK GEAR BOX & BRAKE SYSTEM.		280.00	180.00
	PUTTY & RESPRAY ON FRT RH W/SCREEN PILLAR, FRT RH DOOR, DOOR REAR SIDE PANEL, FRT PANEL, CORNAL PANEL, FLOOR BOARD, FRT BUMPER & AFFECTED AREAS.		1,200.00	1,000.00
	REMOVE & REFIX FRT RH DOOR GLASS & CHECK CENTRE LOCKING & POWER MIRROR.		60.00	60.00
	RUSTPROOFING.		100.00	90.00
			4,160.00	3,290.00
GRAND TOTAL			21,231.35	20,133.86
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				16,100.00

Report Ref No. CC6/AXA14003606/Kha3q2



Report Ref No. CC6/AXA14003606/Kha3q2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.