

ASSIGNMENT

Surveyor:

Kalvin

DOI:

19/06/14

Assg Date:

19/06/14

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKJ 6117A

Claim No.:

SNM/4D02337/CO2/LKKDS

Name of Insured:

Wong Nian Fong

Policy No.:

DMPCSN1418601400

Insured Tel No.:

HP: 9753 8470

Make / Model:

Toyota

Excess Sec II :SS

D.O.A: 07/06/14

Place of Accident:

Yishun Ave 5

Is driver the owner? (YES / NO)

(YES)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO Insured Liability:

% Final ? Yes / No



INSRS:

WSP: SMRT (V/L)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

FOR CSO ONLY:

Is driver the owner? (YES / NO)

If NO, Driver Name / Age:

Driver's Own Vehicle Number:

Insurance Company:

SMB 275J - X

SKJ 6117A - X

RECEIVED 23 JUL 2018

24/6/14 5:00pm Called OI. confirmed the accident but he mentioned that his door is already open before close the door, TP was hit OI. Both vehicles were stationary picking passenger. No evidence. He had a NCD protector. Informed TP claim and aware of NCD issue.

KN FIVE AFTER. OI OPEN DOOR.

26/6/14 Based on damage profile it is possible that when TP was overtaking on the stationary car. The door was opened at the same time. Try to settle at best we are more to be blamed.

29/10/14 File pass to typist for mandate.

14/11/14 Seek mandate.

CCR = \$ 20754.00

LCU = \$ 500.00 (\$ 250 x 2 days)

27-04-16 WRITE TO CHINA & INFORM THEM OF TP'S POSITION AND ASK CHINA WHETHER TO IMPROVE OR MAINTAIN OUR OFFER.

\$ 21254.00

\$ 10627.00

\$ 5.00

\$ 10,632.00

STAGE

DATE / PIC

Finalisation:

Email AIG for OI GIA:

Apt letter to OI:

Call OI:

After call ltr to OI:

Type Report:

Prepare Invoice:

Others:

Documentation Check List: Handler Typist

OI Apt Ltr:	☒	☐
Authorisation To Act:	☒	☐
Release Voucher:	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☒	☐
LTA / GIA:	☒	☐
Medical Bill:	☐	☐
Approval Email:	☒	☐
Payment Breakdown Form:	☐	☐
Others:	☐	☐

FINAL SETTLEMENT

Date:

4/7/18

Confirm with

Audrey

Repair Cost:

SS 20754.00

Final Liability

100% (Agreed / Assessed)

BOLA S/N No.:

NIL

Loss of Rental:

SS

(days)

the car 25/16

If NO or B 28, Ass. Lia:

Loss of Use:

SS 500.00

(\$ 250 x 2 days)

Format Type:

Disbursement:

SS

5.00

Total:

SS 21254

Global Sum: SS

21200.00

Kalin

ASSIGNMENT

From: _____ Date: 19/6/14

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMJ 275J

at Workshop m/s SMT (CL)

of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record) _____

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: P/P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
Person Contacted: _____

Veh No: SMJ 275J Yr Regn: Jun 12012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN NL320F CC 10518

Colour: LHT A/C: Insured / Std / NI / NA

Sp. Reading: 169117 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WM AA2222C7001337

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 275/75 R22-5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Cont: _____

Front Rear
R/Bal. 4 mm R/Bal. 4.4 mm

L/Bal. 4 mm L/Bal. 4.4 mm

D.O.A. 7/6/14 D.O.I. 19/6/14 1330hrs

Survey held at SMT (CL)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear left Door.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
19-08-15	TRY TO OFFER T/P STARTING FROM 50% SLOWLY GOING UP TO NOT MORE THAN 80% AS INSTRUCTED BY CHINA TAIPIING Bus 106/14/1703
	\$20754.00 (Red: \$654.00 / 3 %.) CA2 / SKJ 61174
26-07-16	SPOKE TO SHIONG YI THAT BASED ON OUR LAST CONVERSATION, WE SHOULD IMPROVE OUR OFFER FROM 50% GRADUALLY GOING UP NOT TO 80%, IF EXCEEDING 80%, WE WOULD SEEK CHINA'S MANDATE AS T/P ALSO SHOULD KEEP A SPAKE WHEN OVERTAKING OUR STATIONARY VEHICLE IN ORDER TO PREVENT ANY UNEXPECTED EVENT HAPPENED.
10/7/17	Mr Yew spoke to Shiong Yi request OT's damages photos.
13-03-18	CHINA ASKED THIN THIN TO SHOW HER EVIDENCE OF CONVERSATION BET. MYSELF & SHIONG YI, THEREFORE, I (3.00pm) SPOKE TO SUSAN REQUESTING HER TO REVIEW THIS MATTER & GIVE US THEIR INSTRUCTION TO PROCEED.

Date/Time, File Pass to?

Date/Time, File Return to?

- 1) _____ 2) _____
3) _____ 4) _____
5) _____ 6) _____

Prel Report

Final Report

TOTAL
LOSSKIV FOR
LOD

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Jojo Ngai

From: Claims Dept of CTI [claimsdept@sg.cntaiping.com]
Sent: Friday, 20 June, 2014 12:45 PM
To: Admin-B (LKK Auto)
Cc: KKLau; Kathy Lai
Subject: RE: Direct Settlement - Acc Invl SKJ 6117A(OI) & SMB 275J(TP) on 07/06/2014 (LKK Ref: CC3/CAI14011622/K1rb3)
Attachments: MSME14066296-SKJ6117A.pdf

Dear Jojo,

Our Ref: SNM14D02337/C02/LKKDS

Enclose herewith our insured SAS report for your reference.

Thanks & Regards,

Hwang Shiang Yi
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
105 Cecil Street #18-00/#19-00/#16-01/02
The Octagon Singapore 069534
Co. Reg. No 200208384E
DID : 6389 6541
Fax : 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com
Email : hwangsy@sg.cntaiping.com
Website : www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Jojo Ngai [mailto:admin-b@lkkauto.com]
Sent: Friday, 20 June, 2014 11:39 AM
To: Claims Dept of CTI
Cc: Toh Hock San Alfred; Chee So Chow; Yao Yue Sheng; KKLau; Kathy Lai
Subject: Direct Settlement - Acc Invl SKJ 6117A(OI) & SMB 275J(TP) on 07/06/2014 (LKK Ref: CC3/CAI14011622/K1rb3)

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SMB 275J AT M/s SMRT Automotive Service Pte Ltd.

Enclosed herewith a copy of TP's GIA report , estimated cost of repair and preliminary advice for your perusal.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Kathy and she can be contacted at DID: 6841 2928 & email : kathylai@lkkauto.com

Thanks & Regards

Jojo Ngai

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1,

#01-25 Paya Ubi Industrial Park,

Singapore 408933

DID : 6742 8617

Fax : 6741 4108



Save the trees - Do you really need to print this e-mail?

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592


Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB275J
Ref. No : BUS/06/14/7013
Reg. Date : 01/01/1900
Vehicle Type : BUS -12M
Make : MAN
Model : MAN
Name of Driver : Sim Ah Lek
Type of Accident : OTHERS
Date / Time of Accident : 07/06/2014 05:40:00 PM
Accident Reported Date / Time : 11/06/2014 12:00:00 AM
Surveyor is Required? : Yes
Survey by : China Tai Ping
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC, if any :
rear door windscreen shattered. TP - SKJ6117A
Prepared Date : 11/06/2014 03:21:55 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,446.00	964.00
Total Spray Painting Charges	: 372.00	200.00
Total Material Charges	: 18,630.00	18,630.00
Other Charges	: 960.00	960.00
TOTAL	: 21,408.00	20,754.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 3.00	2.00
Prepared / Adjusted By	: Tan Leong Kim	kalvin
Arc / Surveyor Sing Off Date	: 01/01/1900 12:00:00 AM	19/06/2014 01:31:15 PM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 18/06/2014 01:48:48 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0
 Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,446.00	964.00
Total Spray Painting Charges :	372.00	200.00
Total Material Charges :	18,630.00	18,630.00
Other Charges :	960.00	960.00
TOTAL :	21,408.00	20,754.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	3.00	2.00
Prepared / Adjusted By :	Tan Leong Kim	kalvin
Arc / Surveyor Sing Off Date :	01/01/1900 12:00:00 AM	19/06/2014 01:31:15 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 18/06/2014 01:48:48 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
 Quotation Date : Invoice Date :
 Invoice Amount : Prepared Date :

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommend	Surveyor Approved	Photos Attached
		6010457	EXIT DOOR ASSY	1	20,700.00	10.00	18,630.00	Replace	Replace	No
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)										
								18,630.00	18,630.00	
								18,630.00	18,630.00	

✓ CAP

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Part - 18,630

Labour - 2124

total - \$20,754

Confirmed

✓ 23/6/14

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,446.00	964.00
Total Labour	1,446.00	964.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	372.00	200.00
Total Spray Painting & Panel Beating	372.00	200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER	960.00	960.00
Total Other Costs	960.00	960.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommend	Surveyor Approved	Photos Attached
		6010457	EXIT DOOR ASSY	1	20,700.00	10.00	18,630.00	Replace	Replace	No
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)										
								18,630.00	18,630.00	
								18,630.00	18,630.00	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

LKH Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rosey Naing

From: Hwang Shiang Yi [shiangyi.hwang@sg.cntaiping.com]
Sent: Tuesday, 9 December, 2014 12:00 PM
To: Rosey Naing
Cc: 'Hsiao Tong'
Subject: RE: Your ref : SNM14D02337/C02/LKKDS Our ref : CC3/CAI14011622/K1kb3w2 ACCIDENT INVOLVING SKJ 6117A & SMB 275J ON 07/06/2014 ALONG YISHUN AVENUE 5

Dear Rosey,

Please proceed to offer as per your proposal.

Offer liability starting from 50%.

Thanks & Regards,

Hwang Shiang Yi
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co. Reg. No 200208384E
DID : 6389 6541
Fax : 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com
Email : shiangyi.hwang@sg.cntaiping.com
Website : www.sg.cntaiping.com

6/10/15 TO reply
propose 100%.

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Rosey Naing [mailto:roseynaing@lkkauto.com]
Sent: Tuesday, 9 December, 2014 10:23 AM
To: Hwang Shiang Yi
Cc: 'Hsiao Tong'; 'Rosey Naing'
Subject: FW: Your ref : SNM14D02337/C02/LKKDS Our ref : CC3/CAI14011622/K1kb3w2 ACCIDENT INVOLVING SKJ 6117A & SMB 275J ON 07/06/2014 ALONG YISHUN AVENUE 5

Dear Shiang Yi,

Attach the survey report for your perusal.

Kindly revert your approval /instruction.

Thank you.

"Wishes you a Merry Christmas & Happy New Year 2015"

Kind Regards,
Rosey
LKK Auto Consultants Pte Ltd
51 Ubi Avenue 1 #01-25
Paya Ubi Industrial Park
Singapore 408933
DID : 65- 6841 2132
Fax : 65- 6741 4108
Email: roseynaing@lkkauto.com

From: Hwang Shiang Yi [mailto:shiangyi.hwang@sg.cntaiping.com]
Sent: Tuesday, 9 December, 2014 9:43 AM
To: roseynaing@lkkauto.com
Subject: FW: Your ref : SNM14D02337/C02/LKKDS Our ref : CC3/CAI14011622/K1kb3w2 ACCIDENT INVOLVING SKJ 6117A & SMB 275J ON 07/06/2014 ALONG YISHUN AVENUE 5

Dear Rosey,

Please forward completed survey report.

Thanks & Regards,

Hwang Shiang Yi
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co. Reg. No 200208384E
DID : 6389 6541
Fax : 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com
Email : shiangyi.hwang@sg.cntaiping.com
Website : www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: roseynaing@lkkauto.com [mailto:roseynaing@lkkauto.com]
Sent: Friday, 14 November, 2014 9:18 AM
To: Claims Dept of CTI
Cc: Hwang Shiang Yi; "Hsiao Tong"; roseynaing@lkkauto.com
Subject: Your ref : SNM14D02337/C02/LKKDS Our ref : CC3/CAI14011622/K1kb3w2 ACCIDENT INVOLVING SKJ 6117A & SMB 275J ON 07/06/2014 ALONG YISHUN AVENUE 5

Your ref : SNM14D02337/C02/LKKDS
Our ref : CC3/CAI14011622/K1kb3w2

WITHOUT PREJUDICE

Dear Shiang Yi,

ACCIDENT INVOLVING SKJ 6117A & SMB 275J ON 07/06/2014 ALONG YISHUN AVENUE 5

We refer to the above accident.

OI reported that he was stationary and TP was picking / alighting passenger. Therefore OI opened his rear right door to allow his daughter to enter the car, before to close the door, TP moved out and hit onto OI's rear right door.

TP reported that OI was stationary at the bus stop. TP has turned out of the bus stop at the yellow box. Suddenly OI opened the

Our opinion that this is the conflicting version and there was no evidence nor witness in both parties.

Based on the damages profile it is possible that when TP was overtaking OI stationary car, the door was opened at the same time

We had informed OI about TP claim and NCD issue.

We seek your approval to offer to TP repairer, **SMRT AUTOMOTIVE SERVICES PTE LTD** up to S\$ 17008.20 (all in). The breakdown is as follows:

	Amount Claimed	Amount Revised
1. Cost of Repairs	\$ 21,408.00	\$ 20,754.00
2. Loss of Use (2days x \$250)	\$ 500.00	\$ 500.00
	<u>\$ 21908.00</u>	<u>\$ 21254.00</u>
@ 50% - 80%	<u>\$</u>	<u>\$ 10627.00-17003.20</u>
4.LTA /GIA Search Fee	\$ 5.00	\$ 5.00
	<u>\$ 21,913.00</u>	<u>\$ 10,632.00-17008.20</u>

Enclosed herewith all the relevant documents for your perusal.

For your approval please.

Kind Regards,

Rosey

LKK Auto Consultants Pte Ltd

51 Ubi Avenue 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

DID : 65- 6841 2132

Fax : 65- 6741 4108

Email: roseynaing@lkkauto.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Offer
02.3:

Your Ref: SMB 275J

"Without Prejudice"

Our Ref: CC3/CAI14011622/K1kb3w2

Dear Madeline,

ACCIDENT ON 07/06/2014 INVOLVING VEHICLES SKJ 6117A AND SMB 275J

We refer to the above matter.

Enclosed herewith a copy of our insured's sketch plan for your perusal.

We are of the opinion that this is a case of conflicting versions. There is no conclusive evidence to substantiate either's parties version.

We propose settlement as follows: -

1. Cost of Repair	\$ 20754.00
2. Loss of Use(\$250x2days)	\$ 500.00
	<u>\$ 21254.00</u>
@50%	\$ 10627.00
4. LTA/GIA search fee	\$ 5.00
TOTAL	<u>\$ 10632.00</u>

✓ New 10/12/14

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

"Wishes you a Merry Christmas & Happy New Year 2015"

Kind Regards,

Rosey

LKK Auto Consultants Pte Ltd

51 Ubi Avenue 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

DID : 65- 6841 2132

Fax : 65- 6741 4108

Email: roseynaing@lkkauto.com



Attachments:

LOD OF SMB 275J.pdf; Survey photos.pdf; Inspection Report.pdf

Your ref : SNM14D02337/C02/LKKDS

Our ref : CC3/CA114011622/K1kb3w2

WITHOUT PREJUDICE

Dear Shiang Yi,

ACCIDENT INVOLVING SKJ 6117A & SMB 275J ON 07/06/2014 ALONG YISHUN AVENUE 5

We refer to the above accident.

OI reported that ^{he} OI was stationary and TP was stationary picking / alighting passenger. Therefore OI opened OI vehicle rear right door to allow his daughter to enter the car, before to close the door, TP moved out and hit onto OI rear right door.

TP reported that OI was stationary at the bus stop. Suddenly TP opened the right hand side passenger door and hit TP's rear ^{his door.} ^{TP has turned out of the bus stop at the yellow box.}

Our opinion that this is the conflicting version and there was no evidence nor witness in both parties.

Based on damage profile it is possible that when TP was overtaking a stationary car, the door was opened at the same time.

We had informed OI about TP claim and NCD issue.

We have surveyed the vehicle, and relevant supporting documents enclosed for your perusal.

We seek your approval to offer to TP repairer, **SMRT AUTOMOTIVE SERVICES PTE LTD** is as follows:

- the breakdown is as follows: -

	Amount Claimed	Amount Revised	
1. Cost of Repairs ³²	\$ 21,408.00 ✓	\$ 20,754.00 ✓	
2. Loss of Rental (2 days x \$250) ^{Use}	\$ 500.00 ✓	\$ 500.00 ✓	
	\$ 21908.00	\$ 21254.00 ✓	
@ 50% - 84% ..	\$ 8	\$ 10627.00 ✓	- 17003.20
4. LTA / GIA Search Fee	\$ 5.00 ✓	\$ 5.00 ✓	
	\$ 21,913.00	\$ 10,632.00 ✓	17003.20

Enclosed herewith all the relevant documents for your perusal

Amount of claim S\$ 10,632.00 for approval**Surveyor recommended 2 working days.**

For your approval please.

Chen
13/11/14

Kind Regards,

Rosey

LKK Auto Consultants Pte Ltd

51 Ubi Avenue 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

DID : 65- 6841 2132

Fax : 65- 6741 4108

Email: roseynaing@lkkauto.com

Rosey Naing

From: Hwang Shiang Yi [shiangyi.hwang@sg.cntaiping.com]
Sent: Tuesday, 9 December, 2014 12:00 PM
To: Rosey Naing
Cc: 'Hsiao Tong'
Subject: RE: Your ref : SNM14D02337/C02/LKKDS Our ref : CC3/CAI14011622/K1kb3w2 ACCIDENT INVOLVING SKJ 6117A & SMB 275J ON 07/06/2014 ALONG YISHUN AVENUE 5

Dear Rosey,

Please proceed to offer as per your proposal.

Offer liability starting from 50%.

Thanks & Regards,

Hwang Shiang Yi
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co. Reg. No 200208384E
DID : 6389 6541
Fax : 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com
Email : shiangyi.hwang@sg.cntaiping.com
Website : www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Rosey Naing [mailto:roseynaing@lkkauto.com]
Sent: Tuesday, 9 December, 2014 10:23 AM
To: Hwang Shiang Yi
Cc: 'Hsiao Tong'; 'Rosey Naing'
Subject: FW: Your ref : SNM14D02337/C02/LKKDS Our ref : CC3/CAI14011622/K1kb3w2 ACCIDENT INVOLVING SKJ 6117A & SMB 275J ON 07/06/2014 ALONG YISHUN AVENUE 5

Dear Shiang Yi,

Attach the survey report for your perusal.

Kindly revert your approval /instruction.

Thank you.

"Wishes you a Merry Christmas & Happy New Year 2015"



4/5: Photographs of Damaged Parts Rear Door Trim Board R/H

SKJ6117A - Submitted by: Adrason Private Limited (HQ)

IF THE BOARD OF THE DOOR WAS DAMAGED BY
IMPACT, THE DOOR WAS LIKELY OPENED BEFORE
THE COLLISION. SO TO MAINTAIN OUR STAND
UNLESS T/P IS ABLE TO PRODUCE PROOF OF
CCTV WHICH WE BELIEVE THEY HAVE.



5/5: Photographs of Damaged Parts Centre Door Pillar R/H



3/5: Photographs of Damaged Parts Rear & Front Doors R/H

SKJ6117A - Submitted by: Adrason Private Limited (HQ)

SKJ6117A - Submitted by: Adrason Private Limited (HQ)



1/5: Front View Right

SKJ6117A - Submitted by: Adrason Private Limited (HQ)



2/5: Photographs of Damaged Parts Frontr & Rear Doors R/H

SKJ6117A - Submitted by: Adrason Private Limited (HQ)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI14011622/K1ua3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 24-07-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 6117A	Veh. Inspected	SMB 275J
Policy No.	DMPCSN1418601400	Coverage (\$)	0.00
Claim No.	SNM14D02337/C02/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	19/06/2014

2. Vehicle Particulars & Condition

Make & Model	MAN NL320F	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WMAA22ZZ2C7001337	Colour	WHITE
Odometer	169117	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/75 R22.5	CONTINENTAL	4 mm
L/H Front Tyre	275/75 R22.5	CONTINENTAL	4 mm
R/H Rear Tyre	275/75 R22.5 (D)	CONTINENTAL	4/4 mm
L/H Rear Tyre	275/75 R22.5 (D)	CONTINENTAL	4/4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S DOOR. DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/06/2014	Inspection Date	19/06/2014
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 275J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	EXIT DOOR ASSY	CRACKED	20,700.00	20,700.00
	LESS 10% DISCOUNT		-	-2,070.00
			20,700.00	18,630.00
	<u>LABOUR</u>			
	TO REMOVE AND INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS,		1,446.00	964.00
	TO PROVIDE LABOUR & MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		372.00	200.00
	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER.		960.00	960.00
			2,778.00	2,124.00
	GRAND TOTAL		23,478.00	20,754.00
RECOMMENDED COST OF REPAIRS				20,754.00

Report Ref No. CC3/CTI14011622/K1ua3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.