



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

19/9/14 - 10:30
LKK - Bennett

SURVEYOR COPY

M/S : JERINAL SINGH
BLK 131 SERANGOON AVE 3 #01-06
SINGAPORE 556112

Estimate No: MC0908701
Date: 16 Sep 2014
Policy No: 10077721
Veh Reg No: SGA416X
Make/Model: HONDA ACCORD 2.0 A

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 14/09/2014
TP Veh Reg No: SJJ8642Z

Estimate Repair Cost to Vehicle No :SGA416X

Description	Quantity	List Price SS	Amount SS
LABOUR			
1 TO DISMANTLE & INSTALL DAMAGED PARTS. TO KNOCK & REPAIR REAR FENDER RH, REAR DOOR RH.	1 PC	500.00	250
2 TO SPRAY REAR DOOR RH, REAR FENDER RH.	1 PC	500.00	400
		1,000.00	1,000.00
		Total	SS 1,000.00
		Add GST @ 7%	70.00
		Total Amount Payable	SS 1,070.00

TOTAL: SINGAPORE DOLLAR ONE THOUSAND SEVENTY ONLY
Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

Not Authorised

- LKK Auto Consultants Pte Ltd
- Resurvey before/after Spray Painting.
 - Damaged parts to Display when Re-inspection.
 - Parts prices subject to confirmation.
 - Third Party Survey without prejudice.
 - No illegal modification is allowed.

2 days