### Vic (LKKAuto)

From: Vic (LKKAuto)

**Sent:** Friday, 31 March, 2017 10:08 AM **To:** Richard Ang; Annabel Tan

**Cc:** Admin A; Vic (LKKAuto); Elaine Cheong

Subject: RE: Direct Settlement - Accident Involving GW 3884S (OI : EQI - TBA) & SHC 5094K

(TP: LKK REF - CC3/EQI15002374/Khe3) on 03.02.2015

Dear All,

We refer further to the below email.

Please find below the link of the TP CCTV footage for your reference. Based on the footage, TP vehicle was driving across the junction with amber light when Insured vehicle on the opposite lane was making a right turn.

https://www.dropbox.com/s/mz8508zos7zpvd8/SHC5094K%20030215.mp4?dl=0

As per our surveyor recommendation after inspection, the adjusted COR of TP vehicle at P/P is \$39,605.53 (before gst) with 21 recommended repair days.

We are currently preparing report for mandate approval.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

**LKK Auto Consultants Pte Ltd** 

Phone: 6841-2096 | email: <u>vicalpeh@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**From:** Richard Ang [mailto:richard.ang@eqinsurance.com.sg]

**Sent:** Friday, 13 February, 2015 11:31 AM

To: Admin-A (LKK Auto) <admin-a@lkkauto.com>

Cc: KKLau <kklau@lkkauto.com>; 'kathylai@lkkauto.com'; Vic <vicalpeh@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GW 3884S (OI: EQI - TBA) & SHC 5094K (TP: LKK REF -

CC3/EQI15002374/Khe3 ) on 03.02.2015

Importance: High

UREGNT WITHOUT PREJUDICE

Our ref : DM15HO00230/RA

Your ref : CC3/EQI15002374/Khe3

Dear Su Li,

Reference to our email to you dated 12th February 2015.

Please advised us the repairable limit for the above taxi for our assessment purpose.

Please let us hear from you soonest.

Thanks & Regards,

## Richard Ang

Executive, Claims
EQ Insurance Company Limited
22 Gemmill Lane
Singapore 069257

Tel : (65) 6496 9032 Fax : (65) 6223 4190

Email: richard.ang@eqinsurance.com.sg

From: Richard Ang

Sent: Thursday, 12 February, 2015 3:32 PM

To: 'Admin-A (LKK Auto)'

Cc: KKLau; 'kathylai@lkkauto.com'; Vic

Subject: RE: Direct Settlement - Accident Involving GW 3884S (OI: EQI-TBA) & SHC 5094K (TP: LKK REF-

CC3/EQI15002374/Khe3 ) on 03.02.2015

Importance: High

#### **WITHOUT PREJUDICE**

Our ref : DM15HO00230/RA

Your ref : CC3/EQI15002374/Khe3

Dear Su Li,

Reference to your email dated 12<sup>th</sup> February 2015.

As requested, we enclosed our insured's GIA report for your necessary action.

We are currently conducting an investigation on the above matter, therefore please conduct the survey on a without prejudice basis.

Thanks & Regards,

# Richard Ang

Executive, Claims
EQ Insurance Company Limited
22 Gemmill Lane
Singapore 069257

Tel : (65) 6496 9032 Fax : (65) 6223 4190

Email: richard.ang@eqinsurance.com.sg

From: Admin-A (LKK Auto) [mailto:admin-a@lkkauto.com]

Sent: Thursday, 12 February, 2015 2:28 PM

To: Richard Ang

Cc: KKLau; 'kathylai@lkkauto.com'; Vic

Subject: Direct Settlement - Accident Involving GW 3884S (OI: EQI - TBA) & SHC 5094K (TP: LKK REF -

CC3/EQI15002374/Khe3 ) on 03.02.2015

(Part - 2)

Dear Richard,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 5094K at Trans-Cab Auto Services Pte Ltd.

Enclosed herewith a copy of TP's GIA report, estimated cost of repair and preliminary advice for your perusal.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Best Regards,

Su Li | Admin

#### **LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: <u>admin-a@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

