





762

## ASSIGNMENT

Date: 10.03.2015

TOTAL





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC4/AIG15002569/Gpm3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 11-02-2015	
			Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJY 147K	Veh. Inspected	YK 3646M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	10/02/2015	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	29/01/2015	Inspection Date	11/02/2015	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

AlGAsia Insured's Veh No : SJY147K  
Date of Accident : 29 January 2014



陶林摩打私人有限公司  
**TAN LIM MOTOR PTE LTD**

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

Messrs Excellence Electrical Trading

Date : 30 January 2015

Estimate To Repair YK3646M - Nissan Cabstar  
Chassis No : JN1SF4F23Z0840312

S/No	Quantity	Description	Amount
01	1 pc	<u>LIST ITEMS</u> front bumper assy X Repair.	\$ 695.50
			\$ 695.50
		Less 25 %	\$ 173.88
			\$ 521.63
02	1 pc	<u>SPECIAL NETT ITEMS</u> front licence plate ✓ HT	\$ 40.00
			\$ 40.00
01		<u>LABOUR &amp; MISC. CHARGES</u> Labour	\$ 300.00
			\$ 300.00
		Total	\$ 861.63

200 IN

200  
100

part by part.  
After repair photos.  
2 Days.  
Guo Qiang 82880282  
Guo Qiang @ 11kkauto.com  
11/2/15.



Reply



Reply All



Help



Logout

**From:** Syamimi.Nazri@aig.com**Sent:** Tuesday, 10 February, 2015 5:03:13 PM**To:** 'admin-a@lkkauto.com', 'admin-c@lkkauto.com', ChewHT@lkkauto.com**Cc:** Mooventhiran.Chandrahekarani@aig.com, Kristelli.Lopez@chartisinsurance.com, Lily.Tan@aig.com, Anuar.Abdullah@aig.com**Subject:** - PD New Assignment - SJY147K (OI) VS YK3646M (TP) DOA 29/01/2015

Digital Signature is VALID

**Attachments:** SJY147.TIF

X66

Hi,

Total number of pages in fax attachment : 9

Claim number : TO BE ADVISED

Case owner : TO BE ADVISED

Please be informed that the claim is currently pending for registration in system. We will advise the details as soon as possible.

Thank you.

Best Regards,  
Syamimi Mohd Nazri  
AIG

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

51, Defu Lane 10

Singapore 539216

Tel : 6858 5151 (24HRS) Fax : 6858 0877

GST Regn. No : M2-8922054-2

FAX TRANSMITTAL MEMO

To : AIG Asia Pacific Insurance Date : 10/02/15 @ 1325h  
Dept : Motor Claims Dept Fax : 6833 7416  
From : William Pages : 9 (Including this page)

---

Your Ref : SJY147k

Our Ref : Yk 3646m - TP 201501033

Please arrange for survey as soon as possible.

Thank you & best regards



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SJY147K

Date of Accident : 29 January 2014

Messrs Excellence Electrical Trading

Date : 30 January 2015

Estimate To Repair YK3646M - Nissan Cabstar

Chassis No : JN1SF4F23Z0840312

S/No	Quantity	Description	Amount
01	1 pc	<u>LIST ITEMS</u> front bumper assy	\$ 695.50
			\$ 695.50
		Less 25 %	\$ 173.88
			\$ 521.63
02	1 pc	<u>SPECIAL NETT ITEMS</u> front licence plate	\$ 40.00
			\$ 40.00
01		<u>LABOUR &amp; MISC. CHARGES</u> Labour	\$ 300.00
			\$ 300.00
		Total	\$ 861.63





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG15002569/Gpm3

19 MARCH 2015

**TAN ENG CHOO**  
6A ROCHALIE DRIVE  
SINGAPORE 240006

Dear Sir/Madam,

**ACCIDENT INVOLVING SJY 147K AND YK 3646M ON 29/01/2015**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG

Case Handler

DID: 6742 3197

FAX: 6741 4108

Email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

## Hsiao Tong (LKKAUTO)

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Saturday, 8 July, 2017 11:22 AM  
**To:** 'Nurasikin.Sukimin@aig.com'  
**Subject:** Your Ref: 1091570710SG \*Our Ref: CC4/AIG15002569/Gpm3 [ACCIDENT INVOLVING SJY 147K(OI) & YK 3646M(TP) ON 29/01/2015]

Your Ref: **1091570710SG**  
Our Ref: CC4/AIG15002569/Gpm3

Dear Sirs,

### ACCIDENT INVOLVING SJY 147K(OI) & YK 3646M(TP) ON 29/01/2015

We refer to the above matter.

We had inspected third party vehicle on 11/02/2015. However there was no response from third party on submission of LOD/documents up-to-date.

In view of non-development from the third-party, we will proceed to temporarily close this outstanding claim file and submit our survey report to your good-office.

In future, if there are any new developments from the claimant, we will inform you for our further handling.

\*\*\*Kindly assist to re-open the case in Merimen for us to submit our report.

...CLAIM SUBFOLDER...(Close  
Express)

Claim Audit		Activity Log		Do			
<b>CLAIM SUBFOLDER TRACKING</b>							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2015 16:41		11 Feb 2015 00:00				Closed(Closed without O
Main		Reference		Claims Details			
<b>CLAIM SUBFOLDER DETAILS</b>							
Insured:	ID: S71000322						
Main Claimant:	EXCELLENCE ELECTRICAL TRADING Co. Reg. No.:						
Vehicle Reg. No.:	YK3646M Date of Loss:						
Claim Type:	TP / 1091570710SG Policy/Cover Note No.:						
Vehicle Reg. No. (Insured):	SJY147K Policy No. (Claimant):						
	Excess:						
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, S39216 Defu Lane - Tel: 6858 5151						
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tong, Fong Fong] FongFong.Tor						
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:						
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 24/						
<b>ASSOCIATED MAIL RECEIVED</b>							
<ul style="list-style-type: none"><li>AIG_SG (13/04/2016): Request for updates</li><li>AIG_SG (23/07/2015): Tp</li><li>AIG_SG (11/02/2015): No OI GIA Report (YK3646M VS SJY147K)</li></ul>							

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Hsiao Tong (LKKAUTO)

---

**From:** Sukimin, Nurasikin <Nurasikin.Sukimin@aig.com>  
**Sent:** Monday, 19 March 2018 10:12 AM  
**To:** Hsiao Tong (LKKAUTO)  
**Cc:** Dally Amri, Mimi Zarina  
**Subject:** RE: Your Ref: 1091570710SG \*Our Ref: CC4/AIG15002569/Gpm3 [ACCIDENT INVOLVING SJY 147K(OI) & YK 3646M(TP) ON 29/01/2015]

Without Prejudice

Hi Hsiao Tong

Claim reopened in Merimen. Please let me know if you found the same.

Thanks

Regards,

**NURASIKIN SUKIMIN**

**AIG**

Team Manager - Singapore Auto Express & Recovery, Claims Operations

**[IMPORTANT NOTICE:**

The information in this email (and any attachments hereto) is confidential and may be protected by legal privileges and work product immunities. If you are not the intended recipient, you must not use or disseminate the information. Receipt by anyone other than the intended recipient is not a waiver of any attorney-client or work product privilege. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[Nurasikin.Sukimin@aig.com](mailto:Nurasikin.Sukimin@aig.com) | [www.aig.com](http://www.aig.com)

---

**From:** Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]  
**Sent:** Saturday, March 17, 2018 8:28 AM  
**To:** Sukimin, Nurasikin; Dally Amri, Mimi Zarina  
**Subject:** RE: Your Ref: 1091570710SG \*Our Ref: CC4/AIG15002569/Gpm3 [ACCIDENT INVOLVING SJY 147K(OI) & YK 3646M(TP) ON 29/01/2015]

Hi,

We refer to our below email.

Kindly assist to re-open the case in Merimen for us to submit our report.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hsiao Tong (LKKAuto)

**Sent:** Saturday, 5 August 2017 1:53 PM

**To:** 'Nurasikin.Sukimin@aig.com' <[Nurasikin.Sukimin@aig.com](mailto:Nurasikin.Sukimin@aig.com)>

**Subject:** RE: Your Ref: 1091570710SG \*Our Ref: CC4/AIG15002569/Gpm3 [ACCIDENT INVOLVING SJY 147K(OI) & YK 3646M(TP) ON 29/01/2015]

Hi,

We refer to our below email.

Kindly assist to re-open the case in Merimen for us to submit our report.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hsiao Tong (LKKAuto)

**Sent:** Saturday, 8 July, 2017 11:22 AM

**To:** 'Nurasikin.Sukimin@aig.com' <[Nurasikin.Sukimin@aig.com](mailto:Nurasikin.Sukimin@aig.com)>

**Subject:** Your Ref: 1091570710SG \*Our Ref: CC4/AIG15002569/Gpm3 [ACCIDENT INVOLVING SJY 147K(OI) & YK 3646M(TP) ON 29/01/2015]

Your Ref: **1091570710SG**

Our Ref: CC4/AIG15002569/Gpm3

Dear Sirs,

**ACCIDENT INVOLVING SJY 147K(OI) & YK 3646M(TP) ON 29/01/2015**

We refer to the above matter.

We had inspected third party vehicle on 11/02/2015. However there was no response from third party on submission of LOD/documents up-to-date.

In view of non-development from the third-party, we will proceed to temporarily close this outstanding claim file and submit our survey report to your good-office.

In future, if there are any new developments from the claimant, we will inform you for our further handling.

\*\*\*Kindly assist to re-open the case in Merimen for us to submit our report.

**...CLAIM SUBFOLDER...(Close**  
Express

Claims Audit		Activity Log		Doc
<b>CLAIM SUBFOLDER TRACKING</b>				
Case	Insured	Est Submitted	Adj Assigned / Adj Rpt	Adj Submitted / Ins Auth'd / Status
Main	11 Feb 2015 16:41		11 Feb 2015 00:00	Closed(Closed without O

Plan	Reference	Claim Details
<b>CLAIM SUBFOLDER DETAILS</b>		
Insured:	ID: S7100032Z	
Main Claimant:	EXCELLENCE ELECTRICAL TRADING Co. Reg. No.: -	
Vehicle Reg. No.:	YK3646M	Date of Loss:
Claim Type:	TP / 1091570710SG	Policy/Cover Note No.:
Vehicle Reg. No. (Insured):	SJY147K	Policy No. (Claimant):
		Excess:
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, S39216 Defu Lane - Tel: 6858 5151	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tong, Fong Fong] FongFong.Tan	
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 24/	
<b>ASSOCIATED MAIL RECEIVED</b>		
<ul style="list-style-type: none"> <li>AIG_SG (13/04/2015): Request for updates</li> <li>AIG_SG (23/07/2015): Tp</li> <li>AIG_SG (11/02/2015): No OI GIA Report (YK3646M VS SJY147K)</li> </ul>		

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2015 16:41 <a href="#">Edit Reg</a>		10 Feb 2015 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$340.00</b> <a href="#">Edit Estimates</a>	<b>S\$340.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
<div>CLAIM SUBFOLDER DETAILS <span>[Created by adjuster]</span></div> <div> <div>Insured:</div> <div>TAN ENG CHOO, ID: S0031080H</div> </div> <div> <div>Main Claimant:</div> <div>EXCELLENCE ELECTRICAL TRADING, Co. Reg. No.: 52865962</div> </div> <div> <div>Vehicle Reg. No.:</div> <div>YK3646M</div> </div> <div> <div>Claim Type:</div> <div>TP / 1091570710SG</div> </div> <div> <div>Vehicle Reg. No. (Insured):</div> <div>SJY147K</div> </div> <div> <div>Repairer:</div> <div>Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151</div> </div> <div> <div>Handling Insurer:</div> <div>AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tong, Fong Fong] FongFong.Tong@aig.com</div> </div> <div> <div>Claimant's Insurer:</div> <div>NTUC Income Insurance Co-operative Ltd (HQ) - Tel:</div> </div> <div> <div>Adjuster:</div> <div>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 24/02/2015]</div> </div>				

## Claim Documents

\*YK3646M (1091570710SG)  
[SJY147K]  
TP  
EXCELLENCE ELECTRICAL TRADING  
Jan 29 2015 12:00PM  
[TAN ENG CHOO]  
Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <div>View in Browser</div>			
Photos/Images															3 per page		<div></div>	<div></div>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
2	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
3	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
4	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
5	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
6	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
7	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
8	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
9	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
10	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
11	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
12	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
13	21/07/15 10:06	General View												<div></div>	Load JPG	<div></div>		
14	21/07/15 10:07	Chassis Number												<div></div>	Load JPG	<div></div>		
15	21/07/15 10:07	Odometer Reading												<div></div>	Load JPG	<div></div>		
															1 per page		<div></div>	<div></div>
Documentation															1 per page		<div></div>	<div></div>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	11/02/15 16:37	ASSIGNMENT FROM WORKSHOP												<div></div>	Load PDF			
2	11/02/15 16:37	ASSIGNMENT FROM AIG												<div></div>	Load PDF			
3	11/02/15 16:37	TP ESTIMATE												<div></div>	Load PDF			
4	11/02/15 16:37	TP GIA REPORT												<div></div>	Load PDF			
5	21/07/15 10:08	Scene Photo1												<div></div>	Load JPG	<div></div>		
6	21/07/15 10:08	Scene Photo2												<div></div>	Load JPG	<div></div>		
7	21/07/15 10:08	Scene Photo3												<div></div>	Load JPG	<div></div>		
8	19/03/18 12:25	Email from AIG dd 190318.												<div></div>	Load PDF			
9	19/03/18 12:33	Letter to OI												<div></div>	Load PDF			
10	22/03/18 09:43	Registered Mail Fee												<div></div>	Load PDF			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print		
1	10/03/15 10:46	OI GIA REPORT												<div></div>	Load PDF			
2	09/07/15 12:53	CLEAR												<div></div>	Load DOCX			

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			



**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG15002569/GPB3Q2

Date: 22/03/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100221463  
 Claimant Vehicle No: YK3646M Insured Vehicle No: SJY147K  
 Date of Loss: 29/01/2015 Nature of Claim: TP Claim No: 1091570710SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: YK3646M  
 Make & Model: NISSAN CABSTAR, 2.5 (M) Engine No: QD32111025  
 Reg. Date: 31/03/2000 (Man. Year: 2000) Chassis No: JN1SF4F23Z0840312  
 Colour: White Odometer: 438138 km  
 Engine Capacity: 3153 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 155R12C  
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	561.62	240.00	321.62	57.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	300.00	100.00	200.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>861.62</b>	<b>340.00</b>	<b>521.62</b>	<b>60.54</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>60.31</b>	<b>23.80</b>	<b>36.51</b>	<b>60.54</b>
<b>Nett Amount (S\$)</b>	<b>921.93</b>	<b>363.80</b>	<b>558.13</b>	<b>60.54</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

## INSPECTION

Date of Assignment: 10/02/2015  
 Date Inspected: 11/02/2015 Inspected At: Tan Lim Motor Pte Ltd (Defu)  
 51 Defu Lane 10  
 Singapore 539216  
 Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Repair	521.62 FS	*200.00 FS
2	1		*FRONT LICENCE PLATE	Bent	40.00 FS	*40.00 FS
Total Parts (S\$)					561.62	240.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	300.00	100.00
Gross Labour Cost (S\$)			300.00	100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >