

LKK AUTO CONSULTANTS PTE LTD

51 Ubi Ave1, #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL : 6256 3561

FAX : 6256 4315

Reg. No: 199607198R

GST Reg. No. 19-9607198-R

MINISTRY OF DEFENCE
HQ-TRANSPORT COMMAND
KRANJI CAMP 3
151 CHUA CHU KANG WAY
SINGAPORE 688248

REF No. CC2/MIDA16001915

REF Date 24/08/2017

Code MIDA

DISBURSEMENT FEE

Vehicle No. **MID 18**
Insured
Claim No FY 15/16/0065
Policy No
Accident Date 23/01/2016
Inspection Date

<u>LKK Cost of Claim paid to claimant on behalf of MINDEF</u>		
Repair Cost of SHB 3368P @40%	\$	376.00
GST paid to claimant on behalf of MINDEF	\$	26.32
Loss of Rental (\$127.33 x 4days) @40%	\$	203.73
Loss of Income (\$50.00 x 4days) @40%	\$	80.00
Cost & Disbursement	\$	180.00
Total Fee	\$	866.05

We shall be glad if you could forward us the payment at your early convenience.

Cheque should be crossed and made payable to "**LKK AUTO CONSULTANTS PTE LTD**".

LKK AUTO CONSULTANTS PTE LTD

SBS1