

LKK AUTO CONSULTANTS PTE LTD

51 Ubi Ave1, #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL : 6256 3561

FAX : 6256 4315

Reg. No: 199607198R

GST Reg. No. 19-9607198-R

MINISTRY OF DEFENCE
AFPN HQ-SUPPLY
KRANJI CAMP 3
151 CHUA CHU KANG WAY
BLOCK 822, #03-05
SINGAPORE 688248

REF No. CC2/MIDF16002441

REF Date 06/06/2017

Code MIDF

DISBURSEMENT FEE

Vehicle No. **MID 46313**
Insured
Claim No WY 15/16/AF007
Policy No
Accident Date 18/12/2015
Inspection Date 29/12/2015

<u>LKK Cost of Claim paid to claimant on behalf of MINDEF</u>		
Repair Cost of GBC 4376A	\$	3,750.00
GST paid to claimant on behalf of MINDEF	\$	262.50
Loss of Use (\$60 x 7 days)	\$	420.00
Total Fee	\$	4,432.50

We shall be glad if you could forward us the payment at your early convenience.

Cheque should be crossed and made payable to "LKK AUTO CONSULTANTS PTE LTD".

LKK AUTO CONSULTANTS PTE LTD

SBS1