

INS CASE OWNER

CC 6 AIG 160 04803 / Mlpaz

LJK IDAC

Surveyor:

MaCF

DOI:

ASSIGNMENT

11/4/16

Date / Time:

11/4/16

Registered in Merimon:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

SGX5194G

Claim No.:

Name of Insured:

Tariq Malik @ Nicholas Tariq Malik

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A: 11/3/16

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SJF4440L



INSRS:

WSP: Em-1

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



URGENT

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SJF4440L : CC4/AXA16004861/01106362/D.O.A: 11/3/16  
SGX5194G : CV1/VAL16MX262/CA  
D.O.A: -

STAGE

DATE / PIC

28/11/19

File -> type mandate

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

Ch

After call ltr to OI:

4/12/19

File -> Su U to send DV

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LGD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ ( days) Reduction: % Email  Call

FINAL SETTLEMENT

Date/Time: 4/12/19

Confirm with: Karen

Email  Call

Final Liability: % (Agreed / Assessed) BOLA S/N No.: 28911 + 01101111 If NO or B 28, Ass. Lia: 100%

Repair Cost: WGM S\$ 19795.00

Loss of Rental (LOR): S\$ 1950.00 ( 13 days) x \$150.00

Loss of Use (LOU): S\$ - (5 x days)

Loss of Income (LOI): S\$ - (5 x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search: S\$ 5.35

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/ Independent)

Legal Cost: S\$ -

Total: S\$ 21750.35 Global Sum S\$: 21750.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email  Call

Payee 1: S\$ 21750.00 Name 1: EM-1 Auto Hrc Ltd

Payee 2: (Strike if N.A.) S\$ Name 2:

Payee 3: (Strike if N.A.) S\$ Name 3:

COPY SENT

1) Claim status: No  Reject/Private Settle

2) Report Format: 91

3) Survey fee: \$220.00

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop n/s - PMI

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

/	
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SJF 4440L Yr Regn: NIA / 08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: HONDA GOSSY c.c. 2354

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 17811 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHWAB1850C20N79

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 215/55/2A

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 11/03/2016 D.O.I. 11/03/2016

Survey held at \_\_\_\_\_

Des. of Damages FR / REAR / O/S / N/S / U/C / Rooftop or

FR / REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>US # 185W Red # 1442 / 4471</u>

Date/Time, File Pass to?  : Prel. Report

1)  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_ )

: Interview (\$ \_\_\_\_\_ )

: Tech. Invs (\$ \_\_\_\_\_ )

Survey Fee:	
Transportation:	
\$ + RS _____ SI	
Photos	
Others	

Report Format : \_\_\_\_\_

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SJF 4440L  
 Vehicle Model : HONDA ODYSSEY  
 Accident Date : 11.03.2016  
 Original Reg Date : 29.05.2008

Date : 11.03.2016  
 Chassis : JHMRB18508C203479  
 TP Ins. : AIG

## ESTIMATE

1	1 pc	Tailgate	✓	1,056.00	
2	1 pc	Tailgate Badge	✓	48.00	
3	1 pc	Tailgate Outer Chrome Moulding	✓	256.70	
4	1 set	Tailgate Outer Chrome Moulding Clips	✓	40.00	
5	2 pcs	Tailgate Lamps	✓	560.90	1,121.80
6	2 pcs	Tailgate Lamps Inner Sealer	✓	30.00	60.00
7	2 set	Tailgate Lamps Clips	✓	20.00	40.00
8	1 pc	Tailgate Outer Garnish	✓		694.40
9	1 set	Tailgate Outer Garnish Clips	✓		40.00
10	2 pcs	Tailgate Number Plate Lamp	✓	46.00	92.00
11	1 pc	Tailgate Opener Handle	✓		62.20
12	1 pc	Tailgate Pocker Handle	✗		42.60
13	2 pcs	Tailgate Stopper	✓	18.00	36.00
14	1 pc	Tailgate Inner Trim	✓		328.00
15	1 set	Tailgate Inner Trim Clips	✓		40.00
16	1 pc	Tailgate Weatherstrip	✓		165.90
17	1 pc	Tailgate Inner Lock	✓		175.50
18	1 pc	Tailgate Auto Lock Actuator	✓		156.20
19	1 pc	Tailgate Lock Catch	✓		36.00
20	2 pcs	Tailgate Absorber	✗	192.00	384.00
21	2 pcs	Tailgate Hinges	✗	56.00	112.00
22	1 pc	Rear Windscreen Moulding	✓		93.00
23	1 pc	Rear Windscreen Inner Seal	✓		60.00
24	2 pcs	Taillamps	✓	752.00	1,504.00
25	2 pcs	Taillamps Inner Sealer	✓	30.00	60.00
26	2 set	Taillamp Clips	✓	25.00	50.00
27	1 pc	Taillamp Panel LH	✓		159.20
28	1 pc	Rear Bumper	✓		892.00
29	4 pcs	Rear Bumper Screw Cover	✓	12.00	48.00
30	2 pcs	Rear Bumper Side Retainers	✓	39.00	78.00
31	2 pcs	Rear Bumper Attachment Retainers	✓	36.00	72.00
32	1 set	Rear Bumper Clips	✓		40.00
33	1 pc	Rear Bumper Tow Cover	✓		29.00

C/F

8,072.50

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SJF 4440L

B/F

8,072.50

1	1 pc	Rear Bumper Reflectors	ms	✓	65.00	
2	1 pc	Rear Bumper Top Beam	bt	✓	97.20	
3	1 pc	Rear Bumper Reinforcement	bt	✓	132.20	
4	1 pc	Rear Bumper Reinforcement Bracket LH	bt	✓	70.20	
5	1 pc	End Panel	bt	✓	563.50	
6	1 set	End Panel Top Trim	dig	✓	123.00	
7	1 set	End Panel Top Trim Clips	ms	✓	30.00	
8	1 pc	Spare Tyre Panel	ms	✓	1,118.50	
9	1 pc	Spare Tyre Panel Side Panel LH	bt	✓	256.50	
10	1 pc	Spare Tyre Panel Top Board	dig	✓	360.00	
11	1 pc	Spare Tyre Wheel Nut	ms	x	46.00	
12	2 pcs	Rear Chassis Frame Member	NS	7	800.00	x 1,600.00
13	2 pcs	Rear Fender Inner Trim	NS	7	488.00	976.00
14	2 set	Rear Fender Inner Trim Clips	ms	7	30.00	✓ 60.00
15	1 pc	Rear Fender Inner Trim Tool Box Cover LH		7		79.60
16	2 pcs	Rear Fender Inner Shield	NS	7	105.00	x 210.00
17	2 set	Rear Fender Inner Shield Clips	ms	40	25.00	50.00
18	1 pc	Rear Exhaust Silencer RH	ms	x	972.60	
19	1 pc	Rear Exhaust Silencer LH	bt	✓	595.00	
20	4 pcs	Rear Exhaust Mountings		7	38.00	152.00
21	2 pcs	Rear Exhaust Gasket	ms	✓	45.00	90.00
22	2 pcs	Rear Exhaust Heat Plate	NS	7	78.00	x 156.00
23	1 pc	Rear Absorber LH		7		501.00
24	1 pc	Rear Upper Arm LH		7		146.20
25	1 pc	Rear Lower Arm LH		7		351.00
26	1 pc	Rear Knuckle Arm LH		7		395.00
27	1 pc	Rear Wheel Bearing LH		x		362.90
28	1 pc	Anti Roll Bar		7		153.00
29	2 pcs	Anti Roll Bar Bush		x	29.00	58.00
30	1 pc	Anti Roll Bar Bar Link LH		7		95.00
31	1 pc	Rear Cross Member		7		881.00
32	1 pc	Bonnet	ms	✓		816.00
33	1 pc	Bonnet Rubber (Inner)		4		26.00
34	1 pc	Bonnet Rubber (Outer)		x		26.00
35	2 pcs	Bonnet Side Rubber		22.00		x 44.00

C/F

19,730.90

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SJF 4440L

B/F

19,730.90

1	1 set	Bonnet Rubber Clips	nel	✓	20.00	
2	1 pc	Bonnet Inner Lock	bf	✓	97.20	
3	1 set	Bonnet Insulator Clips	wc	✓	40.00	
4	1 pc	Front Grille	dgc	✓	263.30	
5	1 pc	Front Grille Badge	ua	✓	48.00	
6	1 pc	Front Grille Top Chrome Moulding	rtg	✓	93.60	cash
7	1 pc	Front Grille Center Chrome Moulding	dgc	✓	142.20	cash
8	1 set	Front Grille Clips	wc	✓	30.00	
9	2 pcs	Headlamps			792.00	7 1,584.00 CRA ✓
10	2 pcs	Headlamps Bottom Retainers			49.00	✓ 98.00 dig
11	2 set	Headlamps Clips			20.00	40.00 ua
12	1 pc	Front Bumper				ded 816.00 ✓
13	2 pcs	Front Bumper Side Retainers			38.00	219 76.00 ✓
14	1 set	Front Bumper Clips				ua 40.00 ✓
15	2 pcs	Front Bumper Fog Lamps with Covers			7. 740.90	1,481.80 XSM ✓
17	1 pc	Front Bumper Reinforcement				7 291.00 DD ✓
18	1 pc	Front Bumper Lower Grille	dgc	✓	126.20	
19	1 pc	Engine Under Cover				7 112.00 CRA ✓
20	1 set	Engine Under Cover Clips	wc	✓	30.00	
21	1 set	Horns				7 120.00 XND ✓
22	1 pc	Support Panel	bf	✓	539.60	
23	1 pc	Air Con Condenser				890.00 7 DD ✓
24	1 pc	Condenser Air Con Pipe				390.30 7 BT ✓
25	1 pc	Condenser Suction Pipe				219.50 7 DD ✓
26	1 pc	Condenser Discharge Pipe				236.00 7 BT ✓
27	1 pc	Radiator				1,436.90 7 DD ✓

28,992.50

Less 20% 5,798.50

23,194.00

C/F

23,194.00

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

parts hence notify the following:  
 • To display parts after survey painting  
 • Parts prices are subject to confirmation  
 • No illegal modification is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Vehicle No : SJF 4440L

B/F Acknowledged by Repairer  
 Signature: **23,194.00**  
 Date:

## Special Nett

1	1 pc	Rear Windscreen Sealant		nrc	60.00	40
2	1 pc	Rear Number Plate		lot	50.00	40
3	1 pc	Body Panel Joint Sealant		nrc	120.00	80
4	1 pc	Rear Floor Panel Insulator Pad		nrc	150.00	120
5	4 pcs	Reverse Sensor		lot	450.00	250
6	1 pc	Rear Exhaust Chrome Pipe	nrc	lot	140.00	120
8	1 pc	Spare Tyre		nrc	X 250.00	
9	1 pc	Spare Tyre Rim		nrc	X 320.00	
7	1 pc	Radiator Coolant		41	40.00	
10	1 pc	Front Number Plate with Cover		lot	70.00	
11	1 pc	Front Bumper Lower Spoiler		lot	950.00	800

## Labour charge

Panel Beating	2,600.00	2400
Spray painting	2,500.00	2200
Check Wiring	100.00	30
Anti rust	180.00	150
Towing Fees	70.00	✓
Remove and install rear winscreen.	140.00	120
Remove and install tailgate parts.	90.00	60
Remove and install carpet and seat.	120.00	80
Remove and install reverse sensor	90.00	80
Remove and install rear exhaust silencer.	150.00	120
Remove and install petrol tank.	90.00	80? ✓
Remove and install rear undercarriage.	450.00	180
To perform computerize wheel alignment.	90.00	80
To jack and alignment chassis frame member.	320.00	280
Remove and install air con.	150.00	120

Not Amshortw  
 45 Rpm  
 After painting  
 15 w/days  
 11/03/2016

**\$ 32,934.00**

## Hsiao Tong (LKKAuto)

---

**From:** Chia Sin Muk <em1autopteltd@gmail.com>  
**Sent:** Thursday, 27 June 2019 3:55 PM  
**To:** Hsiao Tong (LKKAuto)  
**Cc:** Admin A  
**Subject:** Re: LOD - SJF 4440L DOA 11.03.2016 - TP AIG \*\*\* LKK REF: CC6/AIG16004803/M1pa3  
**Attachments:** 4440L Logcard-27062019155433.pdf

### WITHOUT PREJUDICE

Dear Hsiao Tong,

File?

As per your telephone conversation, attached PARF/ COE Rebate form  
Kindly revert at your earliest convenience.

### **Thanks & Best Regards,**

Karen, on behalf of,  
Chia Sin Muk (Mr)  
m: (65) 9666 6556 | o: (65) 6452 3298 | f: (65) 6457 5776

### **EM-1 Auto Pte Ltd**

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643  
Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

On Thu, 14 Mar 2019 at 21:17, Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)> wrote:  
Without Prejudice

Dear Sirs/Mdm,

We refer to our below email.

We would like to request a copy of PARF/ COE Rebate of your client vehicle for our necessary action.

Appreciate an early reply.

Best Regards,  
**Hsiao Tong, Chew** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

----- Forwarded message -----

From: **Hsiao Tong (LKKAuto)** <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
Date: Wed, 21 Nov 2018 at 10:06  
Subject: RE: LOD - SJF 4440L DOA 11.03.2016 - TP AIG \*\*\* LKK REF: CC6/AIG16004803/M1pa3  
To: Chia Sin Muk <[em1autopteltd@gmail.com](mailto:em1autopteltd@gmail.com)>  
Cc: Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Without Prejudice**

Dear Sirs/Mdm,

We refer to the above matter.

We would like to request a copy of PARF/ COE Rebate of your client vehicle for our necessary action.

Appreciate an early reply.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAuto)

**Sent:** Saturday, 5 May 2018 5:14 PM

**To:** Chia Sin Muk <[em1autopteltd@gmail.com](mailto:em1autopteltd@gmail.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Joy Irene (LKKAuto) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>

**Subject:** RE: LOD - SJF 4440L DOA 11.03.2016 - TP AIG \*\*\* LKK REF: CC6/AIG16004803/M1pa3

Dear Sir / Madam,

Thank you for your email.

Please note that: -

<b>LKK ref</b>	<b>Officer in charge</b>
CC6/AIG16004803/M1pa3	Hsiao Tong - 6742 3197

Our respective case handler will look into the matter and revert to you in due course.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Chia Sin Muk [<mailto:em1autopteltd@gmail.com>]

**Sent:** Friday, 4 May, 2018 5:24 PM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** LOD - SJF 4440L DOA 11.03.2016 - TP AIG

WITHOUT PREJUDICE

Dear Sir/Madam,

Please find the attached LOD.

COR \$ 22,470.00

LTA \$ 5.35

LOR \$ 2,340.00

Total : \$ 24,815.35

Kindly arrange for settlement.

**Thanks & Best Regards,**

Nicole, on behalf of,  
Chia Sin Muk (Mr)

**m:** (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

**EM-1 Auto Pte Ltd**

Blk B #01-68 Sin Ming Rd Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.



Text size + -

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2299H

### Vehicle Details

Vehicle No.: SJF4440L

Vehicle to be Exported: Yes

Intended De-registration Date: 12 Mar 2016

Vehicle Make: HONDA

Vehicle Model: ODYSSEY 2.4 A

Primary Colour: Beige

Manufacturing Year: 2008

Engine No.: K24A65003479

Chassis No.: JHMRB18508C203479

Maximum Power Output: 118.0 kW (158 bhp)

Open Market Value: \$28,145.00

Original Registration Date: 29 May 2008 ✓

First Registration Date: 29 May 2008

Transfer Count: 0

Actual ARF Paid: \$28,145.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 May 2018

PARF Rebate Amount: \$16,887.00

### Intended COE Rebate Details

COE Expiry Date: 28 May 2018 ✓

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$15,889.00

COE Rebate Amount: \$3,510.00

**Total Rebate Amount: \$20,397.00 ✓**

The information contained herein is correct as at 11 Mar 2016

OK

Land Transport Authority

Please read through the Privacy Statement Terms of Use and Disclaimer.

Home > Used Cars > Aden Automobile > Honda Odyssey 2.4A Absolute

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Mer's Interest

Car Leasing

**URBAN**

LEASING \$0 DOWNPAYMENT!

Honda Odyssey 2.4A Absolute

Overview Financial Accessories Similar Research Photos Map

Add to Compare Add to Shortlist Add a Note Report Error More Actions Share

Car Details

Price	\$41,666
Road Tax	\$1,628 /yr (Excl 2015/16 rebate)
Transmission	Auto
Engine Cap	2,354 cc
Power	118.0 kW (158 bhp) View specs of the Honda Odyssey
Reg Date	05-May-2008 <i>29/5/2008</i>
Mileage	106,000 km
Features	Powerful 2.4L I-VTEC DOHC Engine, ABS, Airbags, Auto Retractable Indicators Mirror, Multi Steering Control, Cruise Control, Auto HID Headlamps.
Accessories	Factory Fitted Audio System With Disc Changer, Sunroof, 3rd Row Electric Seat, Fog Lamp, Leather Seats And Rims.
Description	1 Owner Well Maintained By Previous Fussy Owner! Luxury Black Japanese Spacious And Comfortable 7 Seater MPV. Great handling And Stability, Fuel Efficient, Pristine Condition. A Perfect Choice For Your Lovely Family. Call Our Sales Advisor Now For An Non Obligation Discussion And Come For A Test Drive Before It's Gone Again.
COE	\$18,501
OMV	\$28,209
Depreciation	\$13,729 /year
No. of Owners	1
Type of Veh	MPV
Category	MPV Car
Availability	Available

Like 179

Posted on: 03-Mar-2016 | Last Updated on: 03-Mar-2016

Tags: Honda Odyssey, 2008 Honda Odyssey, Honda, Odyssey, Used Honda

Upfront Payment » more financial info

Transfer Fee	\$11	
Down Payment	\$16,666 (change)	Maximum 60% Loan
1st Instalment	\$1,662	
Total Upfront Payment	\$17,729 (excluding insurance)	

Estimates based on 60% loan at 2.98% interest rate. Check with seller for exact figure.

Items for Honda Odyssey » View All



Gearbox II (Honda AL) Transmitt.



Car Mat From \$30



Seller Information

Company	Aden Automobile • dealer's picket • 5 years sold   7 years available
Address	9012 Tampines Street 93 #03-189 Search cars nearby this location
Office No	66840071
Contact Person(s)	Derrick Tan 98334443

Useful Services

**STA**  
Make sure of this car condition with STA Evaluation.  
**Vehicle Evaluation**  
Find out the market value for your car. Get a free Car Valuation.  
**Free Valuation**

Compare

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Monday, 2 December 2019 2:08 PM  
**To:** Parthiban, Theerthan  
**Cc:** Admin A; Mohd Rizal, Nur Mariah Huibrechts; Lim, Sheng Yang  
**Subject:** <SEEK MANDATE> : Pending Adjuster Survey in Merimen LKK \*\*\* LKK REF: CC6/AIG16004803/M1pa3

AIG ref : **4387491972SG**  
LKK ref : CC6/AIG16004803/M1pa3

Dear Sirs/Madam,

### **ACCIDENT INVOLVING SGX5194G(AIG) / SJF4440L(TP)/ OTHERS ON 11/03/2016**

We refer to the above matter.

The said chain collision involved 4 vehicles whereby our insured was the last vehicle. In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%. We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, "EM-1 AUTO PTE LTD" is as follows: -

	<b>Claimed Amount</b>	<b>Revised Amount</b>
1. Cost of Repair (w/GST)	\$ 35,239.38	\$ 19,795.00
2. Loss of Rental (13 days x \$180.00)	\$ 2,340.00	\$ 2,080.00 (13days x \$160.00)
3. LTA/ GIA Search Fee	\$ 5.35	\$ 5.35
<b>Total</b>	<b>\$ 37,584.73</b>	<b>\$ 21,880.35</b>

\*\*15days recommendation for repair.

All the relevant documents had been uploaded in Merimen.

**Kindly let us have your mandate in Merimen.**

Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>  
**Sent:** Tuesday, 12 November 2019 10:47 AM  
**To:** Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Mohd Rizal, Nur Mariah Huibrechts <NurMariahHuibrechts.MohdRizal@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Admin A <admin-a@lkkauto.com>

**Subject:** RE: Pending Adjuster Survey in Merimen LKK \*\*\* LKK REF: CC6/AIG16004803/M1pa3

***'WITHOUT PREJUDICE'***  
***SAVE AS TO COSTS***

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

***Hi Hsiao Tong,***

***Kindly assist.***

***To check availability of the case handler, you may contact the undersigned.***

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Parthiban, Theerthan

**Sent:** Tue, 12 Nov 2019 01:38:43 +0000

**To:** [admin-a@lkkauto.com](mailto:admin-a@lkkauto.com), [assignments@lkkauto.com](mailto:assignments@lkkauto.com), Veron Chen (LKKAuto), [Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)

**Cc:** Mohd Rizal, Nur Mariah Huibrechts, Lim, Sheng Yang

**Subject:** Pending Adjuster Survey in Merimen LKK

Hi LKK,

The Third Party claim below is under Pending Adjuster Survey status in Merimen

Kindly advise on the current status and if there is any action required

Vehicle Reg. No.: SGX5194G- OI SJF4440L- TP

Date of Loss: 11/03/2016

Claim Type: TP / 4387491972SG

Kindly assist

Thank you

Regards,

Theerthan R Parthiban (Troy)  
AIG  
Senior Claims Examiner, Auto

Singapore Claims Operations | AIG Shared Services

Tel: 8001206556 Ext: 1002217

[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**From:** Parthiban, Theerthan <[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com)>

**Sent:** Tuesday, 12 November, 2019 9:39 AM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>; Mei Kwan (LKKAuto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>

**Cc:** Mohd Rizal, Nur Mariah Huibrechts <[NurMariahHuibrechts.MohdRizal@aig.com](mailto:NurMariahHuibrechts.MohdRizal@aig.com)>; Lim, Sheng Yang <[ShengYang.Lim@aig.com](mailto:ShengYang.Lim@aig.com)>

**Subject:** Pending Adjuster Survey in Merimen LKK



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息 · 如要阅读此信息 · 请开盾附件 ·

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ  
เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면  
첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka  
attachment.

[Click here](#) by 2019-11-19 09:38 +08 to read your message.  
After that, open the attachment.

[More info](#)

**Disclaimer** This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**<SEEK MANDATE> : Pending Adjuster Survey in Merimen LKK \*\*\* LKK R...**

From: Parthiban, Theerthan  
To: Hsiao Tong (LKKAuto)  
Cc: Admin A, Mohd Rizal, Nur Mariah Huibrechts, Lim, Sheng Yang  
Sent: 02/12/2019 4:51:53 pm

---

Hi Hsiao Tong,

Mandate has been approved

Kindly assist with the necessary action

Thank you

Regards,

**Theerthan R Parthiban (Troy)**  
**AIG**  
Senior Claims Examiner, Auto  
Singapore Claims Operations | AIG Shared Services

Tel: 8001206556 Ext: 1002217  
[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>  
**Sent:** Monday, December 2, 2019 2:08 PM  
**To:** Parthiban, Theerthan <Theerthan.Parthiban@aig.com>  
**Cc:** Admin A <admin-a@lkkauto.com>; Mohd Rizal, Nur Mariah Huibrechts <NurMariahHuibrechts.MohdRizal@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>  
**Subject:** [EXTERNAL] <SEEK MANDATE> : Pending Adjuster Survey in Merimen LKK \*\*\* LKK REF: CC6/AIG16004803/M1pa3

This message is from an external sender; be cautious with links and attachments.

AIG ref : **43874919725G**  
LKK ref : CC6/AIG16004803/M1pa3

Dear Sirs/Madam,

**ACCIDENT INVOLVING SGX5194G(AIG) / SJF4440L(TP)/ OTHERS ON 11/03/2016**

We refer to the above matter.

The said chain collision involved 4 vehicles whereby our insured was the last vehicle.  
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.  
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, "EM-1 AUTO PTE LTD" is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 35,239.38	\$ 19,795.00
2. Loss of Rental (13 days x \$180.00)	\$ 2,340.00	\$ 2,080.00 (13days x \$160.00)
3. LTA/ GIA Search Fee	\$ 5.35	\$ 5.35
<b>Total</b>	<b>\$ 37,584.73</b>	<b>\$ 21,880.35</b>

\*\*15days recommendation for repair.

All the relevant documents had been uploaded in Merimen.

**Kindly let us have your mandate in Merimen.**

Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAuto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>

**Sent:** Tuesday, 12 November 2019 10:47 AM

**To:** Parthiban, Theerthan <[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Cc:** Mohd Rizal, Nur Mariah Huibrechts <[NurMariahHuibrechts.MohdRizal@aig.com](mailto:NurMariahHuibrechts.MohdRizal@aig.com)>; Lim, Sheng Yang <[ShengYang.Lim@aig.com](mailto:ShengYang.Lim@aig.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Pending Adjuster Survey in Merimen LKK \*\*\* LKK REF: CC6/AIG16004803/M1pa3

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

***Hi Hsiao Tong,***

***Kindly assist.***

***To check availability of the case handler, you may contact the undersigned.***

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

**From:** Parthiban, Theerthan  
**Sent:** Tue, 12 Nov 2019 01:38:43 +0000  
**To:** [admin-a@lkkauto.com](mailto:admin-a@lkkauto.com), [assignments@lkkauto.com](mailto:assignments@lkkauto.com), Veron Chen (LKKAuto), [Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)  
**Cc:** Mohd Rizal, Nur Mariah Huibrechts, Lim, Sheng Yang  
**Subject:** Pending Adjuster Survey in Merimen LKK

Hi LKK,  
The Third Party claim below is under Pending Adjuster Survey status in Merimen  
Kindly advise on the current status and if there is any action required  
Vehicle Reg. No.: SGX5194G- OI SJF4440L- TP  
Date of Loss: 11/03/2016  
Claim Type: TP / 4387491972SG  
Kindly assist  
Thank you  
Regards,  
Theerthan R Parthiban (Troy)  
AIG

Senior Claims Examiner, Auto  
Singapore Claims Operations | AIG Shared Services  
Tel: 8001206555 Ext: 1002217

[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**From:** Parthiban, Theerthan <[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com)>  
**Sent:** Tuesday, 12 November, 2019 9:39 AM  
**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>; Mei Kwan (LKKAuto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>  
**Cc:** Mohd Rizal, Nur Mariah Huibrechts <[NurMariahHuibrechts.MohdRizal@aig.com](mailto:NurMariahHuibrechts.MohdRizal@aig.com)>; Lim, Sheng Yang <[ShengYang.Lim@aig.com](mailto:ShengYang.Lim@aig.com)>  
**Subject:** Pending Adjuster Survey in Merimen LKK



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-11-19 09:38 +08 to read your message.  
After that, open the attachment.

[More Info](#)

**Disclaimer:** This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

## Print Received Message

This mail is associated with :

**\*SJF4440L (4387491972SG)**

**[SGX5194G]**

TP

ANG TIN KING

Mar 11 2016 7:00AM

[Tariq Malik @ Nicholas Tariq Malik]

Em-1 Auto Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 02/12/2019 15:55 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$21880.35) - SJF4440L - Claim Handler: Sivaguru Raja, Jeevan Raj

Approved:21880.35.

## Hsiao Tong (LKKAuto)

---

**From:** Chia Sin Muk <em1autopteltd@gmail.com>  
**Sent:** Tuesday, 3 December 2019 3:09 PM  
**To:** Hsiao Tong (LKKAuto)  
**Cc:** Admin A  
**Subject:** Re: Your Ref: SJF4440L \*Our Ref: CC6/AIG16004803/M1pa3 [ACCIDENT INVOLVING SGX 5194G(AIG) AND SJF 4440L ON 11/03/2016]

### WITHOUT PREJUDICE

Dear Hsiao Tong,

We confirmed acceptance of your offer Global sum \$21,750.00 (all-in).  
Kindly proceed to arrange payment/DV to EM-1 AUTO PTE LTD.

### **Thanks & Best Regards,**

Karen, on behalf of,

Chia Sin Muk (Mr)

m: (65) 9666 6556 | o: (65) 6452 3298 | f: (65) 6457 5776

### **EM-1 Auto Pte Ltd**

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

On Tue, 3 Dec 2019 at 08:23, Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)> wrote:

Your Ref: **SJF4440L**

Without Prejudice

Our Ref: CC6/AIG16004803/M1pa3

Dear Sirs/Mdm,

### **ACCIDENT INVOLVING SGX 5194G(AIG) AND SJF 4440L ON 11/03/2016**

We refer to the above matter.

We have our principal instruction to offer at a global sum of \$21,750.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LETTER OF AUTHORISATION**

ACCIDENT INVOLVING (any vehicle) SJF4440L and S6X5194G,  
ON 11/3/16 ALONG SLE towards RFE

I, Ang Tin King, NRIC No. / Company Reg. No.  
S1472299H of (address) \_\_\_\_\_

Postal Code \_\_\_\_\_, the registered owner (or authorised agent) of motor vehicle registration number  
SJF4440L hereby authorise your workshop EM-1 Auto Pte Ltd (Company/GST REG.No. : 201316380R)

Blk B #01-68 Sector C Sin Ming Industrial Estate Singapore 575643 to :-

1. Begin or commence repairs to my/our motor vehicle;
2. Start or initiate third party claims for damages incurred by me against third party(jes) responsible for the accident.
3. To instruct EM-1 Auto Pte Ltd on my/our behalf to negotiate a settlement with the third party and/ or his insurers as you deem fit.
4. To appoint vehicle surveyor on my/our behalf to determine reasonable costs of repair and period of repair.
5. To act on my/our behalf for any documents mailed to EM-1 Auto Pte Ltd by the third party and/or his insurers for the claim of my vehicle, if I am not contactable.

I am prepared to attend at my/our solicitors' office or to attend Court in connection with my/our claim, if necessary, I shall give my full co-operation and support for the claim for cost of repair and loss of use and shall keep you informed of any correspondences and/or summons that I may receive due to this action before agreeing to pay up or receive any monies due to this claim.

I authorise you to claim for the period of loss of use as specified by the motor surveyor or such shorter period due to accelerated work. I further authorise you to accelerate the repair period with overtime work and additional resource, I will pay you a reasonable amount to reflect the additional period of time to shorten.

I agree to keep you informed of any document(s), including cheques, mailed to me by third party and/or his insurers before taking any action. I also will not bank in any cheques issued by third party insurance and/or his insurers without the approval of EM-1 Auto Pte Ltd, and should I get approval from EM-1 Auto Pte Ltd to bank in the said cheques, I agree to pay EM-1 Auto Pte Ltd the full settlement amount as stated on the cheques within 5 working days.

Should my/our claim be partly successful or unsuccessful or cannot be proceeded with and/or if any judgement or settlement is not honoured or satisfied by third party, I/We:

1. Agree to pay you the sum of monies (as agreed) or as certified by the surveyor appointed, being the costs of repairs, survey fees and/or any other expenses reasonably incurred by you on my/our behalf. You may use the recovered amount from my claim for loss of us to partially offset the difference.
2. Agree to pay you such increased cost for additional resources and overtime work to shorten the period of repair.
3. Will pay for any shortfall that may result in the settlement amount.

In the event that EM-1 Auto Pte Ltd or the Repairer is compelled to enforce this undertaking, I/We agree that I/we shall pay on a full indemnity basis, the legal costs incurred by EM-1 Auto Pte Ltd or the Repairer.

Signature: \_\_\_\_\_  
Company Stamp:  
(if applicable)

Name: Ang Tin King  
NRIC No: S1472299H  
Contact No: 96859220  
Date: 11/3/16

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R



M/S ANG TIN KING

Invoice : 18/PI00118/4481TP

: 04-May-2018

AIG Asia Pacific Insurance Pte. Ltd.

Motor Claim Department

AIG Building

78 Shenton Way

#07-16 Singapore 079120

Without Prejudice

Date of Accident : 11-Mar-2016  
Our Client's Vehicle Number : SJF 4440L  
Vehicle Make / Model : HONDA ODYSSEY  
Your Insurer : SGX 5194G

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost	18,500.00	1,295.00	19,795.00

GRAND TOTAL

19,795.00



Authorised Signature and Company Stamp

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Mar 2016 <a href="#">Edit Reg</a>		11 Mar 2016 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$18,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$18,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	Tariq Malik @ Nicholas Tariq Malik, ID: S68724603								
Main Claimant:	ANG TIN KING, ID: S1472299H								
Vehicle Reg. No.:	SJF4440L	Date of Loss:	11/03/2016 07:00 - :59 [93 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4387491972SG	Policy/Cover Note No.:	2100038674						
Vehicle Reg. No. (Insured):	SGX5194G	Policy No. (Claimant):	VPA/P0664Z24						
		Excess:							
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Sivaguru Raja, Jeevan Raj] jeevansivagum@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 23/03/2016]								
ASSOCIATED MAIL RECEIVED		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>						
<ul style="list-style-type: none"> <li>AIG_SG (02/12/2019): Alert - Adj Mandate Approved (S\$21880.35) - SJF4440L - Claim Handler: Sivaguru R...</li> </ul>									
ALL ASSOCIATED TASKS		<a href="#">View All</a>	<a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJF4440L (4387491972SG)  
[SGX5194G]  
TP  
ANG TIN KING  
Mar 11 2016 7:00AM  
[Tariq Malik @ Nicholas Tariq Malik]  
Em-1 Auto Pte Ltd

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<a href="#">Upload Video</a>	<a href="#">Upload Audio</a>	<b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span>
<b>Letters/Correspondences</b>						1 per page <input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	(Draft)	<b>Third Party Express Settlement - Payment Breakdown</b>		Edit		
<b>Assessment Reports</b>						1 per page <input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	15/03/16 14:08	<b>Accident Statement</b> <small>From: OD - Reg. No: SGX5194G, Claimant: TARIQ MALIK @ NICHOLAS TARIQ MALIK</small>		Load HTM		
<b>Photos/Images</b>						3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	14/03/16 16:51	<b>Odometer Reading</b>		Load JPG	<input checked="" type="checkbox"/>	
2	14/03/16 16:51	<b>Chassis Number</b>		Load JPG	<input checked="" type="checkbox"/>	
3	14/03/16 16:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
4	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
5	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
6	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
7	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
8	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
9	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
10	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
11	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
12	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
13	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
14	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
15	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
16	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
17	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
18	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
19	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
20	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
21	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
22	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
23	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
24	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
25	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
26	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
27	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
28	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
29	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
30	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
31	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
32	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
33	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
34	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
35	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
36	14/03/16 16:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
37	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
45	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
46	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
47	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
48	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
49	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
50	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
51	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
52	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
53	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
54	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
55	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
56	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
57	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
58	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
59	14/03/16 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
60	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
92	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
93	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
94	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
95	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
96	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
97	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
98	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
99	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
100	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
101	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
102	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
103	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
104	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
105	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
106	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
107	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
108	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
109	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
110	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
111	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
112	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
113	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
114	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
115	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
116	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
117	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
118	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
119	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
120	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
121	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
122	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
123	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
124	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
125	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
126	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
127	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
128	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
129	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
130	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
131	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
132	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
133	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
134	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
135	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
136	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
137	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
138	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
139	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
140	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
141	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
142	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
143	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
144	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
145	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
146	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
147	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
148	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
149	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
150	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
151	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
152	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
153	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
154	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
155	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
156	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
157	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
158	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
159	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
160	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
161	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
162	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
163	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
164	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
165	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
166	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
167	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
168	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
169	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
170	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
171	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
172	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
173	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
174	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
175	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
176	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
177	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
178	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
179	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
180	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
181	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
182	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
183	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
184	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
185	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
186	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
187	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
188	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
189	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
190	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
191	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
192	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
193	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
194	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
195	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
196	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
197	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
198	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
199	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
200	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
201	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
202	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>
203	02/12/19 13:59	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
204	02/12/19 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
205	02/12/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
206	02/12/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
207	02/12/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
208	02/12/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
209	02/12/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
210	02/12/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/16 17:33	TP ESTIMATE - MARKED	 Load PDF	
2	14/03/16 17:33	TP GIA REPORT	 Load PDF	
3	14/03/16 17:42	Singapore Accident Statement	 Load PDF	
4	16/03/16 16:36	Letter to OI	 Load PDF	
5	02/12/19 08:03	RENTAL RECEIPT	 Load PDF	
6	02/12/19 08:03	LTA SEARCH	 Load PDF	
7	06/12/19 09:45	WORKSHOP INVOICE	 Load PDF	
8	06/12/19 09:45	AUTHORISATION TO ACT FORM	 Load PDF	
9	06/12/19 09:45	Release Voucher	 Load PDF	
10	06/12/19 09:45	LOD	 Load PDF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008  
(PAYMENT BREAKDOWN)**

Vehicle No:	SGX5194G (Insd veh)	Model:	HONDA ODYSSEY 2.4 (A)
	SJF4440L (TP veh)		
Date of Accident:	11/03/2016		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	35,239.38
Final Repair Cost	:	\$	21,750.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	13 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	21,750.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <b>Non GIA Registered Workshop</b> :		Agreed Liability _____100_____ (%)	
B) For <b>GIA Registered Workshop</b> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____100_____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Em-1 Auto Pte Ltd	:	\$ 21,750.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN  
\_\_\_\_\_  
LKK Auto Consultants Pte Ltd

06 Dec  
2019  
\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG16004803/M1PA3Q2

Date: 06/12/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100038674  
**Claimant**  
**Vehicle No :** SJF4440L **Insured Vehicle No :** SGX5194G  
**Date of Loss:** 11/03/2016 **Nature of Claim:** TP **Claim No:** 4387491972SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJF4440L**  
 Make & Model: HONDA ODYSSEY, 2.4 (A) Engine No: HIDDEN  
 Reg. Date: 29/05/2008 (Man. Year: 2008) Chassis No: JHMRB18508C203479  
 Colour: Grey Odometer: 117811 km  
 Engine Capacity: 2354 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/55R17 Rear Tyre Size: 215/55R17  
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm  
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,794.00	17,156.00	8,638.00	33.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,140.00	6,050.00	1,090.00	15.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>32,934.00</b>	<b>23,206.00</b>	<b>9,728.00</b>	<b>29.54</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>18,500.00</b>		
(S\$)	32,934.00	18,500.00	14,434.00	43.83
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,305.38</b>	<b>1,295.00</b>	<b>1,010.38</b>	<b>43.83</b>
<b>Nett Amount (S\$)</b>	<b>35,239.38</b>	<b>19,795.00</b>	<b>15,444.38</b>	<b>43.83</b>
<b>+ Car Rental (13.0 x S\$150.00/day) (S\$)</b>		1,950.00		
<b>+ Doc/Search Fee (S\$)</b>		5.35		
<b>Nett Liability (S\$)</b>		<b>21,750.35</b>		
<b>Global Sum Settlement (S\$)</b>		<b>21,750.00</b>		

## INSPECTION

Date of Assignment: 11/03/2016  
 Date Inspected: 11/03/2016 Inspected At: Em-1 Auto Pte Ltd (HQ)  
 Blk 8 Sin Ming Industrial Estate Sector  
 C, #01-68  
 Singapore 575643

Estimated Period of Repair: 15.0 days

---

**Adjuster:** MA CHIN FOOK

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,056.00 FL	*1,056.00 FL
2	1		*TAILGATE BADGE	Necessary	48.00 FL	*48.00 FL
3	1		*TAILGATE OUTER CHROME MOULDING	Distorted	256.70 FL	*256.70 FL
4	1		*SET TAILGATE OUTER CHROME MOULDING CLIPS	Necessary	40.00 FL	*40.00 FL
5	1		*TAILGATE LAMPS	N/S Distorted / O/S Serviceable	1,121.80 FL	*560.90 FL
6	2		*TAILGATE LAMPS INNER SEALER	Necessary	60.00 FL	*40.00 FL
7	2		*SET TAILGATE LAMPS CLIPS	Necessary	40.00 FL	*30.00 FL
8	1		*TAILGATE OUTER GARNISH	Distorted	694.40 FL	*694.40 FL
9	1		*SET TAILGATE OUTER GARNISH CLIPS	Necessary	40.00 FL	*40.00 FL
10	2		*TAILGATE NUMBER PLATE LAMP	Cracked	92.00 FL	*92.00 FL
11	1		*TAILGATE OPENER HANDLE	Distorted	62.20 FL	*62.20 FL
12	1		*TAILGATE POCKER HANDLE	Serviceable	42.60 FL	*- FL
13	1		*TAILGATE STOPPER	N/S Missing	36.00 FL	*18.00 FL
14	1		*TAILGATE INNER TRIM	Distorted	328.00 FL	*328.00 FL
15	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	40.00 FL	*40.00 FL
16	1		*TAILGATE WEATHERSTRIP	Distorted	165.90 FL	*165.90 FL
17	1		*TAILGATE INNER LOCK	Bent	175.50 FL	*175.50 FL
18	1		*TAILGATE AUTO LOCK ACTUATOR	Shorted	156.20 FL	*156.20 FL
19	1		*TAILGATE LOCK CATCH	Bent	36.00 FL	*36.00 FL
20	2		*TAILGATE ABSORBER	Serviceable	384.00 FL	*- FL
21	2		*TAILGATE HINGES	Repair	112.00 FL	*- FL
22	1		*REAR WINDSCREEN MOULDING	Necessary	93.00 FL	*93.00 FL
23	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FL	*40.00 FL
24	1		*TAILLAMPS	N/S Cracked / O/S Serviceable	1,504.00 FL	*752.00 FL
25	2		*TAILLAMPS INNER SEALER	Necessary	60.00 FL	*40.00 FL
26	2		*SET TAILLAMP CLIPS	Necessary	50.00 FL	*30.00 FL
27	1		*TAILLAMP PANEL LH	Bent	159.20 FL	*159.20 FL
28	1		*REAR BUMPER	Deformed	892.00 FL	*892.00 FL
29	1		*REAR BUMPER SCREW COVER (4PCS)	Missing (1Pc Only)	48.00 FL	*12.00 FL
30	2		*REAR BUMPER SIDE RETAINERS	Distorted	78.00 FL	*78.00 FL
31	2		*REAR BUMPER ATTACHMENT RETAINERS	Distorted	72.00 FL	*72.00 FL
32	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
33	1		*REAR BUMPER TOW COVER	Distorted	29.00 FL	*29.00 FL
34	1		*REAR BUMPER REFLECTORS	Missing	65.00 FL	*65.00 FL
35	1		*REAR BUMPER TOP BEAM	Bent	97.20 FL	*97.20 FL
36	1		*REAR BUMPER REINFORCEMENT	Bent	132.20 FL	*132.20 FL
37	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Bent	70.20 FL	*70.20 FL
38	1		*END PANEL	Bent	563.50 FL	*563.50 FL
39	1		*SET END PANEL TOP TRIM	Distorted	123.00 FL	*123.00 FL
40	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FL	*30.00 FL
41	1		*SPARE TYRE PANEL	Buckled	1,118.50 FL	*1,118.50 FL
42	1		*SPARE TYRE PANEL SIDE PANEL LH	Bent	256.50 FL	*256.50 FL
43	1		*SPARE TYRE PANEL TOP BOARD	Distorted	360.00 FL	*360.00 FL
44	1		*SPARE TYRE WHEEL NUT	Serviceable	46.00 FL	*- FL
45	2		*REAR CHASSIS FRAME MEMBER	Serviceable	1,600.00 FL	*- FL
46	1		*REAR FENDER INNER TRIM	N/S Distorted	976.00 FL	*488.00 FL
47	2		*SET REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FL	*60.00 FL

Report was unsubmitted during this print-out.
---

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		*REAR FENDER INNER TRIM TOOL BOX COVER LH	Cut	79.60 FL	*79.60 FL
49	1		*REAR FENDER INNER SHIELD	N/S Distorted / O/S Serviceable	210.00 FL	*105.00 FL
50	2		*SET REAR FENDER INNER SHIELD CLIPS	Necessary	50.00 FL	*40.00 FL
51	1		*REAR EXHAUST SILENCER RH	Serviceable	972.60 FL	*- FL
52	1		*REAR EXHAUST SILENCER LH	Bent	595.00 FL	*595.00 FL
53	4		*REAR EXHAUST MOUNTINGS	Distorted	152.00 FL	*152.00 FL
54	2		*REAR EXHAUST GASKET	Necessary	90.00 FL	*90.00 FL
55	1		*REAR EXHAUST HEAT PLATE	N/S Buckled /O/S Serviceable	156.00 FL	*78.00 FL
56	1		*REAR ABSORBER LH	No Damage	501.00 FL	*- FL
57	1		*REAR UPPER ARM LH	No Damage	146.20 FL	*- FL
58	1		*REAR LOWER ARM LH	Bent	351.00 FL	*351.00 FL
59	1		*REAR KNUCKLE ARM LH	No Damage	395.00 FL	*- FL
60	1		*REAR WHEEL BEARING LH	No Damage	362.90 FL	*- FL
61	1		*ANTI ROLL BAR	No Damage	153.00 FL	*- FL
62	2		*ANTI ROLL BAR BUSH	No Damage	58.00 FL	*- FL
63	1		*ANTI ROLL BAR LINK LH	No Damage	95.00 FL	*- FL
64	1		*REAR CROSS MEMBER	No Damage	881.00 FL	*- FL
65	1		*BONNET	Buckled	816.00 FL	*816.00 FL
66	1		*BONNET RUBBER (INNER)	Not Necessary	26.00 FL	*- FL
67	1		*BONNET RUBBER (OUTER)	Not Necessary	26.00 FL	*- FL
68	2		*BONNET SIDE RUBBER	Not Necessary	44.00 FL	*- FL
69	1		*SET BONNET RUBBER CLIPS	Necessary	20.00 FL	*20.00 FL
70	1		*BONNET INNER LOCK	Bent	97.20 FL	*97.20 FL
71	1		*SET BONNET INSULATOR CLIPS	Necessary	40.00 FL	*40.00 FL
72	1		*FRONT GRILLE	Distorted	263.30 FL	*263.30 FL
73	1		*FRONT GRILLE BADGE	Necessary	48.00 FL	*48.00 FL
74	1		*FRONT GRILLE TOP CHROME MOULDING	Distorted	93.60 FL	*93.60 FL
75	1		*FRONT GRILLE CENTER CHROME MOULDING	Distorted	142.20 FL	*142.20 FL
76	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FL	*30.00 FL
77	2		*HEADLAMPS	Cracked	1,584.00 FL	*1,584.00 FL
78	2		*HEADLAMPS BOTTOM RETAINERS	Distorted	98.00 FL	*98.00 FL
79	2		*SET HEADLAMP CLIPS	Necessary	40.00 FL	*40.00 FL
80	1		*FRONT BUMPER	Deformed	816.00 FL	*816.00 FL
81	2		*FRONT BUMPER SIDE RETAINERS	Distorted	76.00 FL	*76.00 FL
82	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
83	2		*FRONT BUMPER FOG LAMPS WITH COVERS	Serviceable	1,481.80 FL	*- FL
84	1		*FRONT BUMPER REINFORCEMENT	Dented	291.00 FL	*291.00 FL
85	1		*FRONT BUMPER LOWER GRILLE	Distorted	126.20 FL	*126.20 FL
86	1		*ENGINE UNDER COVER	Cracked	112.00 FL	*112.00 FL
87	1		*SET ENGINE UNDER COVER CLIPS	Necessary	30.00 FL	*30.00 FL
88	1		*SET HORNS	No Damage	120.00 FL	*- FL
89	1		*SUPPORT PANEL	Bent	539.60 FL	*539.60 FL
90	1		*AIR CON CONDENSER	Dented	890.00 FL	*890.00 FL
91	1		*CONDENSER AIR CON PIPE	Bent	390.30 FL	*390.30 FL
92	1		*CONDENSER SUCTION PIPE	Dented	219.50 FL	*219.50 FL
93	1		*CONDENSER DISCHARGE PIPE	Bent	236.00 FL	*236.00 FL
94	1		*RADIATOR	Dented	1,436.90 FL	*1,436.90 FL
95	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
96	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
97	1		*BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*80.00 FS
98	1		*REAR FLOOR PANEL INSULATOR PAD	Necessary	150.00 FS	*120.00 FS
99	4		*REVERSE SENSOR	Shorted	450.00 FS	*350.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
100	1		*REAR EXHAUST CHROME PIPE N/S	Bent	140.00 FS	*120.00 FS
101	1		*SPARE TYRE	Serviceable	250.00 FS	*- FS
102	1		*SPARE TYRE RIM	Serviceable	320.00 FS	*- FS
103	1		*RADIATOR COOLANT	Necessary	40.00 FS	*40.00 FS
104	1		*FRONT NUMBER PLATE WITH COVER	Bent	70.00 FS	*40.00 FS
105	1		*FRONT BUMPER LOWER SPOILER	Distorted	950.00 FS	*800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>31,592.50</b>	<b>21,037.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>5,798.50</b>	<b>3,881.50</b>
<b>Total Parts (\$\$)</b>	<b>25,794.00</b>	<b>17,156.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,600.00	2,400.00
2	SPRAY PAINTING	New	2,500.00	2,200.00
3	CHECK WIRING	New	100.00	30.00
4	ANTI RUST	New	180.00	150.00
5	TOWING FEES	New	70.00	70.00
6	REMOVE AND INSTALL REAR WINDSCREEN	New	140.00	120.00
7	REMOVE AND INSTALL TAILGATE PARTS	New	90.00	60.00
8	REMOVE AND INSTALL CARPET AND SEATS	New	120.00	80.00
9	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	80.00
10	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	150.00	120.00
11	REMOVE AND INSTALL PETROL TANK	New	90.00	80.00
12	REMOVE AND INSTALL REAR UNDERCARRIAGE	New	450.00	180.00
13	TO PERFORM COMPUTERIZE WHEEL ALIGNMENT	New	90.00	80.00
14	TO JACK AND ALIGNMENT CHASSIS FRAME MEMBER	New	320.00	280.00
15	REMOVE AND INSTALL AIR CON	New	150.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>7,140.00</b>	<b>6,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >