

INS. CASE OWNER:

CC 4 / AXA1600

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:


REF: AYA

ASSIGNMENT

From: _____ Date: 21/03/06
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKD 1190A
 at Workshop m/s Ming Wah
 of 816 10 Bank Road Park SA 40305
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 830k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 06 days Res: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS wp.

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKD 1190A Yr Regn: 04, 07
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic c.c. 1998
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 144425 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHMF026407S200796

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>7</u> mm	R/Bal. <u>8</u> mm
L/Bal. <u>7</u> mm	L/Bal. <u>8</u> mm
D.O.A. <u>18/3/16</u>	D.O.I. <u>21/3/16</u>

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/3 for pass to Ashby

215 # 29w (Red # 95787 974)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos

Others

TOTAL

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC4/AXA16005162/Kpa3		
8 SHENTON WAY #27-01SINGAPORE 068811		Date : 18-03-2016		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKP 9574L	Veh. Inspected	SKD 1690A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/03/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/03/2016	Inspection Date		
Survey held at	MENG WHEE BROS MOTOR SERVICE BLK 10 ANG MO KIO IND PARK 2A #05-25 SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Meng Whee Bros Motor Service

BLK 10 ANG MO KIO IND PARK 2A #05-25

AMK AUTOPOINT SINGAPORE 568047

TEL:64846330 FAX:64846331

Not Authorised
Uly B?
Resurvey After Paint
Kenneth 96910863

M/S :

Axa

Attn: motor claim dept.

TP estimate

vehicle no : SKD1690A

INVOICE NO:

Q16010

Date:

24/12/2014

QTY	DESCRIPTION	UNIT PRICE	AMOUNT
1	Rear boot bonnet <i>530.20 738.50</i>	<i>Per</i> \$960.00	✓
1	Rear boot lock	<i>R</i> \$295.00	✓
1	Rear boot logo <i>52.40</i>	<i>Per</i> \$120.00	✓
1	Rear boot emblem Civic	<i>Per</i> \$85.00	✓
1	Rear boot emblem 2.0 <i>40.80</i>	<i>Per</i> \$48.00	✓
1	Rear boot emblem i-vtec <i>45.70</i>	<i>Per</i> \$135.00	✓
2	Rear boot lamp <i>C 160.20</i>	<i>split for</i> \$880.00	✓
10	Insulator clips	<i>Per</i> \$50.00	✓
2	Rear boot hinges	<i>R</i> \$360.00	✓
2	Rear boot hinges garnish	<i>Per</i> \$320.00	✓
1	Rear boot wheatherstrips <i>175.20</i>	<i>Both</i> \$380.00	<i>508.50</i>
1	Rear boot inner lock	<i>R</i> \$295.00	✓
1	Rear end panel <i>269.50</i>	<i>Per</i> \$880.00	✓
1	Rear spare tyre panel	<i>R</i> \$990.00	✓
2	Taillamp retainer	<i>Per</i> \$160.00	✓
1	Tail lamp <i>240.50</i>	<i>Per</i> \$380.00	✓
1	Rear end panel garnish <i>78.20 78.50</i>	<i>CR</i> \$280.00	✓
1	Rear bumper <i>638.00</i>	<i>Per</i> \$840.00	✓
1	Reverse sensor	<i>Shut</i> \$220.00	✓
2	Side retainer	<i>Per</i> \$120.00	✓
12	Bumper clips	<i>Per</i> \$60.00	✓
1	Rear exhaust muffle	<i>Per</i> \$1,200.00	✓
1	Rear exhaust chrome	<i>Per</i> \$280.00	✓
1	Rear number plate w/case	<i>Per</i> \$60.00	✓
	Chassis aligner	<i>Per</i> \$380.00	✓
	To remove and refit rear boot bonnet, bumper, rear end panel, lamp, cut and weld spare tank etc and straighten rear chassis.	\$1,200.00	<i>600</i>
	To check rear wiring system	\$120.00	<i>200</i>
	To respray antirust on affected area	\$180.00	<i>600</i>
	To apply putty, primer and respray paint on damaged section	\$1,200.00	<i>7200</i>

Total

\$12,478.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua

Date: 22 Mar 2016

Preliminary Advice

Insured Vehicle No	: SKP9574L	Accident Date	: 18/03/2016
TP Vehicle No	: SKD1690A	Assignment Date	: 18/03/2016
Make	: HONDA CIVIC	Est. Duration of Repair	: 6 days
Date of Inspection	: 21.03.2016		
Inspection At	Meng Whee Bros Motor Service (HQ) 10 Ang Mo Kio Industrial Park 2A, #05-25, AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,478.00
Revised Amount	:S\$	5,548.40
Check Items (Estimated)	:S\$	1,480.00
Total	:S\$	7,028.40

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

Hsiao Tong

From: Hsiao Tong
Sent: Monday, 11 April, 2016 8:29 AM
To: 'walice@clerical.com.sg'
Subject: ACCIDENT INVOLVING SKP 9574L AND SKD 1690A ALONG/AT CLEMENTI AVE 6 ON 18/03/2016

OUR REF : CC4/AXA16005162/Kpa3
YOUR REF : GA011218 (SKP 9574L)

Dear Sirs,

ACCIDENT INVOLVING SKP 9574L AND SKD 1690A ALONG/AT CLEMENTI AVE 6 ON 18/03/2016

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Meng Whee Bros Motor Service acting on behalf of the owner of SKD 1690A against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

11 APRIL 2016

SENG FA PILING PTE LTD

105 SIMS AVE
#05-10 CHANCERLODGE COMPLEX
SINGAPORE 387429
ATTN: THE MANAGEMENT

Dear Sir/ Mdm

OUR REF : CC4/AXA16005162/Kpa3
YOUR REF : GA011218 (SKP 9574L)
ACCIDENT INVOLVING SKP 9574L AND SKD 1690A ALONG/AT CLEMENTI AVE 6
ON 18/03/2016

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Meng Whee Bros Motor Service acting on behalf of the owner of SKD 1690A against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely



Chew Hsiao Tong
Case Handler
DID: 6742 3197
FAX: 6741 4108
EMAIL: chewht@lkkauto.com

Cc AXA Insurance Singapore Pte Ltd
(Motor Claims Dept)

Print Sent Message

This mail is associated with :

***SKD1690A (C0376143)**
[SKP9574L]

TP

SEAH WEI PIN

Mar 18 2016 9:00AM

[SENG FA PILING PTE LTD]

Meng Whee Bros Motor Service

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 01/11/2018 11:28 AM.
To Kianchuan.chan@axa.com.sg
CC AXA_SG; chewht@lkkauto.com
Subject <Seek Mandate> C0376143/ GA011218

Hi,

We refer to the above matter.

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue.

We seek your mandate up to \$5,170.00(all-in). IA with mandate had been uploaded in Merimen.

Kindly let us have your approval/instruction.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197



Auto
Consultants
Pte Ltd

Company Registration No. 199607198H

81 CUBAVE L, #02-25 PAYA LEBI INDUSTRIAL PARK, SINGAPORE 409033 TEL : (065) 62563561 FAX : (065) 62564115

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 01.11.2018

Survey Details:

Date of loss	18.03.2016
Date of appointment	18.03.2016
Date of survey	21.03.2016
Location of survey	MENG WHEE BROS MOTOR SERVICE

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKD 1690A
Make and Model	Renault Latitude (1995cc)
Date of registration	Apr-07
Excess	NIL
Market Value/ Book Value	(est)
Parf/COE Rebate	(est)
Nett Loss	(est)

X Honda (car)
OK

?

Repair details:

Initial Estimate	\$ 12,478.00
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 4,148.40
Check items (estimate)	NIL
Labour	\$ 1,400.00
Supplementary	
Total	\$ 5,548.40
Lump Sum(if applicable)	\$ 4,450.00

Number of days for repair	<u>6</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date:

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 4,450.00	
Loss of use	\$ 720.00	(8days x \$90.00)
Loss of rental	NIL	
Loss of income	NIL	
LTA/GIA search fees	NIL	
Others	NIL	
Proposed Total	\$ 5,170.00	

Print Received Message

This mail is associated with :

***SKD1690A (C0376143)**

[SKP9574L]

TP

SEAH WEI PIN

Mar 18 2016 9:00AM

[SENG FA PILING PTE LTD]

Meng Whee Bros Motor Service

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 14/11/2018 09:04 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SKD1690A - Claim Handler: Chan Kian Chuan

Approved:0.00:LIAB CLEAR, ERROR IN IA MANDATE, TPV MODEL WRONG, MISSING MV, MISSING NETT LOSS, PLS
MAKE SURE ALL INFORMATION IS ACCURATE BEFORE SEEKING MANDATE.



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/03/2019

Survey Details:

Date of loss	18.03.2016
Date of appointment	18.03.2016
Date of survey	21.03.2016
Location of survey	MENG WHEE BROS MOTOR SERVICE

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKD 1690A
Make and Model	Honda Civic (1998cc)
Date of registration	Apr-07
Excess	NIL
Market Value/ Book Value	\$ 30,000.00 (est)
Parf/COE Rebate	(est)
Nett Value/ ERV	(est)

Repair details:

Initial Estimate	\$ 12,478.00
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 4,148.40
Check items (estimate)	NIL
Labour	\$ 1,400.00
Supplementary	NIL
Total	\$ 5,548.40
Lump Sum(if applicable)	\$ 4,450.00

Number of days for repair	<u>6</u>
---------------------------	----------



Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 4,450.00	
Loss of use	\$ 720.00	(8days x \$90.00)
Loss of rental	NIL	
Loss of income	NIL	
LTA/GIA search fees	NIL	
Others	NIL	
Proposed Total	\$ 5,170.00	

...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Mar 2016		18 Mar 2016 16:59 Edit Adj Rpt	S\$2,900.00 Edit Estimates	S\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SENG FA PILING PTE LTD. Co. Reg. No.: 201220369E, Tel: +6593367995								
Main Claimant:	SEAH WEI PIN. ID: S8539534C								
Vehicle Reg. No.:	SKD1690A	Date of Loss:	18/03/2016 09:00 - :59 [107 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0376143	Policy/Cover Note No.:	GA011218 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKP9574L	Policy No. (Claimant):	DMPCSN3063061500						
		Excess:	S\$0.00						
Repairer:	Meng Whee Bros Motor Service (HQ) 10 Ang Mo Kio Industrial Park 2A, #05-25, AMK Autopoint, 568047 Ang Mo Kio - Tel: 6484 6330								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Khor Saw Theng - 6880 4754]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/03/2016]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (14/11/2018): Alert - Adj Mandate Approved (S\$0.00) - SKD1690A - Claim Handler: Chan Kian Chua... AXA_SG (02/07/2018): Re: Direct Settlement - Accident Involving SKP9574L (OI: AXA - C0376143) and SK... AXA_SG (30/03/2016): Re: Direct Settlement - Accident Involving SKP9574L (OI: AXA - C0376143) and SK... AXA_SG (30/03/2016): TP settlement - C0376143/GA011218 AXA_SG (18/03/2016): WP / New TP Assignment - C0376143/GA011218 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKD1690A (C0376143)**
[SKP9574L]
TP
SEAH WEI PIN
Mar 18 2016 9:00AM
[SENG FA PILING PTE LTD]
Meng Whee Bros Motor Service

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print		
1	30/03/16 11:05	Accident Statement From: SC - Reg. No: SKP9574L, Claimant: SENG FA PILING PTE LTD	1	Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	22/03/16 11:11	Adjuster Immediate Advice	1	Load HTM			
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print		
1	18/03/16 16:31	EMAIL_ABS	1	Load PDF			
2	18/03/16 16:31	SKD1690A GIA (TP) & ESTIMATE_ABS MENG HWEE BROS: \$12,478	1	Load PDF			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	22/03/16 10:39	LKK INSPECTION Photos	1	Load PDF			
2	11/04/16 08:46	Letter to OI	1	Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16005162/KPA3Q2

Date: 22/03/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA011218

Claimant Vehicle No : SKD1690A

Insured Vehicle No :

SKP9574L

Date of Loss: 18/03/2016

Nature of Claim:

TP

Claim No: C0376143

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKD1690A

Make & Model: HONDA CIVIC, 2.0 (A)

Engine No: HIDDEN

Reg. Date: 01/04/2007 (Man. Year: 2007)

Chassis No: JHMF26407S200796

Colour: Black

Odometer: 144425 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 8 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,398.00	2,367.04	7,030.96	74.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,400.00	1,680.00	54.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,478.00	3,767.04	8,710.96	69.81
Approved Total (Overridden) (S\$)		2,900.00		
Nett Amount (S\$)	12,478.00	2,900.00	9,578.00	76.76
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 18/03/2016

Date Inspected: 21/03/2016 Inspected At:

Meng Whee Bros Motor Service (HQ)
10 Ang Mo Kio Industrial Park 2A, #05-25,
AMK Autopoint
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2019)
Parts: 143	HONDA CIVIC 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKD1690A)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT BONNET (CONSISTENT)	Buckled	960.00 F	*738.50 FL
2	1		*REAR BOOT LOCK (CONSISTENT)	Repair	295.00 F	*- FL
3	1		*REAR BOOT LOGO (CONSISTENT)	Necessary	120.00 F	*52.40 FL
4	1		*REAR BOOT EMBLEM CIVIC (CONSISTENT)	Necessary	85.00 F	*85.00 FL
5	1		*REAR BOOT EMBLEM 2.0 (CONSISTENT)	Necessary	48.00 F	*40.80 FL
6	1		*REAR BOOT EMBLEM I-VTEC (CONSISTENT)	Necessary	135.00 F	*45.70 FL
7	2		*REAR BOOT LAMP (CONSISTENT)	Scratched / Cut	880.00 F	*320.40 FL
8	10		*INSULATOR CLIPS (CONSISTENT)	Not Necessary	50.00 F	*- FL
9	2		*REAR BOOT HINGES (CONSISTENT)	Repair	360.00 F	*- FL
10	2		*REAR BOOT HINGES GARNISH (CONSISTENT)	Serviceable	320.00 F	*- FL
11	1		*REAR BOOT WHEATHERSTRIPS (50%) (CONSISTENT)	Buckled / Dented	380.00 FS	*87.60 FS
12	1		*REAR BOOT INNER LOCK (CONSISTENT)	Repair	295.00 F	*- FL
13	1		*REAR END PANEL (CONSISTENT)	Buckled	880.00 F	*269.50 FL
14	1		*REAR SPARE TYRE PANEL (CONSISTENT)	Repair	990.00 F	*- FL
15	2		*TAILLAMP RETAINER (CONSISTENT)	Serviceable	160.00 F	*- FL
16	1		*TAIL LAMP (CONSISTENT)	Cut	380.00 F	*240.50 FL
17	1		*REAR END PANEL GARNISH (CONSISTENT)	Cracked	280.00 F	*78.50 FL
18	1		*REAR BUMPER (CONSISTENT)	Bent	840.00 F	*638.00 FL
19	1		*REVERSE SENSOR (CONSISTENT)	Shorted	220.00 F	*220.00 FL
20	1		*SIDE RETAINERS (CONSISTENT)	O/S Distorted	120.00 F	*60.00 FL
21	12		*BUMPER CLIPS (CONSISTENT)	Necessary	60.00 F	*60.00 FL
22	1		*REAR EXHAUST MUFFLE (CONSISTENT)	Not Necessary	1,200.00 F	*- FL
23	1		*REAR EXHAUST CHROME (CONSISTENT)	Not Necessary	280.00 F	*- FL
24	1		*REAR NUMBER PLATE W/CASE (CONSISTENT)	Serviceable	60.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	9,398.00	2,936.90
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	569.86

Total Parts (S\$)	9,398.00	2,367.04
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHASSIS ALIGNMENT	New	380.00	0.00
2	TO REMOVE AND REFIT REAR BOOT BONNET ,BUMPER ,REAR END PANEL,LAMP ,CUT AND WELD SPARE TANK ETC AND STRAIGHTEN REAR CHASSIS	New	1,200.00	600.00
3	TO CHECK REAR WIRING SYSTEM	New	120.00	20.00
4	TO RESPRAY ANTIRUST ON AFFECTED AREA	New	180.00	60.00
5	TO APPLY PUTTY,PRIMER AND RESPRAY PAINT ON DAMAGED SECTION	New	1,200.00	720.00
Gross Labour Cost (S\$)			3,080.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >