

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 9893A - AXA

ROEL

Not Authorised
17B.1
81852.73
Resurvey B4 part

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB 9893A - ROEL
VF1ABL15AUC273423
RENAULT
LATITUDE
14.04.16
AXA

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>Bu</i> 968.78 —
2	1	BUMPER ABSORBER FRT	\$	<i>Sm</i> 303.60 X
3	1	BUMPER BEAM FRT	\$	<i>R</i> 703.14 X
4	1	BUMPER SPOILER FRT	\$	<i>Sm</i> 139.81 X
5	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sm</i> 159.40 X
6	1	BUMPER RETAINER FRT RH	\$	<i>Dis</i> 116.47 —
7	1	BUMPER SUPPORT FRT RH	\$	<i>Sm</i> 18.37 X
8	1	WIPER RESERVOIR	\$	<i>Sm</i> 173.60 X
9	1	WIPER RESERVOIR MOTOR	\$	<i>Sm</i> 91.78 X
10	1	HEADLAMP RH	\$	<i>Sm</i> 911.10 X
11	1	FENDER PANEL FRT RH	\$	<i>R</i> 602.95 X
12	1	FENDER WHEELARCH FRT RH	\$	<i>R</i> 107.33 X
TOTAL			\$	4,296.34
10%			\$	429.63
			\$	3,866.70

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	<i>Ac</i> 66.00 —
2	1SET	WHEELARCH CLIP RH	\$	<i>nn</i> 66.00 X
3	1	TOW COVER FRT	\$	<i>Sm</i> 14.50 X
4	1	CAP HUB RH FRT	\$	<i>Sm</i> 35.00 X
5	1	RIM RH FRT	\$	<i>Sm</i> 385.00 X
6	1	TYRE RH FRT	\$	<i>Sm</i> 330.00 X
7	1SET	BUMPER SUPPORT FRT CLIP RH	\$	<i>nn</i> 9.80 X
8	1SET	BUMPER RETAINER FRT CLIP RH	\$	<i>nn</i> 12.50 X
TOTAL			\$	918.80
TOTAL PARTS			\$	4,785.50

Panel beating, knocking and straightening the
 necessary portion, remove and renewal of
 parts, adjust and realign the same

\$ 1,400.00 *3rd*

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 9893A - AXA

To Check Electrical Lighting Concerned.	\$	170.00	10/
Putty and spray painting of the affected portion.	\$	1,500.00	440/
To check steering geometry and computer wheel alignment	\$	220.00	60/
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To rust-proofing of the affected areas.	\$	170.00	nn X

TOTAL	\$	3,630.00
Over All Total	\$	8,415.50

(PARTS BY PARTS) Repair Days**5 Days**

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: