

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7912S - LONPAC

Done 19/11/16 Not Attached
6/1/17 & 1/8/00p
Candy

Vehicle No.:

SHB 7912S - Candy

Chassis No.:

KL1LA69RJBB097405

Vehicle Make:

CHEVROLET

Vehicle Model:

CHEVROLET EPICA 2.0

Date of Accident :

16.04.16

Third Party Insurer :

LONPAC

		PART	LIST	
1	1	Rear Fender RH	\$	<i>R</i> 1,145.00 X
2	1	Rear Fender Inner Cowling RH	\$	<i>Sm</i> 298.00 X
3	1	Rear Fender Inner Trim RH	\$	<i>Sm</i> 418.44 X
4	1	Rear Tail Lamp RH	\$	<i>Br</i> 479.30 ✓
5	1	Rear Bumper	\$	<i>Del/Dry</i> 1,202.00 ✓
6	1	Rear Bumper Side Retainer RH	\$	<i>Dis</i> 68.76 ✓
7	1	Rear Bumper Reflectors RH	\$	<i>Sm</i> 119.74 X

TOTAL	\$	3,731.24
10%	\$	373.12
	\$	3,358.12

Specical Nett

1	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 35.00 ✓
2	1	Rear Tyre RH	\$	<i>Sm</i> 360.00 X
3	1	Rear Wheel Rim RH	\$	<i>Sm</i> 254.00 X
4	2	Rear Windscreen Sealant	\$	<i>nn</i> 80.00 X
5	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00 X
6	1	Rear Fender Inner Trim Clip	\$	<i>nn</i> 30.00 X
7	1Set	Rear Parking Sensor	\$	<i>nn</i> 300.00 X

TOTAL	\$	1,159.00
TOTAL PARTS	\$	4,517.12

Panel Beating, Knocking And Straightening The
 Necessary Portion, Remove And Renewal Of
 Parts, Adjust And Realign The Same

\$ 2,800.00 *2000*

To Rust-Proofing Of The Affected Areas.

\$ *nn* 220.00 X

TRANS-CAB AUTO SERVICES PTE LTD**Candy**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7912S - LONPAC

Putty and Spray Painting Of The Affected Portion.	\$	2,700.00 <i>4001</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 <i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>

TOTAL	\$	6,400.00
Over All Total	\$	10,917.12

REPAIR DAYS**~~10~~ DAYS**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before *after* spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: