

INS. CASE OWNER:

Gerald.

CC 6-LPC1600

7269, Aug 3 02

LKK:
IDAC:

LIAB/LITY

Surveyor:

Adrian

DOI:

ASSIGNMENT

30/10/16

Date / Time:

20/10/16

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

C7BD1036

Name of Insured:

My Building & Maintenance Service Pte Ltd.

Insured Tel No.:

62416559

HP:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

15/16/16/VCO0/01060

2/15/VCO0/09290

Mitsubishi Canter FEA01BR1 SDEB(COU)

Tengah Merah coast Rd changi
Wedge Entrance (Bkt)

Excess Sec II :SS

D.O.A.:

8/1/16

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Hong Kim Xing

Driver Tel No.:

86068841

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

PA 9175A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Tan Kim



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

20/10/16
AdrianPA 9175A - C 6-LPC1600 62416559 / 8/1/16
C7BD1036 - C 6-LPC1600 62416559 / 8/1/16

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: LWP

Repair Cost:

43

S\$ 3,600

(

4

days)

Reduction:

55

%

Email

Call

FINAL SETTLEMENT

Date/Time: 13.06.19

Confirm with JOHNSON

Email

Call

Final Liability:

100

% 50

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost: 10/16/16: +3850.00

S\$ 1,936.00

CONFLICTING VERSION.

Loss of Rental (LOR):

-

S\$ -

(

days)

Loss of Use (LOU): +750

S\$ 375.00

(\$150

x 5

days)

Loss of Income (LOI):

-

S\$ -

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search: +5.35

S\$ 5.35

Medical:

-

S\$ -

Disbursement:

-

S\$ -

Legal Cost

-

S\$ -

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

450

Total:

+4,601.35

S\$ 2,306.35

Global Sum S\$:

FINAL PAYMENT

Date/Time: 13.06.19

Confirm with: JOHNSON

Email

Call

Payee 1:

S\$ 2,306.35

Name 1:

TAN LIM MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 1 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No**CA / REV / REP. / 24 HRS**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PA917SA Yr Regn: 2010 / Jan.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yutong c.c. 6693Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 463640 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LZYTBT06991019746

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/80 R22-5R: 295/80 R22-5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 20/04/16Survey held at Ten LimDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Lon Pac</u>
	<u>451 + 3600 (RSD: + 4,317.50 55%)</u>

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$) _____

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC6/LPC16007269/Aug3		
100 BEACH ROAD #19-00 SHAW TOWERS SINGAPORE 189702		Date : 20-04-2016		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 103S	Veh. Inspected	PA 9175A	
Policy No.	Z/15/VC00/09290B	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	20/04/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/04/2016	Inspection Date	20/04/2016	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Lonpac Insured's Veh No : GBD103S

Date of Accident : 08 April 2016

Messrs Ang Mo Kio North Bus Service

Date : 08 April 2016

Req: 20/04 @ 1225L
IKK @ Adrian

Estimate To Repair PA9175A - Yutong ZK6100H

Chassis No : LZYTBD6991019746

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	n/s rear wheel mudguard <i>Disltd</i>	\$ 1,919.42 <i>1200.00</i>
02	1 pc	n/s rear wheel hub cap <i>int</i>	\$ 459.89 <i>180.00</i>
03	1 pc	n/s side compartment door <i>Disltd</i>	\$ 994.79 ✓
04	1 pc	n/s side compartment door indication lamp <i>Disltd</i>	\$ 89.79 ✓
		Less 10 %	\$ 3,463.89
			\$ 346.39
			\$ 3,117.50
		<u>LABOUR & MISC. CHARGES</u>	
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,500.00 <i>1000</i>
02		Putty and spray painting of the affected portion.	\$ 1,300.00 <i>700</i>
03		To redo graphic colour sticker	\$ 2,000.00 <i>800</i>
			\$ 4,800.00
		Total	\$ 7,917.50

total: 4556.12

HS: 3.6K

L/S Adrian

20/04/16

OK Days

List: 976.12

S. New: 1,380.00

Labour: \$1,700.00

4,056.12

20%

7,244.89

7 3,200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC16007269/Aeb3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 01-07-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 103S	Veh. Inspected	PA 9175A
Policy No.	Z/15/VC00/092908	Coverage (\$)	0.00
Claim No.	15/16/16/VC00/018609	Excess (\$)	0.00
Assign From	GERALD	Assign Date	20/04/2016

2. Vehicle Particulars & Condition

Make & Model	YUTONG	c.c	6693
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	LZYTBD6991019746	Colour	GREY
Odometer	463640	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	TRIANGLE	6 mm
L/H Front Tyre	295/80 R22.5	TRIANGLE	6 mm
R/H Rear Tyre	295/80 R22.5	TRIANGLE	6 mm
L/H Rear Tyre	295/80 R22.5	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	08/04/2016	Inspection Date	20/04/2016
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 9175A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	N/S SIDE COMPARTMENT DOOR	DENTED	994.79	994.79
1	N/S SIDE COMPARTMENT DOOR INDICATION LAMP	CRACKED	89.79	89.79
	LESS 10% DISCOUNT		-108.46	-108.46
			976.12	976.12
1	N/S REAR WHEEL MUDGUARD (SN)	DISTORTED	1,919.42	1,200.00
1	N/S REAR WHEEL HUB CAP (SN)	CUT	459.89	180.00
	LESS 10% DISCOUNT		-237.93	-
			2,141.38	1,380.00
	<u>LABOUR</u>			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.		1,500.00	700.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,300.00	700.00
	TO REDO GRAPHIC COLOUR STICKER.		2,000.00	800.00
			4,800.00	2,200.00
	GRAND TOTAL		7,917.50	4,556.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CC6/LPC16007269/Aeb3n2

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser****DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.