

INS. CASE OWNER:

CC6/AXA1600

8340, R, 1/1/16

LKK
IDAC

Surveyor:

Kasul

DOI:

ASSIGNMENT

18/5/16

Date / Time:

6/5/16

Registered in Merimen:

6/5/16

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJF 17202

Name of Insured:

FEC (Singapore) Pte Ltd.

Insured Tel No.:

97643111

HP:

Excess Sec II : \$5

D.O.A.:

4/5/16

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Lim Guan Ching

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

C0382367

Policy No.:

VPA1P0063425

Make / Model:

Honda Jazz 1.4 i-DTEC (401)

Place of Accident:

Jurong Point entrance @ Jurong West Rd by

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sng Ah Tei



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

14/5/16
18/5/16SJF 17202 - X
To get endorsement from OI/TP

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

NA 2

VIC-OL

After call ltr to OI:

5/25/11/16

29/11

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

18/11/16 3.26 PM

CALLED OLD SAs LM GUAT CHENG. CONFIRMED ACCIDENT DETAILS IN WHICH TP OVERTOOK A STATIONARY Lorry TO ENTER CARPARK AND HIT OLD. INFORMED OF TP CLAIM. OLD CLAIMS NO LTV FOOTAGE AND ONLY HAS PHOTOS OF DAMAGE AFTER VEHICLES WERE MOVED FROM ACCIDENT SCENE. AWARE OF NCD ISSUES. INFORMED INSURANCE WILL SETTLE AT BEM IF THERE'S LACK OF EVIDENCE.

30/1/19

File - Shun L

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

50

(Agreed / Assessed) BOLA S/N No.:

NA

If NO or B 25, Ass. Lia:

Repair Cost:

\$5

Loss of Rental (LOR):

\$5

(

days)

Loss of Use (LOU):

\$5

(\$

x

days)

Loss of Income (LOI):

\$5

(\$

x

days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

1/1/19
#250.00

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

Name 1:

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

Surveyor *Pearce*

REF: AXA

160083401 N1 Y93

ASSIGNMENT

From: _____ Date: 18082016

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: S6X 8226D

at Workshop m/s Sng An Tee

of Blk 5 Pioneer Road North #01-18

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value: 24K

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 16 days Res.: Yes or No

Lum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S6X 8226D Yr Regn: 2007 / Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hummer Stream C.C. 1799

Colour: Purple A/C: Insured / Std / NI / NA

Sp. Reading: 15708 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHNRN684075200849

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R15

R: ..

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 04/05/16

Rear

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 08/08/16

Survey held at Sng An Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

U/S\$ 2750 (Road\$ 3935.00/ \$ 5447)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE SINGAPORE PTE LTD

Ref : CC6/AXA16008340/yg3

8 SHENTON WAY #27-01 SINGAPORE 068811

Date : 06-05-2016



Code : AXA2

Policy Particulars :- THIRD PARTY CLAIM

1.

Insured Veh.	SJF 1720Z	Veh. Inspected	SGX 8226D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/05/2016

Vehicle Particulars & Condition

2.

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

Conditions of Tyres

3.

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

Description of Damages

4.

--

General Information

5.

Accident Date	04/05/2016	Inspection Date
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.	

Remarks

5a.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ001816

AXA INSURANCE (SINGAPORE) PTE LTD

8 SHENTON WAY AXA TOWER #B1-01
SINGAPORE 068811

ATTENTION:

CONTACT: 63387288

FAX NO: 63370677

DATE: 22/06/2016
ACCIDENT DATE: 04/05/2016
VEHICLE NO: SGX8226D
CHASSIS/ENG.NO:
VEHICLE MODEL: HONDA STREAM
CLAIM NO:
POLICY NO:
REMARK: 8226AXA TP AGST
SJF1720Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR DOOR (LH)	870.40	20	696.32	696.32
2	1	PC	REAR DOOR HINGE LOWER	58.60	20	46.88	46.88
3	1	PC	REAR DOOR REGULATOR AND MOTOR	363.40	20	290.72	290.72
4	1	PC	REAR DOOR BLACK TAPE	37.70	20	30.16	30.16
5	1	PC	REAR DOOR OUTER MOULDING	70.55	20	56.44	56.44
6	1	PC	FRT DOOR (LH)	860.80	20	688.64	688.64
7	1	PC	FRT DOOR BLACK TAPE	48.60	20	38.88	38.88
8	1	PC	FRT DOOR OUTER MOULDING	69.60	20	55.68	55.68
9	1	PC	REAR FENDER (LH)	858.30	20	686.64	686.64
10	1	PC	REAR BUMPER	588.90	20	471.12	471.12
11	6	PC	REAR BUMPER CLIPS	3.90	20	3.12	18.72
12	1	PC	REAR BUMPER RETAINER(LH)	19.50	20	15.60	15.60
				1288.36			
SUB-TOTAL:							3,095.80

** SPECIAL NETT PRICE **

1	1	PC	REAR FENDER GLASS SEALANT (LH)	40.00		40.00	40.00
2	1	PC	REAR TYRE (LH)	380.00		380.00	380.00
3	1	PC	REAR TYRE RIM(LH)	400.00		400.00	400.00
SUB-TOTAL							820.00

** WORK LABOUR **

TO KNOCK ROCKER GARNISH, WELD, REMOVE AND FIX ON ABOVE PARTS	1000.00	700	1,000.00
TO REMOVE AND REFIX 2 DOOR GLASS	120.00	60	120.00

JANICE

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ001816

AXA INSURANCE (SINGAPORE) PTE LTD

8 SHENTON WAY AXA TOWER #B1-01
SINGAPORE 068811

ATTENTION:

CONTACT: 63387288

FAX NO: 63370677

DATE: 22/06/2016
ACCIDENT DATE: 04/05/2016
VEHICLE NO: SGX8226D
CHASSIS/ENG.NO:
VEHICLE MODEL: HONDA STREAM
CLAIM NO:
POLICY NO:
REMARK: 8226AXA TP AGST
SJF1720Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
			TO REMOVE AND REFIX TRIMS AND UPHOLSTERY	180.00		80	180.00
			TO APPLY ANTI RUST COATING	150.00		80	150.00
			TO DO WHEEL ALIGNMENT	60.00		1880	60.00
			TO SPRAY PAINTING ON RR DOOR (LH),FRT DOOR(LH),RR FENDER(LH)	0.00			0.00
			RR BUMPER, ROCKER GARNISH AND AFFECTED AREAS	1200.00		900	1,200.00
			TO REMOVE AND FIX FENDER GLASS	60.00		in x	60.00
SUB-TOTAL							2,770.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
6 days
4/3
18/08/16 @ 1635
email: rasul@lkkauto.com
Resy after repair
1288.36
300.00
1880.00
3468.36
208
2774.68
4/3-2,750
6 days

JANICE

PAGE: 2 of 2

SUB-TOTAL: S\$ 6,685.80

ADD 7% GST. S\$ 468.01

GRAND TOTAL: S\$ 7,153.81

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O.E



MOTURING

Your Fast Track To Complete Motoring

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0846B

Vehicle Details

Vehicle No.: SGX8226D

Vehicle to be Exported: No

Intended De-registration Date: 30 Aug 2016

Vehicle Make: HONDA

Vehicle Model: STREAM 1.8L A

Primary Colour: Black

Manufacturing Year: 2007

Engine No.: R18A11700348

Chassis No.: JHMRN68407S200349

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$20,017.00

Original Registration Date: 08 Sep 2007

First Registration Date: 06 Sep 2007

Transfer Count: 2

Actual ARF Paid: \$22,019.00

24,000
13,909

10,091

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 07 Sep 2017

PARF Rebate Amount: \$12,110.00

Intended COE Rebate Details

COE Expiry Date: 07 Sep 2017

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$17,602.00

COE Rebate Amount: \$1,799.00

Total Rebate Amount: \$13,909.00

The information contained herein is correct as at 17 Aug 2016

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above 1024 X 768 resolution

Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

29 NOVEMBER 2016

FEC (SINGAPORE) PTE LTD
9H YUAN CHING ROAD
LAKESIDE TOWER
#09-80
SINGAPORE 618650

Dear Sir/Madam,

OUR REF : CC6/AXA16008340/R1yg3
YOUR REF : SJF 1720Z
ACCIDENT INVOLVING SJF 1720Z AND SGX 8226D AT JURONG POINT ENTRANCE
ALONG JURONG WEST ST 64 ON 04.05.2016

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/S SNG AH TEE MOTOR & PANEL SERVICE PTE LTD, acting on behalf of the owner of SGX 8226D against your motor insurance policy.

Based on the accident report and accident scenario, we are of the opinion that this is a conflicting version of statement as both drivers reported differently. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)

[Type here]



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

A handwritten signature in black ink, appearing to be 'Naz'.

Naz
Case Handler
DID: 6256 3561
FAX: 6256 4315
Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Singapore Pte Ltd (AXA)
(Motor Claims Dept)

Hsiao Tong (LKKAuto)

From: Khanchna (LKK Auto)
Sent: Monday, 30 April 2018 3:42 PM
To: sharon@sngahtee.com
Cc: Vic (LKKAuto); Rasul (LKKAuto); Admin A
Subject: Your Ref: SGX8226D Our Ref: CC6/AXA16008340/R1mb3 ACCIDENT INVOLVING SJF 1720Z AND SGX 8226D ON 04/05/2016

WITHOUT PREJUDICE

Your Ref: SGX8226D
Our Ref: CC6/AXA16008340/R1mb3

Hi Sir/Madam,

ACCIDENT INVOLVING SJF 1720Z AND SGX 8226D ON 04/05/2016

We refer to the above matter.

Our surveyor have finalise COR at \$2,750.00 (exclude gst) 6 days, finalize amount subject to our principal approval.

In order to expedite the claim process, please forward all relevant documents for us (**LKK**) to proceed on negotiate settlement.

- Please do not send the LOD to our prinicpal for direct settlement.

Thank You.

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

Hsiao Tong (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Monday, 13 May 2019 10:00 AM
To: SUR; assignments
Subject: Re: Please advise status

This mail is associated with :

***SGX8226D (C0382367)**

[SJF1720Z]

TP

ONG KANG GUAN

May 4 2016 1:00PM

[FEC (SINGAPORE) PTE LTD]

Sng Ah Tee Motor & Panel Service Pte Ltd

Dear LKK

Please submit your invoice and close file since no development.

Thank you.

Regards

Sashe

<-- Original Message -->

From: AXA_SG

To: sur@lkkauto.com; assignments@lkkauto.com

CC: AXA_SG

Sent On: 16/04/2019 01:35 PM

Subject: Please advise status



Dear LKK

Please let us have an update on this matter.

Thank you.

Regards

Sashe

This is an auto-generated email. Do not reply to this email.

Sent by : SASHE Go Mui Sang (AXA Insurance Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Hsiao Tong (LKKAUTO)

From: Olivia Lau (LKKAUTO)
Sent: Wednesday, 19 June 2019 4:27 PM
To: Hsiao Tong (LKKAUTO)
Cc: Cecilia Chong (LKK Auto); Vivian Lau (LKKAUTO); Admin A
Subject: [AXA]: [SNG AH TEE]: TP - SGX 8226D - DOA 04.05.2016 // LKK Ref: CC6/AXA16008340/R1mb3
Attachments: Your Ref: SGX8226D Our Ref: CC6/AXA16008340/R1mb3 ACCIDENT INVOLVING SJF 1720Z AND SGX 8226D ON 04/05/2016; Re: Please advise status

LKK Ref: CC6/AXA16008340/R1mb3

FOR TRANSFER

DOA: 04/05/2016
TP: SGX 8226D
WKSP: SNG AH TEE

Hi HT,

No further correspondence with TP on my end. Please proceed.

Thanks.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make
good
use of
Today

...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 May 2016		06 May 2016 15:29 Edit Adj Rpt	S\$2,750.00 Edit Estimates	S\$2,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	FEC (SINGAPORE) PTE LTD , Co. Reg. No.: 199406905C								
Main Claimant:	ONG KANG GUAN , ID: S82008468								
Vehicle Reg. No.:	SGX8226D	Date of Loss:	04/05/2016 13:00 - :59 [103 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0382367	Policy/Cover Note No.:	P0663425 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJF1720Z	Policy No. (Claimant):	GA060156/1						
		Excess:	S\$0.00						
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by SASHE Go Mui Sang]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 17/05/2016]								
Driver/Custodian (Insured):	LIM GUAT CHENG (59 / Female), NRIC: S1265321B Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AXA_SG (26/01/2019): Re: IMMEDIATE ADVICE UPLOADED - C0382367/SGX8226D - AXA_SG (18/05/2016): TP settlement - C0382367/P0663425 - AXA_SG (06/05/2016): WP/ PRI Assignment - C0382367/P0663425									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGX8226D (C0382367)
 [SJF1720Z]
 TP
 ONG KANG GUAN
 May 4 2016 1:00PM
 [FEC (SINGAPORE) PTE LTD]
 Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page		☒			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	19/08/16 13:32		Adjuster Immediate Advice														Load HTML			
Photos/Images															3 per page		☒			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	08/12/17 09:34		Odometer Reading														Load JPG			
2	08/12/17 09:34		Chassis Number														Load JPG			
3	08/12/17 09:34		General View														Load JPG			
4	08/12/17 09:34		General View														Load JPG			
5	08/12/17 09:34		General View														Load JPG			
6	08/12/17 09:34		General View														Load JPG			
7	08/12/17 09:34		General View														Load JPG			
8	08/12/17 09:34		General View														Load JPG			
9	08/12/17 09:34		General View														Load JPG			
10	08/12/17 09:34		General View														Load JPG			
11	08/12/17 09:34		General View														Load JPG			
12	08/12/17 09:34		General View														Load JPG			
13	08/12/17 09:34		General View														Load JPG			
14	08/12/17 09:34		General View														Load JPG			
15	08/12/17 09:34		General View														Load JPG			
16	08/12/17 09:34		General View														Load JPG			
17	08/12/17 09:34		General View														Load JPG			
18	08/12/17 09:34		General View														Load JPG			
19	08/12/17 09:34		General View														Load JPG			
20	08/12/17 09:34		General View														Load JPG			
21	08/12/17 09:34		General View														Load JPG			
22	08/12/17 09:34		General View														Load JPG			
23	08/12/17 09:34		General View														Load JPG			
24	08/12/17 09:34		General View														Load JPG			
25	08/12/17 09:34		General View														Load JPG			
26	08/12/17 09:34		General View														Load JPG			
27	08/12/17 09:34		General View														Load JPG			
28	08/12/17 09:34		General View														Load JPG			
29	08/12/17 09:34		General View														Load JPG			
30	08/12/17 09:34		General View														Load JPG			
31	08/12/17 09:34		General View														Load JPG			
32	08/12/17 09:34		General View														Load JPG			
33	08/12/17 09:34		General View														Load JPG			
34	08/12/17 09:34		General View														Load JPG			

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	08/12/17 09:34	General View	 Load JPG	☒
36	08/12/17 09:34	General View	 Load JPG	☒
37	08/12/17 09:34	General View	 Load JPG	☒
38	08/12/17 09:34	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	06/05/16 14:43	SJF1720Z INS GIA_ABS	 Load PDF	
2	06/05/16 14:43	SGX8226D TP GIA_ABS	 Load PDF	
3	06/05/16 14:43	EMAIL_ABS	 Load PDF	
4	06/05/16 15:27	CI	 Load PDF	
5	06/05/16 15:27	Policy Schedule	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/08/16 15:48	TP ESTIMATE - MARKED	 Load PDF	
2	28/11/16 16:07	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AXA16008340/R1PB3Q2

Date: 06/08/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P0663425

Claimant Vehicle
No : SGX8226D

Insured Vehicle No :

SJF1720Z

Date of Loss: 04/05/2016

Nature of Claim:

TP

Claim No: C0382367

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGX8226D

Make & Model: HONDA STREAM, 1.8 (A)

Engine No: R18A11700348

Reg. Date: 08/09/2007 (Man. Year: 2007)

Chassis No: JHMRN68407S200349

Colour: Black

Odometer: 157018 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15

Rear Tyre Size: 205/65 R15

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,915.80	1,588.36	2,327.44	59.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	1,880.00	890.00	32.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,685.80	3,468.36	3,217.44	48.12
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	6,685.80	2,750.00	3,935.80	58.87
+ GST 7.00/7.00% (S\$)	468.01	192.50	275.51	58.87
Nett Amount (S\$)	7,153.81	2,942.50	4,211.31	58.87

INSPECTION

Date of Assignment: 06/05/2016

Date Inspected: 18/08/2016 Inspected At:

Sng Ah Tee Motor & Panel Service Pte Ltd
(Pioneer)
Blk 3 Pioneer Road North, #01-18
Singapore 628457

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2019)
Parts: M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGX8226D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR (LH) (CONSISTENT)	Bent	870.40 FL	*870.40 FL
2	1		*REAR DOOR HINGE LOWER (CONSISTENT)	Serviceable	58.60 FL	*- FL
3	1		*REAR DOOR REGULATOR AND MOTOR (CONSISTENT)	Serviceable	363.40 FL	*- FL
4	1		*REAR DOOR BLACK TAPE (CONSISTENT)	Necessary	37.70 FL	*37.70 FL
5	1		*REAR DOOR OUTER MOULDING (CONSISTENT)	Necessary	70.55 FL	*70.55 FL
6	1		*FRT DOOR (LH) (CONSISTENT)	Repair	860.80 FL	*- FL
7	1		*FRT DOOR BLACK TAPE (CONSISTENT)	Serviceable	48.60 FL	*- FL
8	1		*FRT DOOR OUTER MOULDING (CONSISTENT)	Serviceable	69.60 FL	*- FL
9	1		*REAR FENDER (LH) (CONSISTENT)	Repair	858.30 FL	*- FL
10	1		*REAR BUMPER (CONSISTENT)	Scratched	588.90 FL	*588.90 FL
11	6		*REAR BUMPER CLIPS (CONSISTENT)	Necessary	23.40 FL	*23.40 FL
12	1		*REAR BUMPER RETAINER (LH) (CONSISTENT)	Necessary	19.50 FL	*19.50 FL
13	1		*REAR FENDER GLASS SEALANT (LH) (CONSISTENT)	Not Necessary	40.00 FS	*- FS
14	1		*REAR TYRE (LH) (CONSISTENT)	Not Necessary	380.00 FS	*- FS
15	1		*REAR TYRE RIM (LH) (CONSISTENT)	Scratched	400.00 FS	*300.00 FS
					Sub Total (\$\$)	4,689.75 1,910.45
					- List Item Discount on L Items 20.00/20.00% (\$\$)	773.95 322.09
					Total Parts (\$\$)	3,915.80 1,588.36

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK ROCKER GARNISH ,WELD ,REMOVE AND FIX ON ABOVE PARTS	New	1,000.00	700.00
2	TO REMOVE AND REFIX 2 DOOR GLASS	New	120.00	60.00
3	TO REMOVE AND REFIX TRIMS AND UPHOLSTERY	New	180.00	80.00
4	TO APPLY ANTI RUST COATING	New	150.00	80.00
5	TO DO WHEEL ALIGNMENT	New	60.00	60.00
6	TO SPRAY PAINTING ON RR DOOR (LH) ,FRT DOOR (LH),RR FENDER (LH) RR BUMPER,ROCKER GARNISH AND AFFECTED AREAS	New	1,200.00	900.00
7	TO REMOVE AND FIX FENDER GLASS	New	60.00	0.00
Gross Labour Cost (S\$)			2,770.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >