

SINCERE LEAD AUTOMOTIVE
 280 Woodlands Industrial Park E5
 #02-10 Harvest@Woodlands
 Singapore 757322
 Tel: 67341869/67341387 Fax: 62877949

Our Ref: SLA/201608-03/9272
 Date: 10/08/2016

Vehicle No: FBK9272R YAMAHA YZF-R15

Item	Vehicle Parts Description	Qty	W/shop Est. (\$)
<u>List Items</u>			
1	Front headlamp assembly	1 pc	450.00
2	Front headlamp cover	1 pc	78.00
3	Front cover	1 pc	372.00
4	Front fender	1 pc	80.00
5	Front spring fork RH & LH @\$450.00	2 pc	900.00
6	Front steering stem upper	1 pc	150.00
7	Front steering stem lower	1 pc	230.00
8	Front steering bearing (upper & lower)	2 pc	140.00
9	Front wheel bearing	1 pc	35.00
10	Front brake disc	1 pc	300.00
11	Fuel tank	1 pc	490.00
12	Handle bar	1 pc	150.00
13	Handle bar grips	1 set	50.00
14	Handle bar balancer	1 set	75.00
15	Rear brake pedal	1 pc	75.00
16	Rear exhaust muffler pipe assembly	1 pc	500.00
17	Rear exhaust heat shield	1 pc	150.00
18	Rear exhaust end cover	1 pc	90.00
19	Brake pedal foot rest	1 pc	55.00
20	RHS front body outer cover	1 pc	350.00
21	RHS side fairing	1 pc	245.00
22	RHS side fairing lower plate	1 pc	175.00
23	LHS front body outer cover	1 pc	350.00
24	LHS side fairing	1 pc	245.00
25	LHS side fairing lower plate	1 pc	175.00
26	RHS & LHS side mirror	1 pc	160.00
			<u>6070.00</u>
			Less 10%: 607.00
			<u>Total: 5463.00</u>

<u>Special Nett Items</u>			
1	Front IU unit	1 pc	160.00
2	Front IU unit bracket	1 pc	35.00
3	Front sports rim	1 pc	400.00
	Rear top box	1 pc	250.00
	Rear top box bracket support	1 pc	75.00
	RHS & LHS side fairing sticker	2 pc	200.00
			<u>Total: 1120.00</u>

Total for spare parts: 6583.00

Vehicle No: FBK9272R YAMAHA YZF-R15

Our Ref: SLA/201608-03/9272

Item	Job Description	W/shop Est. (\$)
1	To remove and replace damaged parts and components.	500.00
2	To supply paint materials, expandable items and putty, respray paint on parts replaced (including fuel tank).	350.00
3	To remove , refix wiring system at accident damaged.	60.00
4	To align front left and right fork.	60.00
5	Transport motorcycle to workshop for repairs.	60.00
Total for labour:		<u>1030.00</u>

Summary

	W/shop Est. (\$)
TOTAL FOR SPARE PARTS:	6583.00
TOTAL FOR LABOUR & SPRAY PAINTING:	<u>1030.00</u>
TOTAL REPAIR COSTS:	<u>7613.00</u>