



Logout

-PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJX8004S AND SGW5954K ON 09 .

From: MohdFitri.Hassim@aig.com

To: admin-a@lkkauto.com, assignments@lkkauto.com

Cc: Andy-SY.Fong@aig.com, Lily.Tan@aig.com, Kristelli.Lopez@chartisinsurance.com, Baljit.Kaur@aig.com, BernardJiQian.Ler@aig.com, KahYin.Leong@aig.com, Kunaseelan.Deivasee

Sent: Friday, 10 June, 2016 4:06:08 PM

Attachments: 10062016155245.pdf

Hi

Please refer to the enclosed request from **N-51 AUTOMOTIVE PTE LTD.**

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign **Adrian Ling** as Single Joint Expert as requested

Mohd Fitri Bin Hassim

AIG

Express Claims Adjuster II

FNOL-Singapore Windscreen | AIG Shared Services

Level 14, Menara Worldwide, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel 80012065561 ext: 1012117

MohdFitri.Hassim@aig.com | www.aig.com